

PARKLAND PRESERVE COMMUNITY DEVELOPMENT DISTRICT

Advanced Meeting Package

Workshop Meeting

Monday December 8, 2025

4:30 p.m.

Location:
Parkland Preserve
Amenity Center
835 Parkland Trail
St. Augustine, FL 32095

Note: The Advanced Meeting Package is a working document and thus all materials are considered <u>DRAFTS</u> prior to presentation and Board acceptance, approval, or adoption.

Parkland Preserve Community Development District

250 International Parkway, Suite 208 Lake Mary FL 32746 321-263-0132 Ext. 226

Board of Supervisors

Parkland Preserve

Community Development District

Dear Board Members:

The Workshop Meeting of the Board of Supervisors of the Parkland Preserve Community Development District is scheduled for Monday, December 8, 2025, at 1:30 p.m. at the Parkland Preserve Amenity Center, 835 Parkland Trail, St. Augustine, FL 32095.

The advanced copy of the agenda for the meeting is attached along with associated documentation for your review and consideration. Any additional support material will be presented at the meeting.

Should you have any questions regarding the agenda, please contact me at (321) 263-0132 X-226 or dharden@vestapropertyservices.com. We look forward to seeing you at the meeting.

Sincerely,

Dana Harden

District Manager

District: PARKLAND PRESERVE COMMUNITY DEVELOPMENT DISTRICT

Date of Meeting: Monday, December 8, 2025

Time: 1:30 PM

Location: Parkland Preserve

Amenity Center 835 Parkland Trail

St. Augustine, FL 32095

Microsoft Teams Meeting
ID: 243 954 129 225
Passcode: HMWBbV

Agenda

- I. Roll Call
- II. Pledge of Allegiance
- **III.** Audience Comments (limited to 3 minutes per individual for agenda items)

The Audience Comment portion of the agenda is where individuals who are present may make remarks on matters that concern the District. Each individual is limited to three (3) minutes for such remarks. Speakers are expected to refrain from personal attacks on the Board of Supervisors or Staff. The Board of Supervisors or Staff are not obligated to provide an immediate response as some issues require research, discussion and deliberation. If the comment concerns a maintenance related item, it should be first addressed with the General Manager outside of the context of the meeting.

- **IV.** Discussion Topics
 - A. Discussion of the 5-Year Plan
 - Parkland Preserve CDD Reserve Study
 <u>Exhibit 1</u>
 - B. Discussion of Integrated Access Solutions Barcode Scanner
 Replacement

 Exhibit 2
 - Correspondence with IAS and District Staff

 Exhibit 3
- V. Audience Comments For Non-Agenda Items (limited to 3 minutes per individual)
- VI. Supervisors Requests
- VII. Adjournment

	EXHIBIT 1

Full Reserve Study Parkland Preserve CDD St.Augustine, Florida



Prepared for FY 2025 Report Date: March 13, 2025





March 13, 2025

Board of Supervisors C/o Vesta Property Services 250 International Parkway, Suite 208 Lake Mary Florida 32746

Re: Reserve Study Report for Parkland Preserve CDD

Dear Supervisors:

Community Advisors is pleased to provide this Reserve Study report for the above referenced District. A site visit was conducted to determine the condition of your major components and provide an opinion of their remaining useful life.

We have developed a plan to fund future capital component replacements which is dependent on adequate funding, component maintenance, usage, weather and other factors. Component replacement cost is determined using local vendors and industry standard publications. This Reserve Study was prepared under the guidelines of the National Reserve Study Standards which is administrated by CAI and the Standards of Practice establish by APRA. Once you have reviewed this report and considered recent expenditures and any historic cost data, we will make necessary adjustments

Respectively submitted,

CRShamand

Charles R. Sheppard RS PRA CCI

Professional Reserve Analyst

10459 Hunters Creek Court Jacksonville, FL 32256 (904) 303-3275

www.communityadvisors.comm









TABLE OF CONTENTS

EXECUTIVE SUMMARY	
Funding Model Summary	1-1
Funding Model Projection	1-2
CURRENT FUNDING PLAN - NOT USED	
CASH FLOW	
Income & Expense Spreadsheet	3-1
EXPENDITURE DETAIL	
Annual Expenditure Detail	4-1
COMPONENT INVENTORY	
Component Inventory	5-1
Component Detail Index	5-4
Component Detail	5-7
DISCLOSURERS & INFORMATION	
Report Navigation	6-1
Methodology & Information	6-2
Terms of Service	6-3
Definitions	6-4

Parkland Preserve CDD

St.Augustine, Florida

Funding Model Summary

Report Date Account Number Version	March 13, 2025 2147
Budget Year Beginning	October 1, 2025
Budget Year Ending	September 30, 2026

Total Units 367

Report Parameters

Inflation3.00%Annual Assessment Increase3.00%Interest Rate on Reserve Deposit3.00%

2025 Beginning Balance

GENERAL INFORMATION

Date of Completion: January 1, 2020
 Date of site visit: February 6, 2025

• Components Included: 50

• Current replacement cost: \$1,892,497

Level of Service: Level I Reserve Study
 Funding Method: The Cash Flow Method

• Funding Goal: Adequate funding with moderate contributions

NOTES

- This analysis completed to establish adequate reserves for component replacement. Assume all components were installed in 2020.
- The CDD has not reserved funds therefore the beginning balance for this analysis is -0- requiring a larger year one contribution.
- Recommended contributions provide adequate funding for future component replacement.

Cash Flow Funding Plan Summary of Calculations

Required Annual Contribution \$125,675.96 \$342.44 per unit annually

Average Net Annual Interest Earned
Total Annual Allocation to Reserves

\$3,770.28
\$129,446.24

\$352.71 per unit annually

Parkland Preserve CDD Funding Model Projection

Beginning Balance: \$0

υ					Projected
	Current	Annual	Annual	Annual	Ending
Year	Cost	Contribution	Interest	Expenditures	Reserves
27.25	1 000 105	105 -5-	2.550		120 115
25-26	1,892,497	125,676	3,770		129,446
26-27	1,949,272	90,409	6,596		226,451
27-28	2,007,750	93,121	9,077	16,989	311,660
28-29	2,067,983	95,915	11,893	11,134	408,333
29-30	2,130,022	98,792	14,488	24,198	497,415
30-31	2,193,923	101,756	17,975		617,145
31-32	2,259,741	104,808	16,659	166,666	571,947
32-33	2,327,533	107,953	20,397		700,296
33-34	2,397,359	111,191	23,600	24,816	810,272
34-35	2,469,280	114,527	26,394	45,015	906,178
35-36	2,537,311	117,963	29,885	27,972	1,026,054
36-37	2,613,430	121,502	34,427		1,181,982
37-38	2,691,833	125,147	39,214		1,346,343
38-39	2,772,588	128,901	43,808	14,964	1,504,089
39-40	2,855,765	132,768	6,164	1,431,392	211,629
40-41	2,916,511	136,751	10,451		358,832
41-42	3,004,006	140,854	14,991		514,676
42-43	3,094,126	145,079	19,793		679,548
43-44	3,186,950	149,432	16,402	282,235	563,147
44-45	3,282,559	153,915	14,148	245,470	485,740
45-46	3,381,035	158,532	19,328		663,600
46-47	3,482,467	163,288	23,512	43,159	807,241
47-48	3,586,941	168,187	28,722	18,011	986,139
48-49	3,694,549	173,232	34,178	20,110	1,173,439
49-50	3,805,385	178,429	24,476	536,007	840,337
50-51	3,919,547	183,782	30,724		1,054,843
51-52	4,037,133	189,296	35,978	44,887	1,235,229
52-53	4,158,247	194,975	42,906		1,473,110
53-54	4,282,995	200,824	49,519	23,313	1,700,139
54-55	4,411,484	206,849	36,932	675,927	1,267,993

	25-26	26-27	27-28	28-29	29-30	30-31	31-32	32-33	33-34	34-35
Beginning Balance Annual Assessment Interest Earned	125,676 3,770	129,446 90,409 6,596	226,451 93,121 9,077	311,660 95,915 11,893	408,333 98,792 14,488	497,415 101,756 17,975	617,145 104,808 16,659	571,947 107,953 20,397	700,296 111,191 23,600	810,272 114,527 26,394
Expenditures Ending Balance	129,446	226,451	16,989 311,660	11,134 408,333	24,198 497,415	617,145	166,666 571,947	700,296	24,816 810,272	45,015 906,178
Description Site Components Cluster Mailboxes										
Pond Fountain Pump Allowance Pond Fountain/Control Allowance					5,065					5,871
Site Components Total:					5,065					5,871
Street Resurfacing Mill/Overlay - Amenity Lot Mill/Overlay - Cardinal Br Lane Mill/Overlay - Dove Tail Circle Mill/Overlay - Dove Tree Lane Mill/Overlay - Eagles Landing Lane Mill/Overlay - Egrets Lndg Mill/Overlay - Falcon Quest Lane Mill/Overlay - Osprey Lndg Mill/Overlay - Parkland Trail Mill/Overlay - Robin Tree Lane Mill/Overlay - Spoonbill Circle										
Mill/Overlay - Spotted Owl Lane Mill/Overlay - White Owl Lane Street Resurfacing Total:										
Fencing/Gates/Access Control Access Control Panel Access Control System							10,149			
Aluminum Fence - Pool Bar Code Reader									11,908	

	25-26	26-27	27-28	28-29	29-30	30-31	31-32	32-33	33-34	34-35
Description										
Fencing/Gates/Access Control continued										
Chain Link VC Fence - Dog Park										
Chain Link VC Fence - Pickleball Courts										20.271
Gate Operators Vehicle Gates										30,271
Vinyl Privacy Fence										
Fencing/Gates/Access Control Total:							10,149		11,908	30,271
Site Lighting										
Light Pole Heads - Pool										
Light Poles Fixtures- Decorative										
Light Poles Fixtures- Parking Lot Site Lighting Total:										
Building Components										
Flooring Allowance - Fitness Room Refurbishment Allowance - Clubhouse Interior										
Refurbishment Allowance - Pool Locker Rooms										
Window/Door Allowance										
Building Components Total:										
Roofing										
Asphalt Shingles - Clubhouse										
Metal Roof - Clubhouse										
Roofing Total:										
Painting										
Misc. Repair/Paint - Clubhouse			14,952							
Painting Total:			14,952							
HVAC										
Heat Pump 1 - Clubhouse							10,627			
Heat Pump 2 - Clubhouse HVAC Total:							10,627			
HVAC 10tal:							21,254			

	25-26	26-27	27-28	28-29	29-30	30-31	31-32	32-33	33-34	34-35
Description										
Life Safety Components										
Fire Alarm Panel/Devices										
Life Safety Components Total:										
Furniture Fixtures Equip.										
Fitness Equipment Allowance										
Furniture Allowance - Clubhouse					5,628					
Furniture Allowance - Pool					13,506					
Furniture Fixtures Equip. Total:					19,134					
Swimming Pool										
Concrete Pavers										
Filtration Refurbish Allowance										
Pool Lift										8,872
Pool Resurfacing/Tile							135,262			
Shade Structures/Fabric - Pool							10500			0.050
Swimming Pool Total:							135,262			8,872
Pickleball Courts										
Court Replacement										
Court Resurfacing (color coat)				11,134					12,908	
Shade Structures/Fabric - Pickleball Courts									10.000	
Pickleball Courts Total:				11,134					12,908	
Bocce Ball Courts										
Carpet/Lane Repair - Bocce Ball Courts			2,037							
Bocce Ball Courts Total:			2,037							
Operating Expense										
Air Handler Rebuild										
Backflow Prevention Devices										
Benches/Trash Cans										
Dog Park Play Equipment										
Dumpster Enclosure										
Interior Painting										
Irrigation System Repair										
			March 1	3 2025						
			ivial CIT T	3, 2023						

	25-26	26-27	27-28	28-29	29-30	30-31	31-32	32-33	33-34	34-35
Description										
Operating Expense continued										
Irrigation System Repair										
Kitchen Appliances										
Landscape Replacement										
Misc. Repair/Paint - Entry Feature										
Pool Filtration Partial Replacement										
Pool Furniture Partial Replacement										
Shade Fabric - Pool										
Sidewalk Repair										
Water Coolers										
Maintained By Others										
Stormwater System										
Streetlights										
Water/Sewer System										
Long Life Components										
Building Foundations/Frames										
Electrical Panels/Wiring/Devices										
Plumbing Pipes/Valves										
Stormwater System										
Year Total:			16,989	11,134	24,198		166,666		24,816	45,015

	35-36	36-37	37-38	38-39	39-40	40-41	41-42	42-43	43-44	44-45
Beginning Balance Annual Assessment Interest Earned	906,178 117,963 29,885	1,026,054 121,502 34,427	1,181,982 125,147 39,214	1,346,343 128,901 43,808	1,504,089 132,768 6,164	211,629 136,751 10,451	358,832 140,854 14,991	514,676 145,079 19,793	679,548 149,432 16,402	563,147 153,915 14,148
Expenditures Ending Balance	27,972 1,026,054	1,181,982	1,346,343	14,964 1,504,089	1,431,392 211,629	358,832	514,676	679,548	282,235 563,147	245,470 485,740
Description Site Components										
Cluster Mailboxes Pond Fountain Pump Allowance Pond Fountain/Control Allowance					24 201					112,926
Site Components Total:					24,201 24,201					112,926
Street Resurfacing										
Mill/Overlay - Amenity Lot					67,468					
Mill/Overlay - Cardinal Br Lane Mill/Overlay - Dove Tail Circle					33,733 72,080					
Mill/Overlay - Dove Tree Lane					49,629					
Mill/Overlay - Eagles Landing Lane					81,280					
Mill/Overlay - Egrets Lndg					39,444					
Mill/Overlay - Falcon Quest Lane					162,812					
Mill/Overlay - Osprey Lndg					112,649					
Mill/Overlay - Parkland Trail Mill/Overlay - Robin Tree Lane					351,902 36,828					
Mill/Overlay - Room Tree Lane Mill/Overlay - Spoonbill Circle					170,746					
Mill/Overlay - Spotted Owl Lane					34,605					
Mill/Overlay - White Owl Lane					22,648					
Street Resurfacing Total:					1,235,823					
Fencing/Gates/Access Control										
Access Control Panel	6,451									
Access Control System									14,471	
Aluminum Fence - Pool										

Bar Code Reader

	35-36	36-37	37-38	38-39	39-40	40-41	41-42	42-43	43-44	44-45
Description										
Fencing/Gates/Access Control continued										
Chain Link VC Fence - Dog Park Chain Link VC Fence - Pickleball Courts										16,918 30,301
Gate Operators										30,301
Vehicle Gates										29,459
Vinyl Privacy Fence Empired Catas (Access Control Total)	(151								1 / /71	76 (77
Fencing/Gates/Access Control Total:	6,451								14,471	76,677
Site Lighting										
Light Pole Heads - Pool Light Poles Fixtures- Decorative										
Light Poles Fixtures- Parking Lot										
Site Lighting Total:										
Building Components										
Flooring Allowance - Fitness Room					6,274					
Refurbishment Allowance - Clubhouse Interior					25.540					55,867
Refurbishment Allowance - Pool Locker Rooms Window/Door Allowance					35,540					
Building Components Total:					41,814					55,867
Roofing										
Asphalt Shingles - Clubhouse					48,176					
Metal Roof - Clubhouse										
Roofing Total:					48,176					
Painting										
Misc. Repair/Paint - Clubhouse	18,941								23,994	
Painting Total:	18,941								23,994	
HVAC										
Heat Pump 1 - Clubhouse									15,152 15,152	
Heat Pump 2 - Clubhouse HVAC Total:									30,303	
									20,200	

	35-36	36-37	37-38	38-39	39-40	40-41	41-42	42-43	43-44	44-45
Description										
Life Safety Components										
Fire Alarm Panel/Devices					10,286					
Life Safety Components Total:					10,286					
Furniture Fixtures Equip.										
Fitness Equipment Allowance					45,378					
Furniture Allowance - Clubhouse					7,563					
Furniture Allowance - Pool					18,151					
Furniture Fixtures Equip. Total:					71,092					
Swimming Pool										
Concrete Pavers										
Filtration Refurbish Allowance										
Pool Lift										
Pool Resurfacing/Tile									192,852	
Shade Structures/Fabric - Pool										
Swimming Pool Total:									192,852	
Pickleball Courts										
Court Replacement										
Court Resurfacing (color coat)				14,964					17,347	
Shade Structures/Fabric - Pickleball Courts										
Pickleball Courts Total:				14,964					17,347	
Bocce Ball Courts										
Carpet/Lane Repair - Bocce Ball Courts	2,580								3,269	
Bocce Ball Courts Total:	2,580								3,269	
Operating Expense										
Air Handler Rebuild										
Backflow Prevention Devices										
Benches/Trash Cans										
Dog Park Play Equipment										
Dumpster Enclosure										
Interior Painting										
Irrigation System Repair										

March 13, 2025

	35-36	36-37	37-38	38-39	39-40	40-41	41-42	42-43	43-44	44-45
Description										
Operating Expense continued										
Irrigation System Repair										
Kitchen Appliances										
Landscape Replacement										
Misc. Repair/Paint - Entry Feature										
Pool Filtration Partial Replacement										
Pool Furniture Partial Replacement										
Shade Fabric - Pool										
Sidewalk Repair										
Water Coolers										
Maintained By Others										
Stormwater System										
Streetlights										
Water/Sewer System										
Long Life Components										
Building Foundations/Frames										
Electrical Panels/Wiring/Devices										
Plumbing Pipes/Valves										
Stormwater System										
77 m i 1	25.052			14064	1 421 205				202 225	245.450
Year Total:	27,972			14,964	1,431,392				282,235	245,470

	45-46	46-47	47-48	48-49	49-50	50-51	51-52	52-53	53-54	54-55	
Beginning Balance	485,740	663,600	807,241	986,139	1,173,439	840,337	1,054,843	1,235,229	1,473,110	1,700,139	
Annual Assessment	158,532	163,288	168,187	173,232	178,429	183,782	189,296	194,975	200,824	206,849	
Interest Earned	19,328	23,512	28,722	34,178	24,476	30,724	35,978	42,906	49,519	36,932	
Expenditures		43,159	18,011	20,110	536,007		44,887		23,313	675,927	
Ending Balance	663,600	807,241	986,139	1,173,439	840,337	1,054,843	1,235,229	1,473,110	1,700,139	1,267,993	
Description											
Description Site Components											
Cluster Mailboxes											
Pond Fountain Pump Allowance											
Pond Fountain/Control Allowance											
Site Components Total:											_
_											
Street Resurfacing											
Mill/Overlay - Amenity Lot											
Mill/Overlay - Cardinal Br Lane											
Mill/Overlay - Dove Tail Circle											
Mill/Overlay - Dove Tree Lane											
Mill/Overlay - Eagles Landing Lane											
Mill/Overlay - Egrets Lndg											
Mill/Overlay - Falcon Quest Lane											
Mill/Overlay - Osprey Lndg Mill/Overlay - Parkland Trail											
Mill/Overlay - Parkiand Tran Mill/Overlay - Robin Tree Lane											
Mill/Overlay - Room Tree Lane Mill/Overlay - Spoonbill Circle											
Mill/Overlay - Spotted Owl Lane											
Mill/Overlay - White Owl Lane											
Street Resurfacing Total:											_
Fencing/Gates/Access Control							10.272				
Access Control Panel							10,352				
Access Control System					42.011						
Aluminum Fence - Pool					43,811						

Community Advisors Page 3-9 March 13, 2025

18,011

Bar Code Reader

	45-46	46-47	47-48	48-49	49-50	50-51	51-52	52-53	53-54	54-55
Description										
Fencing/Gates/Access Control continued										
Chain Link VC Fence - Dog Park										
Chain Link VC Fence - Pickleball Courts										
Gate Operators		43,159								
Vehicle Gates										
Vinyl Privacy Fence					247,041					
Fencing/Gates/Access Control Total:		43,159	18,011		290,852		10,352			
Site Lighting										
Light Pole Heads - Pool					32,525					
Light Poles Fixtures- Decorative					26,020					
Light Poles Fixtures- Parking Lot					16,262					
Site Lighting Total:					74,807					
Building Components										
Flooring Allowance - Fitness Room										
Refurbishment Allowance - Clubhouse Interior										
Refurbishment Allowance - Pool Locker Rooms										
Window/Door Allowance										
Building Components Total:										
Roofing										
Asphalt Shingles - Clubhouse										
Metal Roof - Clubhouse										62,779
Roofing Total:										62,779
										J = ,
Painting							20.007			
Misc. Repair/Paint - Clubhouse							30,395			
Painting Total:							30,395			
HVAC										
Heat Pump 1 - Clubhouse										
Heat Pump 2 - Clubhouse										
HVAC Total:										

	45-46	46-47	47-48	48-49	49-50	50-51	51-52	52-53	53-54	54-55
Description										
Life Safety Components										
Fire Alarm Panel/Devices										
Life Safety Components Total:										
Furniture Fixtures Equip.										
Fitness Equipment Allowance										
Furniture Allowance - Clubhouse					10,164					
Furniture Allowance - Pool					24,394					
Furniture Fixtures Equip. Total:					34,557					
Swimming Pool										
Concrete Pavers										226,671
Filtration Refurbish Allowance										47,131
Pool Lift					13,823					
Pool Resurfacing/Tile					72 101					
Shade Structures/Fabric - Pool					73,181					252 002
Swimming Pool Total:					87,004					273,802
Pickleball Courts										
Court Replacement										339,345
Court Resurfacing (color coat)				20,110					23,313	
Shade Structures/Fabric - Pickleball Courts					48,787					
Pickleball Courts Total:				20,110	48,787				23,313	339,345
Bocce Ball Courts										
Carpet/Lane Repair - Bocce Ball Courts							4,141			
Bocce Ball Courts Total:							4,141			
Operating Expense										
Air Handler Rebuild										
Backflow Prevention Devices										
Benches/Trash Cans										
Dog Park Play Equipment										
Dumpster Enclosure										
Interior Painting										
Irrigation System Repair										
			ı uyo							
			March 1	3, 2025						

	45-46	46-47	47-48	48-49	49-50	50-51	51-52	52-53	53-54	54-55
Description										
Operating Expense continued										
Irrigation System Repair										
Kitchen Appliances										
Landscape Replacement										
Misc. Repair/Paint - Entry Feature										
Pool Filtration Partial Replacement										
Pool Furniture Partial Replacement										
Shade Fabric - Pool										
Sidewalk Repair										
Water Coolers										
Maintained By Others										
Stormwater System										
Streetlights										
Water/Sewer System										
Long Life Components										
Building Foundations/Frames										
Electrical Panels/Wiring/Devices										
Plumbing Pipes/Valves										
Stormwater System										
Year Total:		43,159	18,011	20,110	536,007		44,887		23,313	675,927

Description	Expenditures
No Replacement in 25-26 No Replacement in 26-27	
Replacement Year 27-28	
Painting Misc. Repair/Paint - Clubhouse	14,952
Bocce Ball Courts	11,732
Carpet/Lane Repair - Bocce Ball Courts	2,037
Total for 2027 - 2028	\$16,989
Replacement Year 28-29	
Pickleball Courts	11 124
Court Resurfacing (color coat)	11,134
Total for 2028 - 2029	\$11,134
Replacement Year 29-30	
Site Components Pond Fountain Pump Allowance	5,065
Furniture Fixtures Equip.	
Furniture Allowance - Clubhouse Furniture Allowance - Pool	5,628 13,506
Total for 2029 - 2030	13,506
10tai 101 2029 - 2030	\$24,198
No Replacement in 30-31	
Replacement Year 31-32	
Fencing/Gates/Access Control	10.140
Access Control System HVAC	10,149
Heat Pump 1 - Clubhouse	10,627
Heat Pump 2 - Clubhouse	10,627
Swimming Pool	
Pool Resurfacing/Tile	135,262
Total for 2031 - 2032	\$166,666

Description	Expenditures
No Replacement in 32-33	
Replacement Year 33-34	
Fencing/Gates/Access Control Bar Code Reader	11,908
Pickleball Courts Court Resurfacing (color coat)	12,908
Total for 2033 - 2034	\$24,816
Replacement Year 34-35	
Site Components Pond Fountain Pump Allowance	5,871
Fencing/Gates/Access Control Gate Operators	30,271
Swimming Pool Pool Lift	8,872
Total for 2034 - 2035	\$45,015
Replacement Year 35-36	
Fencing/Gates/Access Control Access Control Panel	6,451
Painting Misc. Repair/Paint - Clubhouse	18,941
Bocce Ball Courts	2.590
Carpet/Lane Repair - Bocce Ball Courts Total for 2035 - 2036	$\frac{2,580}{\$27,972}$
No Replacement in 36-37 No Replacement in 37-38	
Replacement Year 38-39	
Pickleball Courts Court Resurfacing (color coat)	14,964
Total for 2038 - 2039	\$14,964

Description	Expenditures
Replacement Year 39-40	
Site Components	
Pond Fountain/Control Allowance	24,201
	27,201
Street Resurfacing Mill/Overlay Amonity Let	67.169
Mill/Overlay - Amenity Lot Mill/Overlay - Cardinal Br Lane	67,468 33,733
Mill/Overlay - Caldinar Br Lane Mill/Overlay - Dove Tail Circle	72,080
Mill/Overlay - Dove Tail Circle Mill/Overlay - Dove Tree Lane	49,629
Mill/Overlay - Bove Tree Lane Mill/Overlay - Eagles Landing Lane	81,280
Mill/Overlay - Eagles Landing Lane Mill/Overlay - Egrets Lndg	39,444
Mill/Overlay - Egicts Endg Mill/Overlay - Falcon Quest Lane	162,812
Mill/Overlay - Osprey Lndg	112,649
Mill/Overlay - Parkland Trail	351,902
Mill/Overlay - Robin Tree Lane	36,828
Mill/Overlay - Spoonbill Circle	170,746
Mill/Overlay - Spotted Owl Lane	34,605
Mill/Overlay - White Owl Lane	22,648
Building Components	==, 0.0
Flooring Allowance - Fitness Room	6,274
Refurbishment Allowance - Pool Locker Rooms	35,540
	33,340
Roofing Asphalt Shingles Clubbouse	10 176
Asphalt Shingles - Clubhouse	48,176
Life Safety Components	10.206
Fire Alarm Panel/Devices	10,286
Furniture Fixtures Equip.	
Fitness Equipment Allowance	45,378
Furniture Allowance - Clubhouse	7,563
Furniture Allowance - Pool	18,151
Total for 2039 - 2040	\$1,431,392
No Replacement in 40-41	
No Replacement in 41-42	
No Replacement in 42-43	
Replacement Year 43-44	
Fencing/Gates/Access Control	
Access Control System	14,471

Description	Expenditures
Replacement Year 43-44 continued	
Painting	
Misc. Repair/Paint - Clubhouse	23,994
HVAC	
Heat Pump 1 - Clubhouse	15,152
Heat Pump 2 - Clubhouse	15,152
Swimming Pool	
Pool Resurfacing/Tile	192,852
Pickleball Courts	
Court Resurfacing (color coat)	17,347
Bocce Ball Courts	
Carpet/Lane Repair - Bocce Ball Courts	3,269
Total for 2043 - 2044	\$282,235
Replacement Year 44-45	
Site Components	
Cluster Mailboxes	112,926
Fencing/Gates/Access Control	
Chain Link VC Fence - Dog Park	16,918
Chain Link VC Fence - Pickleball Courts	30,301
Vehicle Gates	29,459
Building Components	55.06 5
Refurbishment Allowance - Clubhouse Interior	55,867
Total for 2044 - 2045	\$245,470
No Replacement in 45-46	
Replacement Year 46-47	
Fencing/Gates/Access Control	
Gate Operators	43,159
Total for 2046 - 2047	\$43,159
Replacement Year 47-48	
Fencing/Gates/Access Control	
Bar Code Reader	18,011
Total for 2047 - 2048	\$18,011

Description	Expenditures
Replacement Year 48-49	
Pickleball Courts	
Court Resurfacing (color coat)	20,110
Total for 2048 - 2049	\$20,110
Replacement Year 49-50	
Fencing/Gates/Access Control	
Aluminum Fence - Pool	43,811
Vinyl Privacy Fence	247,041
Site Lighting	
Light Pole Heads - Pool	32,525
Light Poles Fixtures- Decorative	26,020
Light Poles Fixtures- Parking Lot	16,262
Furniture Fixtures Equip.	
Furniture Allowance - Clubhouse	10,164
Furniture Allowance - Pool	24,394
Swimming Pool	
Pool Lift	13,823
Shade Structures/Fabric - Pool	73,181
Pickleball Courts	
Shade Structures/Fabric - Pickleball Courts	48,787
Total for 2049 - 2050	\$536,007
No Replacement in 50-51	
Replacement Year 51-52	
Fencing/Gates/Access Control	
Access Control Panel	10,352
Painting	
Misc. Repair/Paint - Clubhouse	30,395
Bocce Ball Courts	
Carpet/Lane Repair - Bocce Ball Courts	4,141
Total for 2051 - 2052	\$44,887
	Ψ-1-1,007

Description	Expenditures
No Replacement in 52-53	
Replacement Year 53-54	
Pickleball Courts	
Court Resurfacing (color coat)	23,313
Total for 2053 - 2054	\$23,313
Replacement Year 54-55	
Roofing	
Metal Roof - Clubhouse	62,779
Swimming Pool	
Concrete Pavers	226,671
Filtration Refurbish Allowance	47,131
Pickleball Courts	
Court Replacement	339,345
Total for 2054 - 2055	\$675,927

Parkland Preserve CDD Component Inventory

		\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	ejt		e Til	jiti ^{to} Zi ^{ti}		
	Og Str	نې پروي	y s S	<u>خ</u> ا	Star of	ggit .x5	.≿ ≿	Care Cos
Description	Sur con	€8,76	5° 25°	40	, 5 _{0,}	Sills Sills	Jit Ost	Car Cas
Site Components								
Cluster Mailboxes	2020	44-45	25	0	19	23 Each	2,800.00	64,400
Pond Fountain Pump Allowance	2020	29-30	5	5	4	1 Lump Sum	4,500.00	4,500
Pond Fountain/Control Allowance	2020	39-40	20	0	14	1 Lump Sum	16,000.00	_16,000
Site Components - Total								\$84,900
Street Resurfacing								
Mill/Overlay - Amenity Lot	2020	39-40	20	0	14	2,124 Square Yards	21.00	44,604
Mill/Overlay - Cardinal Br Lane	2020	39-40	20	0	14	1,199 Square Yards	18.60	22,301
Mill/Overlay - Dove Tail Circle	2020	39-40	20	0	14	2,562 Square Yards	18.60	47,653
Mill/Overlay - Dove Tree Lane	2020	39-40	20	0	14	1,764 Square Yards	18.60	32,810
Mill/Overlay - Eagles Landing Lane	2020	39-40	20	0	14	2,889 Square Yards	18.60	53,735
Mill/Overlay - Egrets Lndg	2020	39-40	20	0	14	1,402 Square Yards	18.60	26,077
Mill/Overlay - Falcon Quest Lane	2020	39-40	20	0	14	5,787 Square Yards	18.60	107,638
Mill/Overlay - Osprey Lndg	2020	39-40	20	0	14	4,004 Square Yards	18.60	74,474
Mill/Overlay - Parkland Trail	2020	39-40	20	0	14	12,508 Square Yards	18.60	232,649
Mill/Overlay - Robin Tree Lane	2020	39-40	20	0	14	1,309 Square Yards	18.60	24,347
Mill/Overlay - Spoonbill Circle	2020	39-40	20	0	14	6,069 Square Yards	18.60	112,883
Mill/Overlay - Spotted Owl Lane	2020	39-40	20	0	14	1,230 Square Yards	18.60	22,878
Mill/Overlay - White Owl Lane	2020	39-40	20	0	14	805 Square Yards	18.60	14,973
Street Resurfacing - Total						1		\$817,025
Fencing/Gates/Access Control								
Access Control Panel	2020	35-36	16	0	10	1 Square Feet	4,800.00	4,800
Access Control System	2020	31-32	12	0	6	1 Lump Sum	8,500.00	8,500
Aluminum Fence - Pool	2020	49-50	30	0	24	449 Linear Feet	48.00	21,552
Bar Code Reader	2020	33-34	14	0	8	1 Square Feet	9,400.00	9,400
Chain Link VC Fence - Dog Park	2020	44-45	25	0	19	402 Linear Feet	24.00	9,648
Chain Link VC Fence - Pickleball Courts	2020	44-45	25	0	19	540 Linear Feet	32.00	17,280
Gate Operators	2020	34-35	12	3	9	4 Each	5,800.00	23,200
Vehicle Gates	2020	44-45	25	0	19	4 Each	4,200.00	16,800
Vinyl Privacy Fence	2020	49-50	30	0	24	1,381 Linear Feet	88.00	121,528
Fencing/Gates/Access Control - Total						,		\$232,708
Site Lighting								
Site Lighting	2020	40.50	20	0	24	10 Each	1 600 00	16,000
Light Poles Fixtures Description	2020	49-50	30	0	24	10 Each 8 Each	1,600.00	16,000
Light Poles Fixtures- Decorative Light Poles Fixtures- Parking Lot	2020	49-50	30 30	0	24 24		1,600.00	12,800
Site Lighting - Total	2020	49-50	30	U	24	5 Each	1,600.00	8,000 \$36,800
Building Components								
Flooring Allowance - Fitness Room	2020	39-40	20	0	14	122 Square Yards	34.00	4,148
Refurbishment Allowance - Clubhouse Inte		44-45	25	0	19	2,655 Square Feet	12.00	31,860
Refurbishment Allowance - Pool Locker Ro		39-40	20	0	14	264 Square Feet	89.00	23,496
Window/Door Allowance	2020	59-60	40	0	34	Lump Sum	65,000.00	65,000
Building Components - Total								\$124,504

Parkland Preserve CDD Component Inventory

	~	ු වූ	gott Soli		raent.	idio		*
Description	One Sold	50 76	* 25°	y dij	Ser Servi	Signs .	عظ والله الله	CHILD'S
Roofing Asphalt Shingles - Clubhouse Metal Roof - Clubhouse Roofing - Total	2020 2020	39-40 54-55	20 35	0	14 29	65 Squares 1,480 Square Feet	490.00 18.00	31,850 <u>26,640</u> \$58,490
Painting Misc. Repair/Paint - Clubhouse Painting - Total	2020	27-28	8	0	2	4,860 Square Feet	2.90	14,094 \$14,094
HVAC Heat Pump 1 - Clubhouse Heat Pump 2 - Clubhouse HVAC - Total	2020 2020	31-32 31-32	12 12	0	6 6	1 Each 1 Each	8,900.00 8,900.00	8,900 <u>8,900</u> \$17,800
Life Safety Components Fire Alarm Panel/Devices Life Safety Components - Total	2020	39-40	20	0	14	Lump Sum	6,800.00	<u>6,800</u> \$6,800
Furniture Fixtures Equip. Fitness Equipment Allowance Furniture Allowance - Clubhouse Furniture Allowance - Pool Furniture Fixtures Equip Total	2020 2020 2020	39-40 29-30 29-30	20 10 10	0 0 0	14 4 4	Lump Sum Lump Sum Lump Sum	30,000.00 5,000.00 12,000.00	30,000 5,000 <u>12,000</u> \$47,000
Swimming Pool Concrete Pavers Filtration Refurbish Allowance Pool Lift Pool Resurfacing/Tile Shade Structures/Fabric - Pool Swimming Pool - Total	2020 2020 2020 2020 2020 2020	54-55 54-55 34-35 31-32 49-50	35 35 15 12 30	0 0 0 0	29 29 9 6 24	10,570 Square Feet Lump Sum 1 Each 3,540 Square Feet 3 Each	9.10 20,000.00 6,800.00 32.00 12,000.00	96,187 20,000 6,800 113,280 36,000 \$272,267
Pickleball Courts Court Replacement Court Resurfacing (color coat) Shade Structures/Fabric - Pickleball Courts Pickleball Courts - Total Bocce Ball Courts	2020 2020 2020 2020	54-55 28-29 49-50	35 5 30	0 4 0	29 3 24	4 Each 1,084 Square Yards 3 Each	36,000.00 9.40 8,000.00	144,000 10,190 <u>24,000</u> \$178,190
Carpet/Lane Repair - Bocce Ball Courts Bocce Ball Courts - Total	2020	27-28	8	0	2	80 Square Yards	24.00	1,920 \$1,920

Parkland Preserve CDD Component Inventory

		b	W.
Description			Carcost
Operating Expense			
Air Handler Rebuild	Operating Expense	0.00	
Backflow Prevention Devices	Operating Expense	0.00	
Benches/Trash Cans	Operating Expense	0.00	
Dog Park Play Equipment	Operating Expense	0.00	
Dumpster Enclosure	Operating Expense	21.00	
Interior Painting	Operating Expense	0.00	
Irrigation System Repair	Operating Expense	0.00	
Kitchen Appliances	Operating Expense	0.00	
Landscape Replacement	Operating Expense	0.00	
Misc. Repair/Paint - Entry Feature	Operating Expense	0.00	
Pool Filtration Partial Replacement	Operating Expense	0.00	
Pool Furniture Partial Replacement	Operating Expense	0.00	
Shade Fabric - Pool	Operating Expense	0.00	
Sidewalk Repair	Operating Expense	0.00	
Water Coolers	Operating Expense	0.00	
Operating Expense - Total			
Maintained By Others			
Stormwater System	Not CDD Responsibility	0.00	
Streetlights	Not CDD Responsibility	0.00	
Water/Sewer System	Not CDD Responsibility	0.00	
Maintained By Others - Total			
Long Life Components			
Building Foundations/Frames	Long Life Component	0.00	
Electrical Panels/Wiring/Devices	Long Life Component	0.00	
Plumbing Pipes/Valves	Long Life Component	0.00	
Stormwater System	Long Life Component	0.00	•
Long Life Components - Total			
Total Asset Summary			\$1,892,497

Parkland Preserve CDD Component Detail Index

Asset ID Description		Replacement	Page
Site C	omponents		
1058	Cluster Mailboxes	44-45	5-7
1091	Pond Fountain Pump Allowance	29-30	5-7
1055	Pond Fountain/Control Allowance	39-40	5-8
Street	Resurfacing		
1001	Mill/Overlay - Amenity Lot	39-40	5-9
1082	Mill/Overlay - Cardinal Br Lane	39-40	5-9
1087	Mill/Overlay - Dove Tail Circle	39-40	5-9
1086	Mill/Overlay - Dove Tree Lane	39-40	5-10
1090	Mill/Overlay - Eagles Landing Lane	39-40	5-10
1089	Mill/Overlay - Egrets Lndg	39-40	5-10
1083	Mill/Overlay - Falcon Quest Lane	39-40	5-11
1080	Mill/Overlay - Osprey Lndg	39-40	5-11
1026	Mill/Overlay - Parkland Trail	39-40	5-11
1088	Mill/Overlay - Robin Tree Lane	39-40	5-12
1085	Mill/Overlay - Spoonbill Circle	39-40	5-12
1084	Mill/Overlay - Spotted Owl Lane	39-40	5-12
1081	Mill/Overlay - White Owl Lane	39-40	5-13
Fencir	ng/Gates/Access Control		
1066	Access Control Panel	35-36	5-14
1070	Access Control System	31-32	5-14
1014	Aluminum Fence - Pool	49-50	5-14
1067	Bar Code Reader	33-34	5-15
1004	Chain Link VC Fence - Dog Park	44-45	5-16
1062	Chain Link VC Fence - Pickleball Courts	44-45	5-16
1065	Gate Operators	34-35	5-17
1064	Vehicle Gates	44-45	5-17
1075	Vinyl Privacy Fence	49-50	5-18
Site Li	ighting		
1036	Light Pole Heads - Pool	49-50	5-19
1077	Light Poles Fixtures- Decorative	49-50	5-19
1041	Light Poles Fixtures- Parking Lot	49-50	5-20
Building Components			
1033	Flooring Allowance - Fitness Room	39-40	5-21

Parkland Preserve CDD Component Detail Index

Asset IDDescription		Replacement	Page
Building Components Continued			
1031	Refurbishment Allowance - Clubhouse Interior	44-45	5-21
1030	Refurbishment Allowance - Pool Locker Rooms	39-40	5-22
1029	Window/Door Allowance	59-60	5-22
Roofin	g		
1008	Asphalt Shingles - Clubhouse	39-40	5-23
1009	Metal Roof - Clubhouse	54-55	5-23
Paintir	ng		
1006	Misc. Repair/Paint - Clubhouse	27-28	5-24
HVAC			
1042	Heat Pump 1 - Clubhouse	31-32	5-25
1043	Heat Pump 2 - Clubhouse	31-32	5-25
T 10 C			
	fety Components	20.40	5.06
1054	Fire Alarm Panel/Devices	39-40	5-26
Furnit	ure Fixtures Equip.		
1032	Fitness Equipment Allowance	39-40	5-27
1034	Furniture Allowance - Clubhouse	29-30	5-27
1035	Furniture Allowance - Pool	29-30	5-28
Swimn	ning Pool		
1079	Concrete Pavers	54-55	5-29
1016	Filtration Refurbish Allowance	54-55	5-29
1072	Pool Lift	34-35	5-30
1015	Pool Resurfacing/Tile	31-32	5-30
1013	Shade Structures/Fabric - Pool	49-50	5-31
Diablak	oall Courts		
1011	Court Replacement	54-55	5-32
1011	Court Resurfacing (color coat)	28-29	5-32 5-32
1010	Shade Structures/Fabric - Pickleball Courts	49-50	5-32 5-33
1007	Shade Structures/1 doile 1 lexicoun Courts	17 50	5 55
Bocce Ball Courts			
1012	Carpet/Lane Repair - Bocce Ball Courts	27-28	5-34

Parkland Preserve CDD Component Detail Index

Asset ID Description		Replacement	Page
Operat	ting Expense		
1073	Air Handler Rebuild	25-26	5-35
1071	Backflow Prevention Devices	25-26	5-35
	Benches/Trash Cans	25-26	5-35
1074	Dog Park Play Equipment	25-26	5-36
	Dumpster Enclosure	39-40	5-36
1069	Interior Painting	25-26	5-36
	Irrigation System Repair	25-26	5-37
1068	Kitchen Appliances	25-26	5-37
	Landscape Replacement	25-26	5-37
	Misc. Repair/Paint - Entry Feature	25-26	5-37
	Pool Filtration Partial Replacement	25-26	5-38
	Pool Furniture Partial Replacement	25-26	5-38
	Shade Fabric - Pool	25-26	5-39
	Sidewalk Repair	25-26	5-39
1061	Water Coolers	25-26	5-39
Mainta	nined By Others		
1056	Stormwater System	25-26	5-41
	Streetlights	25-26	5-41
	Water/Sewer System	25-26	5-41
Long I	ife Components		
0	Building Foundations/Frames	25-26	5-42
	Electrical Panels/Wiring/Devices	25-26	5-42
	Plumbing Pipes/Valves	25-26	5-42
1078	Stormwater System	25-26	5-42
	Total Funded Assets	50	
	Total Unfunded Assets	_0	
	Total Assets	50	

Parkland Preserve CDD Component Detail

Cluster Mailboxes - 2044

Placed in Service January 2020
Useful Life 25
Replacement Year 44-45
Remaining Life 19



Pond Fountain Pump Allowance - 2029

Asset ID 1091 Asset Actual Cost \$4,500.00


Percent Replacement 100%

Category Placed in Service Useful Life Adjustment Separate Site Components January 2020

Useful Life 5

Replacement Year 29-30

Remaining Life 4







Parkland Preserve CDD Component Detail

Pond Fountain/Control Allowance - 2039

		1 Lump Sum	@ \$16,000.00
Asset ID	1055	Asset Actual Cost	\$16,000.00
		Percent Replacement	100%
Category	Site Components	Future Cost	\$24,201.43

Placed in Service
Useful Life
Replacement Year
Remaining Life
Site Components
January 2020
39-40
14





Parkland Preserve CDD Component Detail

Mill/Overlay - Amenity Lot - 2039

Asset ID 1001 Asset Actual Cost \$44,604.00
Percent Replacement 100%
Category Street Resurfacing Future Cost \$67,467.55

Placed in Service
Useful Life
Replacement Year
Remaining Life
January 2020
39-40
14



Mill/Overlay - Cardinal Br Lane - 2039

Asset ID 1082 Asset Actual Cost \$22,301.40
Percent Replacement 100%
Category Street Resurfacing Future Cost \$33,732.87

Placed in Service
Useful Life

Replacement Year
Remaining Life

January 2020
39-40
14

Mill/Overlay - Dove Tail Circle - 2039

Asset ID 1087 Asset Actual Cost \$47,653.20
Percent Replacement 100%
Category Street Resurfacing Future Cost \$72,079.74

Category Street Resurfacing
Placed in Service January 2020
Useful Life 20
Replacement Year 39-40
Remaining Life 14

Community Advisors Page 5-9 March 13, 2025

Mill/Overlay - Dove 7	Tree Lane - 2039		
Asset ID	1086	1,764 Square Yards Asset Actual Cost	@ \$18.60 \$32,810.40
1 18500 12	1000	Percent Replacement	100%
Category	Street Resurfacing	Future Cost	\$49,628.67
Placed in Service	January 2020		. ,
Useful Life	20		
Replacement Year	39-40		
Remaining Life	14		
Mill/Overlay - Eagles	Landing Lane - 2039		
		2,889 Square Yards	@ \$18.60
Asset ID	1090	Asset Actual Cost	\$53,735.40
		Percent Replacement	100%
Category	Street Resurfacing	Future Cost	\$81,279.61
Placed in Service	January 2020		
Useful Life	20		
Replacement Year	39-40		
Remaining Life	14		
Mill/Overlay - Egrets	Lndg - 2039		
		1,402 Square Yards	@ \$18.60
Asset ID	1089	Asset Actual Cost	\$26,077.20
		Percent Replacement	100%
Category	Street Resurfacing	Future Cost	\$39,444.10
Placed in Service	January 2020		
Useful Life	20		
Replacement Year	39-40		
Remaining Life	14		

Mill/Overlay - Falcon	n Quest Lane - 2039		
Asset ID	1083	5,787 Square Yards Asset Actual Cost	@ \$18.60 \$107.638.20
Asset ID	1083		\$107,638.20 100%
Category	Street Resurfacing	Percent Replacement Future Cost	\$162,812.43
Placed in Service	January 2020	Puture Cost	\$102,612.43
Useful Life	20 20		
Replacement Year	39-40		
Remaining Life	14		
Mill/Overlay - Ospre	y Lndg - 2039		
		4,004 Square Yards	@ \$18.60
Asset ID	1080	Asset Actual Cost	\$74,474.40
		Percent Replacement	100%
Category	Street Resurfacing	Future Cost	\$112,649.21
Placed in Service	January 2020		
Useful Life	20		
Replacement Year	39-40		
Remaining Life	14		
Mill/Overlay - Parkla	and Trail - 2039		
		12,508 Square Yards	@ \$18.60
Asset ID	1026	Asset Actual Cost	\$232,648.80
		Percent Replacement	100%
Category	Street Resurfacing	Future Cost	\$351,902.18
Placed in Service	January 2020		
Useful Life	20		
Replacement Year	39-40		
Remaining Life	14		

Mill/Overlay - Robin	Tree Lane - 2039		
Asset ID	1088	1,309 Square Yards Asset Actual Cost Percent Replacement	@ \$18.60 \$24,347.40 100%
Category Placed in Service Useful Life	Street Resurfacing January 2020 20	Future Cost	\$36,827.63
Replacement Year Remaining Life	39-40 14		
Mill/Overlay - Spoon	bill Circle - 2039		
Asset ID	1085	6,069 Square Yards Asset Actual Cost Percent Replacement	@ \$18.60 \$112,883.40 100%
Category Placed in Service Useful Life	Street Resurfacing January 2020 20	Future Cost	\$170,746.27
Replacement Year Remaining Life	39-40 14		
Mill/Overlay - Spotte	d Owl Lane - 2039		
Asset ID	1084	1,230 Square Yards Asset Actual Cost Percent Replacement	@ \$18.60 \$22,878.00 100%
Category Placed in Service Useful Life Replacement Year Remaining Life	Street Resurfacing January 2020 20 39-40 14	Future Cost	\$34,605.03

Mill/Overlay - White Owl Lane - 2039

		805 Square Yards	@ \$18.60
Asset ID	1081	Asset Actual Cost	\$14,973.00
		Percent Replacement	100%
Category	Street Resurfacing	Future Cost	\$22,648.01
Placed in Service	January 2020		
Useful Life	20		
Replacement Year	39-40		
Remaining Life	14		

Access Control Panel - 2035

 htrol Panel - 2035
 1 Square Feet
 @ \$4,800.00

 Asset ID
 1066
 Asset Actual Cost
 \$4,800.00

 Percent Replacement
 100%

 CaFegroing/Gates/Access Control
 Future Cost
 \$6,450.80

Placed in Service
Useful Life

Replacement Year
Remaining Life

January 2020

35-36

10



Access Control System - 2031

 1 Lump Sum
 @ \$8,500.00

 Asset ID
 1070
 Asset Actual Cost
 \$8,500.00

 Percent Replacement
 100%

 CaFegroing/Gates/Access Control
 Future Cost
 \$10,149.44

Placed in Service
Useful Life

Replacement Year
Remaining Life

January 2020
12
31-32
6

Aluminum Fence - Pool - 2049

Remaining Life

Asset ID 1014 Asset Actual Cost \$21,552.00 Percent Replacement 100%

449 Linear Feet

@ \$48.00

Calegoing/Gates/Access Control
Placed in Service January 2020
Useful Life 30
Replacement Year 49-50

24

Aluminum Fence - Pool continued...



Bar Code Reader - 2033

Placed in Service

Replacement Year

Remaining Life

Useful Life

Asset ID 1067

CaFegraing/Gates/Access Control January 2020 14 33-34 8

1 Square Feet @ \$9,400.00 Asset Actual Cost \$9,400.00 Percent Replacement 100% \$11,907.64 Future Cost



Chain Link VC Fence - Dog Park - 2044

		402 Linear Feet	@ \$24.00
Asset ID	1004	Asset Actual Cost	\$9,648.00
		Percent Replacement	100%
CaFegroing/Gates/Access Control		Future Cost	\$16,917.83
Placed in Service	January 2020		
Useful Life	25		
Replacement Year	44-45		
Remaining Life	19		



Chain Link VC Fence - Pickleball Courts - 2044

Asset ID	1062	540 Linear Feet Asset Actual Cost Percent Replacement	@ \$32.00 \$17,280.00 100%
CaFegoing/Gates/Access Control		Future Cost	\$30,300.58
Placed in Service	January 2020		
Useful Life	25		
Replacement Year	44-45		
Remaining Life	19		



Community Advisors Page 5-16 March 13, 2025

Gate Operators - 2034

Asset ID 1065 Asset Actual Cost \$23,200.00
Percent Replacement 100%
CaFegroing/Gates/Access Control Future Cost \$30,270.74

Placed in Service
Useful Life
Adjustment
3
Replacement Year
Remaining Life
January 2020
34-35



Vehicle Gates - 2044

Asset ID 1064 Asset Actual Cost \$16,800.00 Percent Replacement 100%

4 Each

Future Cost

@ \$4,200.00

\$29,458.90

CaFegoring/Gates/Access Control
Placed in Service January 2020
Useful Life 25
Replacement Year 44-45
Remaining Life 19



Vinyl Privacy Fence - 2049

 cy Fence - 2049
 1,381 Linear Feet
 @ \$88.00

 Asset ID
 1075
 Asset Actual Cost
 \$121,528.00

 Percent Replacement
 100%

 Calcoming/Gates/Access Control
 Future Cost
 \$247,041.40

Placed in Service
Useful Life
Replacement Year
Remaining Life
January 2020
49-50
24



Light Pole Heads - Pool - 2049

Asset ID 1036

Category Site Lighting
Placed in Service January 2020
Useful Life 30
Replacement Year 49-50
Remaining Life 24



Light Poles Fixtures- Decorative - 2049

Asset ID 1077

Category
Placed in Service
Useful Life
Replacement Year
Remaining Life
Site Lighting
January 2020
January 2020
49-50
24



Light Poles Fixtures- Parking Lot - 2049		5 Each	@ \$1,600.00
Asset ID	1041	Asset Actual Cost	\$8,000.00
		Percent Replacement	100%
Category	Site Lighting	Future Cost	\$16,262.35
Placed in Service	January 2020		
Useful Life	30		
Replacement Year	49-50		
Remaining Life	24		



Flooring Allowance - Fitness Room - 2039

Asset ID	1033	122 Square Yards Asset Actual Cost Percent Replacement	@ \$34.00 \$4,148.00 100%
Category	Building Components	Future Cost	\$6,274.22
Placed in Service	January 2020	Tuture Cost	Ψ0,271.22
Useful Life	20		
Replacement Year	39-40		
Remaining Life	14		



Refurbishment Allowance - Clubhouse Interior - 2044

Asset ID	1031	2,655 Square Feet Asset Actual Cost Percent Replacement	@ \$12.00 \$31,860.00 100%
Category	Building Components	Future Cost	\$55,866.70
Placed in Service	January 2020		
Useful Life	25		
Replacement Year	44-45		
Remaining Life	19		



Refurbishment Allowance - Pool Locker Rooms - 2039

Asset ID 1030 Asset Actual Cost \$23,496.00
Percent Replacement 100%
Category Building Components Future Cost \$35,539.81

Placed in Service
Useful Life
Replacement Year
Remaining Life
Usandary 2020
January 2020
39-40
14



Window/Door Allowance - 2059

Asset ID 1029 Asset Actual Cost \$65,000.00
Percent Replacement 100%
Category Building Components Future Cost \$177,573.84

Placed in Service
Useful Life
40
Replacement Year
Remaining Life
34



Asphalt Shingles - Clubhouse - 2039

 ngles - Clubhouse - 2039
 65 Squares
 @ \$490.00

 Asset ID
 1008
 Asset Actual Cost
 \$31,850.00

 Percent Replacement
 100%

 Category
 Roofing
 Future Cost
 \$48,175.98

Category Roofing
Placed in Service January 2020
Useful Life 20
Replacement Year 39-40
Remaining Life 14



Metal Roof - Clubhouse - 2054

Asset ID 1009

Category Roofing
Placed in Service January 2020
Useful Life 35
Replacement Year 54-55
Remaining Life 29

 1,480 Square Feet
 @ \$18.00

 Asset Actual Cost
 \$26,640.00

 Percent Replacement
 100%

 Future Cost
 \$62,778.90



Misc. Repair/Paint - Clubhouse - 2027

1006	4,860 Square Feet Asset Actual Cost Percent Replacement	@ \$2.90 \$14,094.00 100%
Painting	Future Cost	\$14,952.32
•		. ,
8		
27-28		
2		
	Painting January 2020 8	1006 Asset Actual Cost Percent Replacement Painting Future Cost January 2020 8



Heat Pump 1 - Clubhous	se - 2031	1 Each	@ \$8,900.00
Asset ID	1042	Asset Actual Cost	\$8,900.00
		Percent Replacement	100%
Category	HVAC	Future Cost	\$10,627.07
Placed in Service	January 2020		
Useful Life	12		
Replacement Year	31-32		
Remaining Life	6		
Heat Pump 2 - Clubhous	se - 2031	1 Each	@ \$8,900.00
Asset ID	1043	Asset Actual Cost	\$8,900.00
		Percent Replacement	100%
Category	HVAC	Future Cost	\$10,627.07
Placed in Service	January 2020		
Useful Life	12		
Replacement Year	31-32		
Remaining Life	6		

Fire Alarm Panel/Devices - 2039

Asset ID	1054	Asset Actual Cost	\$6,800.00
		Percent Replacement	100%
CategoryLife Safety Components		Future Cost	\$10,285.61
Placed in Service	January 2020		
Useful Life	20		
Replacement Year	39-40		
Remaining Life	14		



Fitness Equipment Allowance - 2039

Asset ID 1032 Asset Actual Cost \$30,000.00 Percent Replacement 100% Categoryurniture Fixtures Equip. **Future Cost** \$45,377.69

Placed in Service January 2020 Useful Life 20 Replacement Year 39-40 Remaining Life 14



Furniture Allowance - Clubhouse - 2029

Asset ID 1034

Categoryurniture Fixtures Equip. Placed in Service January 2020 Useful Life 10 29-30 Replacement Year Remaining Life 4

Asset Actual Cost \$5,000.00 Percent Replacement 100% **Future Cost** \$5,627.54



Furniture Allowance - Pool - 2029

Asset ID	1035	Asset Actual Cost	\$12,000.00
		Percent Replacement	100%
Categor i yuı	rniture Fixtures Equip.	Future Cost	\$13,506.11
Placed in Service	January 2020		
Useful Life	10		
Replacement Year	29-30		
Remaining Life	4		



Concrete Pavers - 2054

Placed in Service

Category

Useful Life

Asset ID 1079

Swimming Pool January 2020 35

Replacement Year 54-55 Remaining Life 29

 10,570 Square Feet
 @ \$9.10

 Asset Actual Cost
 \$96,187.00

 Percent Replacement
 100%

 Future Cost
 \$226,670.96



Filtration Refurbish Allowance - 2054

Asset ID 1016

Category Swimming Pool
Placed in Service January 2020
Useful Life 35
Replacement Year S4-55
Remaining Life 29

Asset Actual Cost \$20,000.00
Percent Replacement 100%
Future Cost \$47,131.31



Pool Lift - 2034

Asset ID 1072 Asset Actual Cost \$6,800.00
Percent Replacement 100%
Category Swimming Pool Future Cost \$8,872.46

Placed in Service January 2020
Useful Life 15
Replacement Year 34-35
Remaining Life 9



Pool Resurfacing/Tile - 2031

Asset ID 1015 Asset Actual Cost \$1

Category Swimming Pool
Placed in Service January 2020
Useful Life 12
Replacement Year 31-32
Remaining Life 6



Shade Structures/Fabric - Pool - 2049

Asset ID 1013 Asset Actual Cost \$36,000.00
Percent Replacement 100%
Category Swimming Pool Future Cost \$73,180.59

Category Swimming Pool
Placed in Service January 2020
Useful Life 30
Replacement Year 49-50
Remaining Life 24



Court Replacement - 2054

Asset ID 1011 Asset Actual Cost \$144,000.00
Percent Replacement 100%
Category Pickleball Courts Future Cost \$339,345.43

Placed in Service
Useful Life
35
Replacement Year
Remaining Life
January 2020
54-55
29



Court Resurfacing (color coat) - 2028

Adjustment

Replacement Year

Remaining Life

@ \$9.40 1,084 Square Yards Asset ID 1010 Asset Actual Cost \$10,189.60 Percent Replacement 100% Pickleball Courts **Future Cost** Category \$11,134.45 Placed in Service January 2020 Useful Life 5



4

3

28-29

Community Advisors Page 5-32 March 13, 2025

Shade Structures/Fabric - Pickleball Courts - 2049

Asset ID	1059	3 Each Asset Actual Cost Percent Replacement	@ \$8,000.00 \$24,000.00 100%
Category	Pickleball Courts	Future Cost	\$48,787.06
Placed in Service	January 2020		
Useful Life	30		
Replacement Year	49-50		
Remaining Life	24		



Carpet/Lane Repair - Bocce Ball Courts - 2027

Asset ID	1012	80 Square Yards Asset Actual Cost Percent Replacement	@ \$24.00 \$1,920.00 100%
Category	Bocce Ball Courts	Future Cost	\$2,036.93
Placed in Service	January 2020		
Useful Life	8		
Replacement Year	27-28		
Remaining Life	2		



Air Handler Rebuild

Asset ID 1073 Asset Actual Cost

Category Operating Expense Future Cost
Placed in Service January 2020

No Useful Life

Operating Expense

Backflow Prevention Devices

Asset ID 1071 Asset Actual Cost

Percent Replacement 100%
Category Operating Expense Future Cost

Placed in Service January 2020 No Useful Life

Operating Expense

Benches/Trash Cans

Asset ID Asset Actual Cost
Percent Replacement 100%
Category Operating Expense Future Cost

Category Placed in Service No Useful Life Operating Expense January 2020



Operating Expense

Dog Park Play Equipment

No Useful Life

Asset ID 1074 Asset Actual Cost

Category Operating Expense Future Cost
Placed in Service January 2020

Operating Expense

Dumpster Enclosure

Asset ID Asset Actual Cost \$21.00
Percent Replacement 100%
Category Operating Expense Future Cost \$31.76

Placed in Service
Useful Life
Replacement Year
Remaining Life
Useful Life
20
Replacement Year
14



Operating Expense

Interior Painting

Asset ID 1069 Asset Actual Cost
Percent Replacement 100%

Category Operating Expense Future Cost
Placed in Service January 2020
No Useful Life

Operating Expense

Irrigation System Repair

Asset ID Asset Actual Cost

Percent Replacement 100%
Category Operating Expense Future Cost
Placed in Service January 2020

Placed in Service No Useful Life

Operating Expense

Kitchen Appliances

Asset ID 1068 Asset Actual Cost

Percent Replacement 100%
Category Operating Expense Future Cost

Placed in Service January 2020
No Useful Life

Operating Expense

Landscape Replacement

No Useful Life

Asset ID Asset Actual Cost
Percent Replacement 100%

Category Operating Expense Future Cost
Placed in Service January 2020

Operating Expense

Misc. Repair/Paint - Entry Feature

Asset ID Asset Actual Cost
Percent Replacement 100

Category Operating Expense Future Cost

Placed in Service January 2020

No Useful Life

Misc. Repair/Paint - Entry Feature continued...



Operating Expense

Pool Filtration Partial Replacement

Asset ID Asset Actual Cost
Percent Replacement 100%
Category Operating Expense Future Cost

Category Operating Expense
Placed in Service January 2020
No Useful Life

Operating Expense

Pool Furniture Partial Replacement

Asset ID Asset Actual Cost
Percent Replacement 100%
Category Operating Expense Future Cost

Category Operating Expense
Placed in Service January 2020
No Useful Life

Operating Expense

Shade Fabric - Pool

Asset ID

Asset Actual Cost Percent Replacement

Category Placed in Service No Useful Life Operating Expense January 2020

Future Cost

100%



Operating Expense

Sidewalk Repair

Asset ID

Asset Actual Cost Percent Replacement Future Cost

100%

Category Placed in Service No Useful Life Operating Expense January 2020

Operating Expense

Water Coolers

Asset ID

1061

Asset Actual Cost Percent Replacement

100%

Category
Placed in Service
No Useful Life

Operating Expense January 2020 Future Cost

Community Advisors Page 5-39 March 13, 2025

Water Coolers continued...



Operating Expense

Stormwater System

Asset ID 1056 Asset Actual Cost Percent Replacement

Category Maintained By Others Future Cost
Placed in Service January 2020

No Useful Life

Not CDD Responsibility

Streetlights

Asset ID Asset Actual Cost

100%

Percent Replacement 100%
Category Maintained By Others Future Cost

Placed in Service January 2020
No Useful Life

1 to Choldi Elic

Not CDD Responsibility

Water/Sewer System

Asset ID

Asset Actual Cost
Percent Replacement
Category Maintained By Others

Future Cost

Category Maintained By Others
Placed in Service January 2020
No Useful Life

Not CDD Responsibility

Building Foundations/Frames

Asset ID Asset Actual Cost

Category Long Life Components Placed in Service January 2020

No Useful Life

100% Percent Replacement **Future Cost**

Long Life Component

Electrical Panels/Wiring/Devices

Asset ID Asset Actual Cost

Category Long Life Components Placed in Service January 2020

No Useful Life

Percent Replacement 100% **Future Cost**

Future Cost

Long Life Component

Plumbing Pipes/Valves

Asset ID **Asset Actual Cost** Percent Replacement 100%

Category Long Life Components Placed in Service January 2020 No Useful Life

Long Life Component

Stormwater System

Asset ID 1078 **Asset Actual Cost**

Percent Replacement 100% **Category Long Life Components Future Cost** Placed in Service January 2020

No Useful Life

Long Life Component

Report Navigation

- Executive Summary provides information about projected year end reserve balance, current annual contribution, interest, and inflation rates:
 - Level of Service is the type of reserve study
 - Funding Method is either Component Funding or Pooled Cash
 - Component Funding Contribution is a year one only amount
 - Current Funding Plan currently used by the Association
 - Recommended Funding Plan maintains adequate funding
- **Funding Model Projections** include both your current plan and our recommended plan. The information included in each column is described below:
 - Year begins with your study year generally for a 30-year term
 - Current cost is the current replacement of all components
 - Annual contribution is the amount placed in reserves each year
 - Annual interest earned on your funds
 - Annual expenditures are the projected component replacement cost by year
 - Projected ending balance is the year end reserve fund balance
 - Fully funded reserves are the fully funded balance for that year. Fully Funded formula is Fully Funded Balance= Component cost x Age/Useful Life
 - Percent Funded is a measure of fund strength
- Current Funding Projection is your current funding plan and how it performs
- Recommended Funding Model Projection is the plan we recommend
- Cash Flow is a 30-year statement that provides both income and expense information to quickly find when expenditures occur and the resulting financial status of your reserves
- **Annual Expenditure Detail** provides a year to year list of your projected expenditures This is a good section to review each year when preparing your budgets
- Condition Assessment (if included) is a brief description of major component condition
- **Component Inventory** contains a list of your components, remaining useful life and quantities we determined from our site visit and other means of measurement
- Component Detail Index allows quick access to the detail we have included for each component separated into categories
- Component Detail provides a listing of each component, quantities or allowances and photographs of major ones
- Methodology Terms of Service Company Profile are our Disclosure sections with information about our assumptions, methods of work and our credentials

METHODOLOGY

Reserve Analysis is a process that identifies capital expenses the District can expect and creates a plan to fund them. This is accomplished by a site visit to visually evaluate components to measure quantities and determine their remaining life. Component Selection Process is based on the Community Associations Institute (CAI) standards for reserve studies and selection of components.

Component must be a commonly owned, have a limited and predictable life, replacement cost must be above a minimum threshold cost. Useful life and replacement cost are obtained from site inspection by experienced inspectors and our database of information, historical information, local Vendors and comparison of similar component cost found at other properties.

The funding plan we develop includes; adequate cash balances, even contributions so all owners pay their fair share over time and moderate contributions with acceptable increases. Percent Funded is defined by industry standards as 70-100% strong, 30-70% fair or adequate and below 30% weak or inadequate. <u>Baseline Funding</u> maintains funds above zero resulting is a high risk of special assessments or deferred maintenance and should be avoided. Threshold Funding maintains reserves above a "Threshold" level providing adequate funding with moderate risk; using this method requires regular analysis updates.

CREDENTIALS

Community Advisors, LLC provides capital reserve planning, property inspection, and construction oversight for a broad base of clients including High-rise Condominiums, Homeowner Associations, Churches, Private Schools, Time Shares, Active Adult, Municipal Utility Plants, Marinas, Historic Buildings & Museums and commercial investment properties.

Personal Service attention to detail, quick response and valued client relationships.

Range of Experience includes a broad selection of building types, ages and uses from protected historic structures to new communities ready for developer turnover. As commercial general contractors we have experience building many of the types of structure we now provide reserve analysis for, so we understand potential problem areas. As commercial inspectors we have experienced a variety of structural and cosmetic conditions offering solutions for repair. Areas of expertise include MEP systems, energy management, life safety systems, building envelope and roof components, marine structures, street and other site improvements.

Detailed Site Evaluation is Conducted to make sure we know your property and include all your assets in our analysis. With our years of experience with community development and commercial construction projects we understand both horizontal and vertical construction and utilize realistic replacement cost and useful life projections in our analysis. Financial Plan Meets CAI & APRA Standards with information obtained during the site visit we build a custom-made financial plan to ensure adequate funding for future component replacement which equates to maintaining community value.

Reserve Analyst Credentials: Mr. Charles Sheppard is the owner of Community Advisors responsible for field inspection oversight and day to day operations. Mr. Sheppard hold a BS degree from VA Tech and has conducted building evaluations for over 30 years. He is a licensed Florida General Contractor, Home Inspector and earned the professional designations of Certified Construction Inspector (CCI), Professional Reserve Analyst (PRA) and Reserve Specialist (RS).

TERMS OF SERVICE

We have completed an analysis of your capital components that serves as a budgeting tool. This reserve study reflects the information provided by this client and is not for the purposes of performing an audit or estimating construction projects. Our site visit includes visual observation of components that are accessible and safe for our inspectors to evaluate. Roof evaluation is limited to ground observation for sloped roofs and roof top inspection for flat roofs if safe and stable access is available that meets our safety standards.

We are not responsible for any hidden defects or determining the condition of hidden or underground components or systems. Observing environmental conditions, hazardous materials or determine compliance with building codes or other regulations is not included in our scope of work. Our site visit is not a safety inspection and we are not responsible for any hazards that exist. Destructive testing is not conducted. It has been assumed, unless otherwise noted in this report, that all assets have been designed and constructed properly and that each estimated useful life will approximate that of the norm per industry standards and/or manufacturer's specifications.

Projections of component remaining useful life assumes this client will perform necessary preventative maintenance and repair per industry standards. This reserve analysis study and the parameters under which it has been completed are based upon information provided to us in part by the Client and its contractors, assorted vendors, specialist and independent contractors. Reserve fund balances and contribution amounts for use in our analysis is furnished by the client and deemed accurate. Useful life projections are determined by historical records, component condition and our opinion based on evaluating similar components on other projects. These life projections are changed by weather conditions, use, maintenance procedures and other factors out of our control therefore regular updates to this analysis are needed to maintain funding accuracy. Replacement cost is determined by our experience with similar projects, local vendor pricing and client historical records and should not be considered suitable for budgeting repair or replacement projects. Local contractor proposals must be obtained for this work. No liability is assumed as the result of changing market prices or inaccurate estimates or projections of remaining useful life of components.

Component replacement cost and interest rates constantly change. In order to maintain accuracy of your funding plan updates to this analysis should be conducted annually with a site visit every 2-3 years unless conditions warrant annual visits. Community Advisors, LLC shall not be required to participate in any legal action taken by or against our clients for any reason and shall also not be required to give testimony in depositions or in court. In all cases the liability of Community Advisors, LLC and its Principals, Employees, contractors and Vendors shall be limited to the consulting fee agreed upon for the production of this report. Client financial information is considered confidential and is not disclosed to third parties without your approval. We do use your name for our list of valued clients and when submitting proposals for new projects that request references or recent projects. That request may include size of property, number of units or major components. We also use photos from time to time of components as an example for educational and marketing efforts. Community Advisors and the analyst who prepared this study do not have any relationship that can be considered a conflict of interest. From time to time our Clients ask that we manage repair or replacement of components due to our experience in construction management. We do so with the understanding that full disclosure for both parties is completed.

DEFINITIONS

Adjustment to Useful Life: Typical useful life projections are used for each component. The adjustment is used to modify that life projection for earlier or later replacement. It only applies to the current replacement cycle.

Cash Flow Method: A method of determining reserve contributions that are "pooled" to fund replacement cost as needed without restricting funds to any one component.

Component Method: A funding method that fully funds each reserve component then sums those for the annual contribution.

Current Funding Plan: The funding plan currently used at the time of this analysis with updated component inventory and financial assumptions. This allows you to see how the current contribution level funds future component replacement.

Effective Age: Difference of useful and remaining useful life.

Fully Funded Balance: Represents the cost of used component life represented by the formula.

FFB = (Current Cost x Effective Age)/ Useful Life

Interest Contribution: The interest that should be earned on invested reserves.

Percent Funded: Ratio of reserve balance to fully funded balance.

Remaining Life: Number of years a component is projected to continue to function.

Threshold Funding: This plan maintains fund balance above a predetermined threshold dollar or percent funded amount.

Useful Life: The estimated useful life of an asset based upon industry standards, manufacturer specification, visual inspection, location, usage, association standards and prior history.

EXHIBIT 2

Integrated Access Solutions, LLC

2227 Crystal Cove Dr. Green Cove Springs, FL 32043-9604 USA Service@iasnfl.com



Estimate

ADDRESS

Parkland Preserve

ESTIMATE # 2702

DATE 11/24/2025

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
11/24/2025	BAI Barcode Scanner and Assembly w/ Pad Mount Kit	BAI Barcode Scanner at Assembly w/ Pad Mount Pedestal Kit		3,965.00	3,965.00T
	Labor	Labor to install new bard reader	code 2	170.00	340.00T
Contact Integra	ted Access Solutions, LLC to pag	ı. SUB ⁻	ΓΟΤΑL		4,305.00
Estimate is vali	d for 30 days from date of estima	te. TAX			0.00
IAS shall retain	a security interest in all goods a	TOTA	AL	\$	4,305.00

IAS shall retain a security interest in all goods and materials until same has been paid in full. Buyer/owner agrees to pay all collection and attorney fees, as well as a 1.5% per month service charge on all past due amounts. All terms and scope of work for this contract are contained herein.

Workmanship warranty is one year from install date.

Manufacturer warranties are per manufacturer.

Payment terms will be 50% down and 50% upon completion of job.

Accepted Date

Accepted By

	EXHIBIT 3

From: IAS Service < Sent: Monday, November 24, 2025 2:22 PM

To: Dana A. Harden < dharden@vestapropertyservices.com; Ron W. Zastrocky rzastrocky@vestapropertyservices.com;

Cc: Jarrod A. Vaughn < <u>ivaughn@vestapropertyservices.com</u>>

Subject: Re: Parkland Preserve

Dana,

I just got off of the phone with Barcode Automation. I verified that the reader that is installed at Parkland is no longer under warranty, but we have two paths that we can take to get it fixed. Just so we are on the same page, the part that needs repair is NOT field serviceable. So here are our options:

- We can send a tech out to pull the barcode reader down and start the repair ticker coordination with Barcode.
 - This requires us to send it back and wait for them to evaluate it and send us a repair authorization to approve it being fixed.
 - The time frame is usually 3-5 weeks in turnaround from the time they receive the damaged reader back.
 - o Once we get it, I will have a tech out to re-install it immediately
 - There is a 30 day warranty on the repair only.
- We can replace the unit with a new unit.
 - o This comes with a renewed 5 year warranty.

I have attached the estimate with the new part option to this email. Just let me know which route you would like me to pursue.

Brandon

Service Desk
IntegratedAccessSolutions.com
Office - (904) 404-7047
Email - Service@IASNFL.com



From: Dana A. Harden dharden@vestapropertyservices.com

Sent: Sunday, November 23, 2025 9:17 PM

To: IAS Service <<u>Service@iasnfl.com</u>>; Ron W. Zastrocky <<u>rzastrocky@vestapropertyservices.com</u>>

Cc: Jarrod A. Vaughn < jvaughn@vestapropertyservices.com>

Subject: RE: Parkland Preserve

Brandon,

Please send a quote for repair as soon as possible. Thank you.



CELEBRATING 30 YEARS OF SERVICE TO OUR COMMUNITIES 1995-2025

Your Community.
Our Commitment.

Dana Harden, LCAM, AMS, PCAM

District Manager P. 904.775.9754

250 International Pkwy, Ste. 208 Lake Mary, FL 32746 www.VestaDistrictServices.com





Careers | Request Proposal



CONFIDENTIALITY NOTICE: Into e-mail, and any attachment to it, contains privileged and confidential information intended only for the use of the individual(s) or entity named on the e-mail. If the reader of this e-mail is not the intended recipient, or the employee or agent responsible for delivering it to the intended recipient, you are hereby notified that reading it is strictly prohibited. If you have received this e-mail in error, please immediately return it to the sender and delate it from your system.

In compliance with the Florida Sunshine Law, CDD Board members should not globally respond to this e-mail via, "reply to all".

District Communications Reminder: Florida has a broad public records law. Your email communication may be subject to public disclosure.

From: IAS Service < Service@iasnfl.com > Sent: Friday, November 21, 2025 11:29 AM

To: Ron W. Zastrocky <rzastrocky@vestapropertyservices.com>

Cc: Dana A. Harden heroller.comh

Subject: Re: Parkland Preserve

Ron,

I looked at Scott's notes, and he made reference to a broken mirror causing vibrations on the head of the BAI scanner. I have requested pricing for repair. As soon as I have that I will forward an estimate to you.

Brandon

Service Desk

IntegratedAccessSolutions.com

Office - (904) 404-7047

Email - Service@IASNFL.com



From: Ron W. Zastrocky <rzastrocky@vestapropertyservices.com>

Sent: Friday, November 21, 2025 9:49 AM **To:** IAS Service < Service@iasnfl.com>

Cc: Dana A. Harden dharden@vestapropertyservices.com; Jarrod A. Vaughn jvaughn@vestapropertyservices.com;

Subject: Parkland Preserve

Good morning,

The barcode reader quit reading barcodes at 4:38pm yesterday. Viewed video and it is confirmed that the reader wasn't reading barcodes. We have it on hold open at this time.

Ron Zastrocky

Your Community.
Our Commitment.

Field Operations Manager

C. 904-577-3075

Vesta Property Services 245 Riverside Ave, Suite 300, Jacksonville, FL 32202 www.VestaPropertyServices.com

Careers | Request Proposal

_

CONFIDENTIALITY NOTICE: This e-mail, and any attachment to it, contains privileged and confidential information intended only for the use of the individual(s) or entity named on the e-mail. If the reader of this e-mail is not the intended recipient, or the employee or agent responsible for delivering it to the intended recipient, you are hereby notified that reading it is strictly prohibited. If you have received this e-mail in error, please immediately return it to the sender and delete it from your system.