

Heritage Isle at Viera Community Development District

Board of Supervisors Special Meeting July 22, 2025

District Office: 8529 South Park Circle, Suite 330 Orlando, Florida 32819 407.472.2471

www.heritageisleatvieracdd.org

Professionals in Community Management

HERITAGE ISLE AT VIERA COMMUNITY DEVELOPMENT DISTRICT

Board of Supervisors	VACANT Bob Goldstein Jo Labreque Jon Smallegan Kenneth Walter	Chairman Vice Chairman Assistant Secretary Assistant Secretary Assistant Secretary
District Manager	Brian Mendes	Rizzetta & Company, Inc.
District Counsel	Wes Haber	Kutak Rock, LLP.
District Engineer	Ana Saunders	BSE Consultants

All cellular phones must be placed on mute while in the meeting room.

The Audience Comment portion of the agenda is where individuals may make comments on matters that concern the District. Individuals are limited to a total of three (3) minutes to make comments during this time.

Pursuant to provisions of the Americans with Disabilities Act, any person requiring special accommodations to participate in this meeting/hearing/workshop is asked to advise the District Office at least forty-eight (48) hours before the meeting/hearing/workshop by contacting the District Manager at (407) 472-2471. If you are hearing or speech impaired, please contact the Florida Relay Service by dialing 7-1-1, or 1-800-955-8771 (TTY) 1-800-955-8770 (Voice), who can aid you in contacting the District Office.

A person who decides to appeal any decision made at the meeting/hearing/workshop with respect to any matter considered at the meeting/hearing/workshop is advised that person will need a record of the proceedings and that accordingly, the person may need to ensure that a verbatim record of the proceedings is made including the testimony and evidence upon which the appeal is to be based.

HERITAGE ISLE AT VIERA COMMUNITY DEVELOPMENT DISTRICT

District Office - Orlando FL - (407) 472-2471

Mailing Address - 3434 Colwell Avenue, Suite 200, Tampa, FL 33614

www.heritageisleatvieracdd.com

July 15, 2025

Board of Supervisors Heritage Isle at Viera Community **Development District**

FINAL AGENDA

Dear Board Members:

4.

5.

6.

The meeting of the Board of Supervisors of the Heritage Isle at Viera Community Development District will be held on July 22, 2025, at 10:30 a.m. at the Heritage Isle Clubhouse located at 6800 Legacy Blvd., Melbourne, FL 32940. The following is the final agenda for this meeting:

1. CALL TO ORDER / ROLL	CALL
-------------------------	------

2. PUBLIC COMMENT

3.

COMMU	JNITY UPDATES
Α.	Juniper Community Update
В.	Monthly Report(s) Update by Supervisor Ken Walter
	1. Joint Landscape Committee Reports
C.	Pond Maintenance UpdateTab 2
D.	Precision Sidewalk Job ReportTab 3
Ε.	Hoover Service ReportTab 4
STAFF	REPORTS
Α.	District Counsel
	1. Phase 3 Irrigation Overhaul RFP
	(Under Separate Cover)
Β.	District Engineer
	1. Updates on Hoover Pump Separation
	Consideration of Rush Marine Inspection &
	Evaluation ProposalTab 5
С.	District Manager
	1. Discussion of Vacant Board Seat
	2. Updates on Bridge Repairs
	3. Updates on Budget
BUSINE	ESS ADMINISTRATION
Α.	Consideration of the Minutes of the Board of Supervisors
	Meeting Held on May 20, 2025Tab 6
В.	Ratification of Operation and Maintenance Expenditures
	for May & June 2025Tab 7
	ESS ITEMS
Α.	Ratification of District ItemsTab 8
	1. Savoy Proposal
	2. Irrigation Controller Replacement Phase 2
	3. Park 5 Berm Plants Proposal
	4. Phase 7 Park Irrigation Valve Proposal
	5. Funston Berm Revamp Proposal
	Decoder Module Replacements Clock 5 & 9

- 7. Galindo Irrigation Small Pipe Repair Proposal
- 8. Irrigation Valves Replacement Proposal
- 9. Sign Removal and Installation Proposal
- Β. **Discussion of Golf Cart Signs**

7. SUPERVISOR REQUESTS AND COMMENTS

8. ADJOURNMENT

I look forward to seeing you at the meeting. In the meantime, if you have any questions, please do not hesitate to contact me at (407) 472-2471.

Very truly yours,

Brían Mendes

Brian Mendes District Manager

Subject: Joint Landscape Committee (JLC) July 2025 Report

The following report is submitted for the board packets

This report provides a composite Heritage Isle landscape update that addresses the homeowner lots, clubhouse HIDA and CDD properties. The JLC uses a matrix to review contractor performance. Please see attachments A and B.

We use a green, yellow and red ranking on all landscaping and irrigation processes. Here are the highlights from the 10 July 2025 meeting,

Currently, our main focus is to ensure that our landscape services remain on track with the published schedules which includes all services for front and back yards of the homeowner lots ,HIDA property, clubhouse and all common areas.

This time of year is a landscaper challenge. This is the peak period for growing which means the lawns, the shrubs, trees, etc are growing at exponential speed! It just seems like the weeds grow the fastest.

Any slip in schedule, especially now, causes more challenges to keep our properties looking sharp.

Juniper is currently resourced with 34 personnel on property. And , as of 11 July 2025 , the detailing and weeding is behind schedule by TWO weeks. And now, they are in a catch-up mode. However, we required a get well plan to refocus resources and get back on schedule. As a result, the following planned actions by the Juniper branch manager was provided as follows;

1. Mowing- All properties have been serviced according to schedule.

2. Detail and Pruning- Additional crew will be on property to complete all phases, clubhouse, HIDA and common areas by 30 July 2025. This personnel augmentation will commence on 14 July 2025 and will run through 31 July 2025. At which time they should be back on schedule.

3. Weed Control- Fuseilade was applied to all planting beds and areas throughout the community to mitigate torpedo grass. A follow-up application is required and will be accomplished 22-23 July 2025. The plan is to stay on track and complete all weed abatement by the end of July 2025.

A two person weed control team will be on property until the weed control is manageable . Once phases 2 and 5 are completed, then this team will treat all phases in sequential order. 4. Work Orders- 91 in progress. The work order team is addressing these work orders by severity and first in first out process management. The majority of the work orders are for irrigation services.

An eblast was sent out by management to the community to remind homeowners to cease submitting work orders for any unscheduled wet checks. Per the contract, this service is scheduled quarterly. However, any leaks or damaged heads must be reported to management for corrective action.

5. Specialty Team- A 4 person team is now on property to trim the robelini palm trees until completed and back on schedule.

The JLC and our management team are committed to work with Juniper to ensure we receive quality general landscaping, reliable irrigation and processes that keep our properties looking sharp.

Irrigation- it's business as usual. The irrigation team continues to address wiring issues and keeping our overall system operational. Phase 1 is still experiencing wire problems. While repairs are underway, they are using timers on each affected valve box to deliver irrigation to the properties. The vast majority of the timers are deployed in phase 1, and some on clubhouse and a few on common area properties.

The issue rests with lack of irrigation reliability in these older phases (1,2,3). Due to the unreliable wiring, we can experience a drop in irrigation service anytime. When this happens, and it happens frequently, it requires significant time to locate and diagnose the problem. This causes a significant labor requirement on a finite irrigation work crew.

Our irrigation overhaul project will make the irrigation in these older phases and common areas reliable!

Special Mention: For some good news, special thanks to Juniper. The tall palm tree pruning project this year was a total success and improvement from last year. It was well organized . We experienced no palm frond staging. and the work was completed within 4-5 weeks. Last year it took months to complete. BZ to Juniper.

Other items:

CDD Bull nose updates:

- Legacy blvd and Carambola revised estimated completion date (15 July 2025)

CDD park 4 received 9 Crepe Myrtles along the south end of the park path (10 July 2025)

CDD installed two shrub beds adjacent to Quint and Balboa (10 July 2025). These are nice enhancements to an area that had no landscaping.

Clubhouse- Awaiting proposals from Juniper to refresh areas around the clubhouse.

Quarterly Juniper Education scheduled for 29 July 2025. The topic is "Pollinators"

The next Landscape Corner in the newsletter will be discussing "holly trees"

New Business

- HIDA Phase 3 irrigation overhaul

- RFP for services has been completed and ready for board approval.

- CDD Phase 3 irrigation (common areas) overhaul being finalized by CDD counsel.

- HIDA homeowner lot landscape draft RFP will be finalized on 16 July 2025 and ready for board decision. The current Juniper homeowner lot landscaping contract expires on 31 December 2025.

Thank you!

June 2025 Landscape Report : Ken W

Hi, please forward the following report to the CDD board of Supervisors.

Juniper has been keeping pace with the maintenance schedules and landscape services on CDD property. Unfortunately, we've experienced some significant irrigation problems that affected phases 1 and 2 and common area.

We had two controller modules that failed . The modules are part of the controllers. They are the operational components on the controller. Because of the failures, they required immediate replacement for both modules. The two failed modules caused some of the wire strands to short out requiring further testing and wire install to restore irrigation. Now Juniper is finalizing the necessary repairs. Also, we had a controller in park 4 that required replacement.

We are now seeing, our irrigation reliability in the older phases become more unreliable. As a community we need to overhaul the irrigation system in the older phases. And due to problems over the last few years, phase 3 was selected as the first phase to receive an overhaul of the 2 wire apparatus in the ground. Phases 1 and 2 will follow. This has been discussed in previous reports. It's time for action.

HIDA has the lead with the irrigation overhaul Request for Information (RFI) process while keeping our manager (Brian) informed with the process. To date they have hosted visits from 4 irrigation companies to ask questions relative to the overhaul and conduct a site survey.

Each company was requested to provide a draft statement of work, plan of action and milestones and cost estimate by 30 June 2025.

Once the packages are received, the the RFP process will begin. We have to work closely with HIDA since two RFPs will be required , one for the homeowner lots and one for the common areas.

In phase 3, there are 161 valves that service the homeowner lots and 41 valve boxes that service the common areas. The are also approximately 10 shared junction boxes. These valve boxes are tied into the controllers via the solenoids and decoder circuitry. We have two (2) controllers in phase 3.

Due to the nature of this project, in that our irrigation system has shared requirements and are inter-twined, we must collaborate with HIDA for the following reasons:

While CDDs and HOAs in Florida have different roles, they can collaborate on projects that benefit their shared community requirements. These are the recommended FIORIDA requirements when a CDD and HOA collaborate on a project for the benefit of the overall community.

1, They must identify a shared need. In our case, it's the irrigation system.

2. Establish roles and responsibilities. For us we need to work as a team, however each entity will be responsible for their financial requirement for their irrigation components within phase 3.

3. Develop Joint Solicitation Documents. Both the CDD and HIDA develop separate RFPs for the same work for their responsible components of the project. Financing the project will require two quotes, one for the HIDA and one for the CDD.

4. Advertise and Distribute the Solicitation. This project is already underway.. A request for information (RFI) was communicated to 4 recommended vendors. The vendors have been on property to make their assessments. Each company will be submitting their RFI packages by 30 June 2025. RFI packages are to include a draft SOW, plan of action and milestones and a preliminary quote.

5. Vendor Evaluation and Selection. The vendor evaluations will be accomplished by the management companies (Leland and Rizzetta) augmented with the board liaisons and members from the Joint Landscape Committee as needed. Then the Request for Proposals (RFPs) will be prepared. We expect the RFPs to be released no later than 30 July 2025. This will provide adequate time to create and finalize the RFPs for release. Upon release, the vendors will have until 15 August to submit their proposals.

6. Contract Negotiation and Award. The management companies will jointly negotiate the terms and conditions. The contracts should clearly define the responsibilities of both the HIDA and CDD. Awarding the contracts must be approved by both the CDD and HIDA boards.

7. Project Execution and Oversight. The managers and board liaisons will monitor the project status in accordance with the contract terms. And address any issues that arise.

8. Project Completion and Payment. Once the project is completed to the satisfaction of both the CDD and HIDA, then the final payment can be released.

CDD General Landscaping:

Mowing- All phases have been on schedule and accomplished in concert with the homeowner lots.

Detail- Lifting the Legacy blvd hardwood trees has commenced. The parks and common areas have been detailed. And the property has been sprayed with pre emergent herbicide to mitigate spring weeds. Additionally they will be putting fertilizer on the grass throughout the property during June.

Tall Palm trees- The Wickham palms have been pruned. Legacy blvd is currently underway as the pruning crews commenced work this weekend (14 June 2025).

Bullnose update- the corner of Savoy is in the process of the refresh. We expect the new sod and plants early the week of 16 June. Carambola will follow expecting the refresh to commence during the week of 16 June 2025.

In response to an action item from the May CDD meeting concerning tree and shrub installations, the following is provided:

Tree installation- Chris Druse will be installing new Crepe Myrtles in park 4. These trees will fill in the voids along the sidewalk on the south side.

Hedgeline and Tree installation- Approximately 150ft of hedgeline will be installed along the east side of Quint and Balboa. It will consist of viburnum hedges and a number of Crepe Myrtles

Planting Bed behind the Guardhouse- This area was refreshed with beautiful Ixora shrubs. Big improvement!

Thanks!

Ken Walter 3372 Russ Pl. 32940 Heritage Isle ,CDD, Board of Supervisors, (seat#3) kwaltercdd@gmail.com us

ATTACHMENT A

GENERAL LANDSCAPE MAINTENANCE

Date: June 27, 2025

	Mowing	Edging	Hardwood Trees	Shrubs	Weeds **	Fertlization /Herbicide	Robellini's	Detailing
Homeowner Lots			this is a one time a year event	Vendor needs to get back on schedule as they are 1 week behind IF there is no weather issue target completion is in 2 weeks			Backyards are the problems Vendor has l person who trims all day about 40 houses. Bill checked backyards yesterday and they weren't done. Vendor monitoring situation	Schedule is behind
Clubhouse					Pool area is green as it was sprayed today Despite the recent communication to the community HO's still complainng			
CDD common areas		needs sharper bed lines to prepare for mulch	Bill is working with CDD foreman ken asked to check sidewalks hanging below 8 feet		weeds in the parks			

ATTACHMENT A

 ** Ken made a motion and it was seconded to continue
 with the current plan for the next 2 weeks to mitigate
 weeds - Vote taken and motion carries
 ** Ken made a motion and it
 was seconded to continue
 with the eblasts to the
 community with Amenity
 outages

KEY

Green - Normal	
Yellow - Minor	
Red - Problem & will need	
Action	

ATTACHMENT B

IRRIGATION

Date: _____June 27 2025_

	Wetchecks	Timers	Regular Maintenance	Outage	Community Communication
Homeowner Lots	Being completed as scheduled	last board mtg 80 add'i timers were requested. Chris provided an inventory of where all are deployed. If there is an outage of more than 1 day eblast needs to be sent to community	Action - Goal is to fix same day	Drop areas - 1/2 phase 1 - 40% are back tentative. Phase 2 on Abbeyville. Carambola	
Clubhouse		under road in front of clubhouse to be resolved after phase l			
CDD common areas	Monthly	a few by Savoy near Galindo		due to timer deployment	

KEY

Green - Normal	
Yellow - Minor	
Red - Problem & will need Action	



Heritage Isle CDD May, 2025 Quarterly Fountain Maint.



Entrance Left



Entrance Right



Entrance Left Light Control Panel



Entrance left before



Entrance right before

Performed Fountain Maintenance on both fountains. Cleaned floats, lights and intake screens. Checked all electrical readings and timer settings. All ok at departure. *Newly installed light control boxes are showing an alarming amount of rust already.



Entrance left after



Entrance right after



Entrance Right Light Control Panel

Customer: Heritage Isle CDD

Height: 1/4" to 2"

Slope: 1:12

Location: Repairs

Date: 4/30, 5/1-2, 5/6-7, 2025

Crew: Lee, Jared, Jacob, Elijah

#	High/8ths	Low/8ths	Inches	Sq Ft	Hazard Location
1	3	2	60	25	2833 Galindo Cir
2	6	5	60	25	2833
3	7	6	60	25	2833
4	6	5	60	25	2813
5	6	4	60	25	2803
6	8	5	60	25	2803
7	3	2	60	25	2773
8	4	3	60	25	2763
9	6	4	60	25	2763
10	6	4	46	25	2763
11	5	4	63	25	2763
12	4	2	60	25	2763
13	4	3	60	25	2763
14	7	5	60	25	2753
15	6	3	60	25	2743
16	3	2	60	25	2733
17	7	6	60	25	2723
18	5	2	60	25	2723
19	4	3	60	25	2713
20	6	5	60	25	2693
21	5	3	60	25	2693
22	10	9	60	25	X2683
23	3	3	60	25	X2703
24	4	2	60	25	X2703
25	8	5	60	25	X2763
26	4	2	60	25	2863
27	4	3	60	25	2833
28	7	4	60	25	X2803
29	8	6	60	25	2943
30	4	0	35	25	2943
31	3	0	25	25	2953
32	8	6	60	25	2953
33	3	2	60	25	2953
34	4	2	60	25	2953
35	7	4	60	25	2963
36	8	0	45	25	2973
37	3	0	15	25	2973
38	6	5	60	25	2973
39	6	0	20	25	2983
40	7	0	40	25	2983
41	6	5	60	25	2993
42	5	0	47	25	3073
43	3	0	13	25	3073
44	5	4	60	25	3093
45	4	3	60	25	3093
46	4	3	60	25	3133
47	3	3	60	25	3133
48	4	2	60	25	3133
49	7	6	60	25	3163
50	4	2	60	25	X 3193
51	6	4	60	25	X 3193
52	4	2	60	25	X 3193
53	4	2	60	25	X 3193
	· · · ·				

#	High/8ths	Low/8ths	Inches	Sq Ft	Hazard Location
54	5	4	60	25	X3163
55	4	2	60	25	3102
56	4	3	60	25	3102
57	2	0	48	25	2822 Galindo Cr
58	7	6	60	25	2822
59	2	0	33	25	2822
60	6	4	62	25	2822
61	3	0	48	25	2842
62	7	6	60	25	2882
63	7	1	60	25	2882
64	4	1	60	25	2882
65	2	0	24	25	2882
66	5	0	34	25	2892
67	5	0	45	25	2902
68	2	0	23	25	2902
69	2	0	23	25	2902
70	4	1	60	25	2912
71	6	0	22	25	2942
72	5	0	47	25	2942
73	2	0	46	25	2942
74	4	3	51	25	2942
75	11	5	60	25	2942
76	6	2	60	25	X3003
77	2	0	52	25	X3003
78	3	2	60	25	X3013 JBE
79	8	5	60	25	3307 Bancroft DrLFS
80	3	2	60	25	3307
81	3	2	60	25	3307
82	6	5	60	25	3317
83 84	7 4	5 3	60 60	25 25	<u>3357</u> 3337
85	4 5	4	60	25 25	3327
86		4	60	25 25	3307 Bancroft Dr
87	3	4	60	25	X 3357
88	4	2	48	25	X 3407
89	4	0	55	25	X 3407
90	2	0	21	25	X 3407
91	3	0	48	25	X 3467
92	4	1	48	25	3506
93	3	1	60	25	3546
94	3	2	60	25	X 3556
95	4	0	41	25	X 3536
96	2	0	24	25	X 3536
97	3	0	39	25	3467
98	3	0	41	25	3467
99	4	0	49	25	3447
100	2	0	25	25	3447
101	4	1	60	25	3437
102	4	2	60	25	3427
103	3	0	42	25	3427
104	6	4	60	25	3427
105	4	3	60	25	3427
106	4	0	54	25	3417
107	3	0	26	25	3417
108	3	0	39	25	3417
109	4	0	19	25	3417
110	6	0	33	25	3417
111	6	2	48	25	3417
112	2	0	23	25	3576 Bancroft Dr
113	3	0	40	25	3576 Bancroft Dr

#	High/8ths	Low/8ths	Inches	Sq Ft	Hazard Location
114	4	4	60	25	3357
115	2	0	20	25	3357
116	4	3	60	25	3387
117	4	3	60	25	3397
118	3	2	60	25	3407
119	3	2	60	25	6907 Owen Dr
120	3	2	60	25	6907 Owen Dr
121	5	2	60	25	6907 Owen Dr
122	4	2	60 60	25	<u>6917</u> 6917
123 124	<u>3</u> 4	3	60	25 25	6927
124	4	3	60	25 25	6927
125	4	3	60	25	6937
120	4	3	60	25	6957
128	3	2	60	25	6997
129	3	3	60	25	6976
130	5	2	60	25	6966
131	4	2	60	25	6966
132	3	0	36	25	6956
133	2	0	24	25	6956
134	3	3	60	25	6936
135	4	3	60	25	6936
136	3	3	60	25	6916
137	4	3	60	25	6884 Renshaw Dr
138	5	4	60	25	6894
139	2	0	5	25	6894
140	4	3	60	25	6894
141	6	5	60	25	6914
142	6	5	60	25	6934
143	3	2	60	25	6944
144	5	4	60	25	6954
145	4	4	60	25	6965 Renshaw Dr
146	5	4	60	25	6955
147	5	3	60	25	6905
148	8 5	4	60	25	6895 XC054
149 150		2 3	60	25	X6854 X6854
150	4 5	4	60 60	25 25	7112 Rossi Way
151	5	4	60	25	7112 Rossi Way 7122
152	4	0	41	25	7132
155	8	2	60	25	7152
155	7	3	60	25	7152
156	3	2	60	25	7172
157	3	0	15	25	7182
158	4	0	7	25	7182
159	4	0	38	25	7182
160	5	0	39	25	7182
161	3	0	19	25	7182
162	5	2	60	25	7192
163	2	2	60	25	7192
164	3	0	30	25	7212
165	3	1	60	25	7212
166	6	1	60	25	7212
167	3	0	35	25	7212
168	6	0	40	25	X7212
169	2	0	26	25	7181
170	6	0	36	25	7181
171	4	0	37	25	7181
172	5	0	52	25	7171
173	2	0	30	25	7151

#	High/8ths	Low/8ths	Inches	Sq Ft	Hazard Location
174	5	2	60	25	7151
175	10	0	53	25	7141
176	2	0	12	25	7151
177	6	0	40	25	7151
178	4	1	60	25	7151
179	3	3	60	25	7121
180	5	3	60	25	7121
181 182	3	0 2	30 60	25	7121 7121
183	2 4	0	35	25 25	7121
184	3	0	33	25	7121
185	2	2	60	25	7113 Egbert St
186	4	3	60	25	7113 Egbert St
187	7	6	60	25	7113 Egbert St
188	6	2	60	25	7123
189	4	4	60	25	7143
190	3	0	35	25	7143
191	2	0	38	25	7153
192	5	2	60	25	7163
193	2	1	60	25	7163
194	4	0	52	25	7183
195	4	2	60	25	7183
196	2	0	35	25	7193
197	4	2	60	25	7164
198	2	0	35	25	X7113
199	2	0	43	25	7105 Mendel Way
200	3	1	60	25	7105 Mendel Way
201	2	1	60	25	7115
202	3	0	16	25	7115
203	2	1	60	25	7135
204	4	2	60	25	7135
205	8	0	53	28	7256
206	9	6	60	25	7256
207 208	2 3	0	25 32	25 25	7246 7246
208	3	2	<u> </u>	25 25	7246
209	3	2	60	25	7240
210	2	2	60	25	7196
212	4	0	22	25	7186
213	2	0	38	25	7186
214	2	0	29	25	7186
215	2	1	60	25	7176
216	3	2	60	25	7166
217	3	3	60	25	7166
218	2	0	25	25	7156
219	2	1	60	25	7126
220	2	0	20	25	7106
221	2	0	25	25	7106
222	3	1	51	25	7106
223	2	2	25	25	7106
224	4	3	60	25	7107 Broderick Dr
225	3	0	37	25	7117
226	2	0	40	25	7117
227	4	0	44	25	7117
228	2	1	60	25	7117
229	2	0	6	25	7117
230	2	2	60	25	7157
231	2	0	24	25	7177
232	3 6	0	28	25	7177
233	Ö	0	44	25	7187

#	High/8ths	Low/8ths	Inches	Sq Ft	Hazard Location
234	2	0	31	25	7197
235	3	0	37	25	7217
236	3	1	60	25	7217
237	2	0	18	25	7217
238	2	2	60	25	7237
239	2	0	36	25	7257
240	6	3	60	25	7198
241	6	1	60	25	7198
242	2	1	60	25	7188
243	6	0	50	25	7168
244	6	3	60 53	25	7198
245 246	2 5	0	34	25 25	7118 X3304 Gurrero Dr
240	2	0	19	25	X3444
247	3	0	31	25	X3444
240	4	0	43	25	X3464
250	7	5	60	25	X3464
251	3	2	27	25	X3484
252	3	3	34	25	X3484
253	3	0	24	25	3535
254	2	0	21	25	3535
255	2	0	15	25	3535
256	8	0	42	25	3535
257	5	0	42	25	3535
258	5	0	39	25	3535
259	2	0	32	25	3555
260	2	0	31	25	3575 Gurrero Dr
261	4	3	60	25	3695
262	2	1	60	25	3735
263	2	0	32	25	3735
264	2	0	28	25	3735
265	2	0	27	25	3735
266	2	0	26	25	3735
267	2	0	22	25	3735
268	2	1	60	25	3745
269	2	0	29	25	3785
270	3	0	20	25	3785
271 272	3	2	60 60	25 25	<u>3805</u> 3754
272	3 3	1 0	19	25 25	3754
273	2	0	37	25	3754
274	3	0	39	25	X3695
276	3	1	60	25	3694
277	4	0	42	25	3634
278	8	0	42	25	3594
279	2	0	13	25	3594
280	2	0	34	25	3574
281	3	0	28	25	3574
282	3	0	29	25	3574
283	3	2	60	25	3554
284	3	1	60	25	3534
285	2	0	39	25	3534
286	6	0	56	25	3514
287	6	3	60	25	3504
288	5	0	40	25	3504
289	3	0	22	25	3474
290	7	5	60	25	3474
291	2	1	60	25	3354
292	6	0	50	25	3344
293	7	0	44	25	3344

#	High/8ths	Low/8ths	Inches	Sq Ft	Hazard Location
294	2	0	14	25	3344
295	3	0	40	25	3324
296	3	2	60	25	3324
297	2	0	55	20	3354 Guerro Cir
298	2	2	60	25	3404
299	3	2	60	25	3434
300	4	2	60	25	3454
301	6	4	60	25	3464
302	4	0	37	25	3564
303	2	0	18	25	3564
304	2	0	25	25	3564
305 306	2 5	0	33 37	25 25	<u>3564</u> 3604
307	3	0	55	25	3674
308	2	0	23	25	3674
309	2	0	19	25	3674
310	3	0	48	25	3684
311	2	1	60	25	3694
312	2	0	15	25	X 3695
313	2	0	37	25	X 3695
314	3	0	19	25	X 3695
315	2	0	9	25	X 3705
316	2	0	31	25	X 3705
317	2	0	21	25	X 3705
318	2	0	23	25	X 3735
319	2	0	32	25	X 3735
320	3	0	12	25	X 3735
321	2	0	45	25	X 3735
322	2	1	60	25	3754
323	2	2	60	25	3764
324	2	0	32	25	3764
325	4	2	60	25	3764
326	2	0	23	25	3784
327	2	0	29	25	3784
328 329	2 2	0	24 30	25 25	3784 3784
329	2	0	22	25 25	3784 3804
331	2	0	22	25	3804
332	2	0	25	25	3804
333	2	0	23	25	3804
334	3	0	45	25	3595
335	2	0	50	25	3595
336	8	0	32	25	3595
337	5	3	60	25	X 3454
338	2	0	56	25	X 3454
339	3	0	29	25	X 3454
340	2	0	22	25	X 3454
341	3	2	60	25	X 3434
342	3	0	45	25	X 3404
343	2	0	24	25	X 3404
344	2	0	26	25	7121 Ralston St
345	3	3	60	25	7161
346	5	3	60	25	7210
347	2	0	26	25	7180
348	3	2	60	25	7170
349	4	1	60	25	7140
350	4	2	60	25	7141 Ralston St
351	3	0	34	25	7201
352	3	2	60 27	25	7250
353	2	0	27	25	7150

#	High/8ths	Low/8ths	Inches	Sq Ft	Hazard Location
354	3	0	38	25	7150
355	2	0	33	25	7103 Halleck St
356	3	1	60	25	7143
357	4	2	60	25	7153
358	3	1	60	25	7173
359	6	4	60	25	7203
360	5	2	60	25	7252
361	5	4	60 43	25	7222
362 363	2 5	0	43 41	25 25	7182 7172
363	3	0	41 25	25 25	7162
365	4	0	39	25	7132
366	4	0	42	25	7132
367	2	0	50	25	7132
368	2	0	8	25	7132
369	2	0	9	25	7132
370	4	0	39	25	7133 Halleck St
371	6	0	32	25	7143
372	4	2	60	25	7152
373	4	3	72	30	7021 Abbeyville Rd
374	3	2	8	0	Sec 2
375	3	0	30	25	7021
376	2	0	32	25	7021
377	3	0	43	25	7021
378	4	0	51	25	7021
379	4	0	46	20	7011
380	3	0	55	20	7001
381	4	0	58	20	7001
382	3	0	53	20	6971
383	3	2	60	20	6971
384	4	0	39	25	6951
385	2	0	47	20	6931
386	2	0	24	20	6931
387	3 5	0	36 36	20	6931 6031
388 389	3	0	54	20 30	<u> 6931</u> 6900
390	6	0		20	6900
391	3	0	43	20	6930
392	3	0	37	20	6930
393	2	0	34	25	6940
394	3	0	33	25	6940
395	3	0	20	25	6970
396	3	2	60	25	6980
397	4	3	60	25	6960 Abbeyville Rd
398	4	0	27	25	7021
399	4	0	31	25	7021
400	3	1	60	25	6931
401	4	0	24	25	6911
402	3	0	28	25	6911
403	2	0	21	25	6911
404	2	0	29	25	6911
405	2	0	30	25	7003 Premonition Dr
406	2	0	30	25	7003
407	4	0	54	25	6993
408	2	0	9	25	6993
409	3	0	51	20	6953
410	3	1	60	20	6913
411	3	2	60	25	6903
412	2	0	57	20	6972 6082
413	2	0	54	25	6982

414 3 0 57 30 6992 415 4 3 60 25 Preminition Dr at Carmabola CIr 416 6 0 26 25 X 6913 417 5 3 60 22 X 6913 418 4 4 60 24 6972 419 3 0 20 25 7003 Premonition Dr 420 3 0 20 25 7003 Premonition Dr 421 3 0 56 30 6975 Lowington Way 422 2 1 60 30 6985 423 0 51 50224 10 424 0 43 10 6834 427 4 0 66 30 6924 428 6 39 35 Lowington Way at Carambola Cir 428 3 0 23 Lowington Way at Carambola Cir 431	#	High/8ths	Low/8ths	Inches	Sq Ft	Hazard Location
416602625X 691341753602469724193020267003 Premotion Dr4203020207003 Premotion Dr4213056306975 Lovington Way422216030692542340512569354243048306935425305315693442620431069344274056306974428635935Lovington Way at Carambola Cir429401925Lovington Way at Carambola Cir430504325Lovington Way at Carambola Cir43143602569444356044256944435604425694543831602569374393361306987 Floristan Dr439336130893744131602569374413160256937442546025693744343034284393037256937 <td< td=""><td>414</td><td>3</td><td>0</td><td>57</td><td>30</td><td>6992</td></td<>	414	3	0	57	30	6992
417 5 3 60 25 X 6913 418 4 60 24 6972 419 3 0 20 26 7003 Premonition Dr 420 3 0 26 300 6975 Lovington Way 421 3 0 56 30 6975 Lovington Way 422 2 1 60 30 6985 423 4 0 51 25 6985 424 3 0 49 30 6985 424 3 0 49 30 6935 425 2 0 43 10 6934 426 2 0 43 25 Lovington Way at Carambola Cir 430 5 0 43 25 Lovington Way at Carambola Cir 433 5 0 13 25 Lovington Way at Carambola Cir 433 5 0 31 260 <	415	4	3	60	25	Preminition Dr at Carmabola Cir
41846024 6972 4193020257003 Premonition Dr4203020207003 Premonition Dr4213056306975 Lovington Way422216030698542340512569954243049306935425305315692442620431069344274056306974428635935Lovington Way at Carambola Cir430504325Lovington Way at Carambola Cir431436025Lovington Way at Carambola Cir432302325Lovington Way at Carambola Cir433503125Lovington Way at Carambola Cir4344360256955435503125436746025695743831602569374404260266937441310256937442546025693744420342533554333037259337442546025 <td< td=""><td></td><td></td><td>-</td><td>26</td><td></td><td>X 6913</td></td<>			-	26		X 6913
419302026703 Premonition Dr420302000034213056306975 Lovington Way4222160306985423405125699542430493069354253053156924426204310693442740563069644286359356974429401925Lovington Way at Carambola Clr430504325Lovington Way at Carambola Clr431436025Lovington Way at Carambola Clr433503125Lovington Way at Carambola Clr4336025694443560442543752602543831602643933613044042026439336130441316025443034254442034454602647569374444026438303744940 <td>417</td> <td></td> <td></td> <td></td> <td></td> <td></td>	417					
420 3 0 20 20 7003 421 3 0 56 30 6975 Lovington Way 422 2 1 60 30 6986 423 4 0 51 25 6935 424 3 0 49 30 6833 425 3 0 53 15 6934 426 2 0 43 10 6934 427 4 0 56 30 6974 428 6 3 59 35 Lovington Way at Carambola Cir 430 5 0 43 25 Lovington Way at Carambola Cir 431 4 3 60 25 6944 433 5 0 31 25 Lovington Way at Carambola Cir 433 5 0 24 6945 6944 436 7 4 60 25 6937						
421 3 0 56 30 6975 Lovington Way 422 2 1 60 30 6985 423 4 0 51 25 6955 424 3 0 49 30 6935 425 3 0 53 15 6924 426 2 0 43 10 6934 427 4 0 56 30 6964 428 6 3 59 35 Lovington Way at Carambola Cir 430 5 0 43 25 Lovington Way at Carambola Cir 431 4 3 60 23 25 Lovington Way at Carambola Cir 433 6 0 44 25 6944 436 7 4 60 25 6945 433 1 60 25 6945 433 1 60 25 6937	_		_			
422 2 1 60 30 6065 423 4 0 51 25 6955 424 3 0 49 30 6835 425 3 0 53 15 6824 426 2 0 43 10 6934 427 4 0 56 30 6964 428 6 3 59 35 6974 429 4 0 19 25 Lovington Way at Carambola Cir 430 5 0 43 25 Lovington Way at Carambola Cir 431 4 3 60 25 Lovington Way at Carambola Cir 433 5 0 14 25 6944 435 6 0 42 5 6945 433 3 1 60 25 6945 438 3 1 60 25 6937 <tr< td=""><td></td><td></td><td>_</td><td></td><td></td><td></td></tr<>			_			
4234051256955 424 3049306935 426 2043106934 426 2043106934 427 4056306964 428 6359356974 428 635935Lovington Way at Carambola Cir 430 504325Lovington Way at Carambola Cir 431 436025Lovington Way at Carambola Cir 432 302325Lovington Way at Carambola Cir 433 503125Lovington Way at Carambola Cir 434 4360256944 435 6044256945 438 3160256945 438 3160256937 440 4260256937 444 203425x6927 444 203425x6927 444 203425x6927 444 2023253345 444 2023253345 444 2023253345 444 2023253345 444 2023253345 444 2						
4243049306935 425 3063156924 426 2043106334 427 4056306964 427 401925Lovington Way at Carambola Cir 428 635935Lovington Way at Carambola Cir 430 504325Lovington Way at Carambola Cir 431 436025Lovington Way at Carambola Cir 431 436025Lovington Way at Carambola Cir 434 4360256944 435 6044256944 436 7460256987 437 5260256987 438 3160256987 439 3361206937 440 4260206937 441 3160256937 444 203425x6927 444 203425x6927 444 202825x6937 444 202825x6937 444 202825x6927 444 2028253355 453 3059253345 444 2 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td></t<>						
425 3 0 53 15 6924 426 2 0 43 16 6934 427 4 0 56 30 6974 428 6 3 59 35 6974 428 6 3 59 35 6974 429 4 0 19 25 Lovington Way at Carambola Cir 430 5 0 43 25 Lovington Way at Carambola Cir 433 5 0 31 25 Lovington Way at Carambola Cir 433 5 0 31 25 6944 435 6 0 44 25 6945 433 1 60 25 6937 6947 439 3 3 61 30 6937 441 3 1 60 25 6937 441 3 0 37 25 6927			_			
4262043106934 427 4056306964 428 635935Lovington Way at Carambola Cir 429 401925Lovington Way at Carambola Cir 430 504325Lovington Way at Carambola Cir 431 436025Lovington Way at Carambola Cir 431 436025Lovington Way at Carambola Cir 433 503125Lovington Way at Carambola Cir 434 4360256944 435 6044256944 436 7460256945 437 5260256945 438 3160256937 440 4260266937 441 3160256937 444 2034256927 444 2034258937 443 3054258937 444 2028253345 446 3054253345 446 3054253345 446 30523345 446 3035253385 443 3035253345 444 <t< td=""><td></td><td></td><td>_</td><td></td><td></td><td></td></t<>			_			
4274056306964 428 6359356974 429 401925Lovington Way at Carambola Cir 430 504325Lovington Way at Carambola Cir 431 436025Lovington Way at Carambola Cir 432 302325Lovington Way at Carambola Cir 432 302325Lovington Way at Carambola Cir 433 503125Lovington Way at Carambola Cir 434 4360256944 435 6044256944 436 7460256985 437 5260256987 438 3160256937 440 4260206937 441 3160256937 442 5460256937 444 203425x6927 444 203425x6927 444 202825x6927 444 202825x6927 444 202825x6927 444 023253345 446 3053253365 446 30263385 451 2 </td <td></td> <td></td> <td>_</td> <td></td> <td>_</td> <td></td>			_		_	
4286359356974 429 401925Lovington Way at Carambola Cir 430 504325Lovington Way at Carambola Cir 431 436025Lovington Way at Carambola Cir 432 302325Lovington Way at Carambola Cir 434 4360256944 435 6044256944 436 7460256945 437 5260256945 438 3160256987 440 4260206937 441 3160256937 444 2034258937 441 3160256937 444 2034258927 444 2034258927 444 204830x6927 444 202825x6927 446 3023253345 451 204830x6957 448 2028253345 451 2027253345 451 2027253345 452 3035253385 453 30253345<			_			
429401925Lovington Way at Carambola Cir430504325Lovington Way at Carambola Cir431436025Lovington Way at Carambola Cir432302325Lovington Way at Carambola Cir433503125Lovington Way at Carambola Cir4344360256944435604425694443674602569954375260256987438316025698743933613069574404260206937441316025693744254602569374433037256927444203425x6927444202325345445202825x69574463053253345443305325334544420232533454452027253345446305325334544731602533454533035253385 <t< td=""><td></td><td></td><td>-</td><td></td><td></td><td></td></t<>			-			
430 5 0 43 25 Lovington Way at Carambola Cir 431 4 3 60 25 Lovington Way at Carambola Cir 432 3 0 23 25 Lovington Way at Carambola Cir 433 5 0 31 25 Lovington Way at Carambola Cir 434 4 3 60 25 6944 435 6 0 44 25 6955 436 7 4 60 25 6945 438 3 1 60 25 6987 439 3 61 30 6987 6037 441 3 1 60 25 6937 441 3 0 37 25 6937 441 2 0 34 25 x6927 444 2 0 34 25 x6927 444 2 0 44 25						
431436025Lovington Way at Carambola Cir432302325Lovington Way at Carambola Cir433503125Lovington Way at Carambola Cir43443602569444356044256944436746025694543752602569454383160256987 Floristana Dr4393361306987 Floristana Dr43931602569374404260206937441316025693744254602569374433037256927444203425x6927444203425x6927445204830x692744630532533454503039203345451202725338545230532533854533359253385454303525338545530253345456446025334545763 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td></td<>						
432302325Lovington Way at Carambola Cir433503125Lovington Way at Carambola Cir43443602569444356044256944436746025694543752602569454383160256987 Floristana Dr43933613069574404260206937441316025693744254602569374433037256927444203425x6927444204830x6927446305425x6927447316020x6957448202825x69574494023253345451202725335545230532533854512025233365453303525338545430253385454302533854553025334545644602533454576 </td <td></td> <td></td> <td>-</td> <td></td> <td></td> <td></td>			-			
433503125Lovington Way at Carambola Cir4344360256944435604425694443674602569454375260256945438316025698743933613069974404260206937441316025693744254602569374433037256927444203425 $\times 6927$ 444203425 $\times 6927$ 445204830 $\times 6957$ 446305425 $\times 6927$ 447316020 $\times 6957$ 44820232533454503039203345451202725338545230532533854533035253385454302533854553025338545644602533454564460253345456446025344545942<						
4344360256944435604425694443674602569554375260256987 Floristana Dr4383160256987 Floristana Dr43933613069874404260206937441316025693744254602569374433037256927444203425×6927445204830×6927445204830×6927446305425×6927447316020×6957448202325334544302325334545120272533854523035253385453335925338545430252533854564460253445458516025344545942602534454594260253445456446025344545644 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td></t<>						
4356044256944436746025694543752602569454383160256987 Floristana Dr43933613069974404260206937441316025693744254602569374433037256927444203425x6927445203425x6927446305425x6927447316020x6957448202325334544940232533454503039203345451202725338545230532533854533035253385456446025334545851602534154585160253445459426025344545851602534454585160253445459426025344446026253	-					
436746025695543752602569454383160256987 Floristana Dr43933613069574404260206937441316025693744254602569374433037256927444203425x6927445204830x6927445202825x6927446305425x6927447316020x6957448202825x6957448202325334545120272533554523053253365453303525338545430352533854553025253385456446025334545763602534154606360253415458516025341545942602534144623015303444632160						
4375260256945438316025698744042602069374413160256937442546025693744330372569374433037256927444203425x6927444203425x6927444203425x6927446305425x6927447316020x6957448202825x69574494023253345450303920334545120272533554523053253385453303525338545430252533854553025334545644602533454585160253415459426025344545851602534454594260253445459426025341446120403425<						
4383160256987 Floristana Dr43933613069574404260206937441316025693744254602569374433037256927444203425 $x 6927$ 444203425 $x 6927$ 445204830 $x 6927$ 446305425 $x 6927$ 447316020 $x 6957$ 4482023253345 Moonstone Ln448202325334545120272533854523053253385451202525338545230352533854533025253385454302533854553025338545644602533454576360253445460636040342545644602533454576360253445460636040342546120						
440426020 6937 441 316025 6937 442 546025 6937 443 303725 6927 444 203425 $x6927$ 444 203425 $x6927$ 445 204830 $x6927$ 446 305425 $x6927$ 447 316020 $x6957$ 448 202825 $x6957$ 448 202325 3345 Moonstone Ln 450 303920 3345 451 202725 33355 453 303525 3385 454 303525 3385 455 3025 25 3385 456 446025 3345 456 446025 3415 458 516025 3415 458 516025 3415 460 636040 3425 461 204025 3415 456 44025 3415 456 426025 3415 456 426025 3414 460 <td></td> <td></td> <td></td> <td>60</td> <td></td> <td>6987 Floristana Dr</td>				60		6987 Floristana Dr
44131 60 25 6937 442 54 60 25 6937 443 30 37 25 6927 444 20 34 25 $x6927$ 445 20 48 30 $x6927$ 446 30 54 25 $x6927$ 446 30 54 25 $x6927$ 447 31 60 20 $x6957$ 448 20 23 25 3345 449 40 23 25 3345 450 30 39 20 3345 451 20 27 25 3355 452 30 53 25 3385 454 30 35 25 3385 455 30 25 25 3385 455 30 25 25 3385 456 44 60 25 3345 456 42 60 25 3415 459 42 60 25 3414 460 63 60 40 3425 461 20 40 25 3414 462 32 60 25 3344 463 21 60 25 3344 464 40 26 25 3344 466 <td></td> <td></td> <td>3</td> <td></td> <td></td> <td></td>			3			
4425460256937 443 3037256927 444 203425x6927 445 204830x6927 446 305425x6927 446 305425x6957 447 316020x6957 448 202825x6957 449 4023253345 450 3039203345 451 2027253355 452 3053253385 453 3359253385 454 3035253385 455 3025253385 455 30253345 456 4460253385 457 6360253445 461 2040253445 461 2040253414 462 3260253414 463 2160253414 464 4026253414 465 5057303404 466 301530B 466 301530B 466 <t< td=""><td>440</td><td>4</td><td>2</td><td>60</td><td>20</td><td>6937</td></t<>	440	4	2	60	20	6937
443303725 6927 444203425 $x6927$ 445204830 $x6927$ 446305425 $x6927$ 447316020 $x6957$ 448202825 $x6957$ 449402325334545030392033454512027253355452305325338545333592533854543035253385455302525338545644602533454585160253345459426025341546063604034254612040253414463216025341446440262534144655057303404466301530B467605223384469203525338447042583033744713054203364	441	3	1	60	25	6937
444203425 $x 6927$ 445 204830 $x 6927$ 446 305425 $x 6927$ 447 316020 $x 6957$ 448 202825 $x 6957$ 449 402325 3345 450 303920 3345 451 202725 3355 452 305325 3365 453 303525 3385 454 303525 3385 455 302525 3385 456 446025 3345 457 636025 3345 458 516025 3415 460 636040 3425 461 204025 3414 462 326025 3414 463 216025 3414 464 402625 3394 466 301530 364 468 203025 3384 469 203525 3384 470 425830 3374 471 305420 3364	442	5	4	60	25	6937
44520 48 30x6927 446 30 54 25 x6927 447 31 60 20 x6957 448 20 28 25 $x6957$ 449 40 23 25 3345 450 30 39 20 3345 451 20 27 25 3355 452 30 53 25 3365 453 30 35 25 3385 454 30 35 25 3385 455 30 25 25 3385 456 44 60 25 3395 457 63 60 25 3345 458 51 60 25 3415 459 42 60 25 3415 460 63 60 40 3425 461 20 40 25 3414 463 21 60 25 3414 464 40 26 25 3394 466 30 15 30 B 467 60 52 25 3384 468 20 30 25 3384 468 20 30 25 3384 466 30 15 30 364 468 2<	443	3	0	37	25	6927
44630 54 25 $x6927$ 447 31 60 20 $x6957$ 448 20 28 25 $x6957$ 449 40 23 25 3345 450 30 39 20 3345 451 20 27 25 3355 452 30 53 25 3385 453 33 59 25 3385 454 30 35 25 3385 455 30 25 25 3385 456 44 60 25 3385 456 44 60 25 3345 457 63 60 25 3415 458 51 60 25 3415 458 51 60 25 3415 460 63 60 40 3425 461 20 40 25 3414 462 32 60 25 3414 466 30 15 30 B 467 60 52 25 3384 466 30 15 30 B 466 30 15 30 B 466 30 15 30 B 466 20 35 25 3384 468 2 <t< td=""><td>444</td><td>2</td><td>0</td><td>34</td><td>25</td><td>x6927</td></t<>	444	2	0	34	25	x6927
447316020 $x6957$ 448 202825 $x6957$ 449 402325 3345 Moonstone Ln 450 303920 3345 451 202725 3355 452 305325 3365 453 303525 3385 454 303525 3385 455 302525 3385 456 446025 3395 457 636025 3345 458 516025 3415 460 636040 3425 461 204025 3414 462 326025 3414 463 216025 3414 464 402625 3414 466 301530B 467 605225 3384 468 203025 3384 469 203525 3384 470 425830 3374 471 305420 3364	445		0			x6927
448202825x6957 449 4023253345 Moonstone Ln 450 3039203345 451 2027253355 452 3053253365 453 3359253385 454 3035253385 455 3025253385 456 4460253395 457 6360253345 458 5160253345 458 5160253415 460 6360403425 461 2040253414 462 3260253414 463 2160253414 464 4026253414 465 5057303404 466 301530B 467 6052253384 469 2035253384 469 2035253384 469 2035253384 470 4258303374 471 3054203364						x6927
449402325 3345 Moonstone Ln450303920 3345 451202725 3355 452305325 3365 453335925 3385 454303525 3385 455302525 3385 456446025 3385 457636025 3345 458516025 3415 460636040 3425 461204025 3414 462326025 3414 463216025 3414 4663015 30 3404 4663015 30 3404 4663015 30 8 4676052 25 3384 468203025 3384 469203525 3384 470425830 3374 471305420 3364						
4503039203345 451 2027253355 452 3053253365 453 3359253385 454 3035253385 455 3025253385 456 4460253395 457 6360253345 458 5160253415 459 4260253415 460 6360403425 461 2040253414 462 3260253414 463 2160253414 464 4026253414 466 301530B 467 6052253384 468 2030253384 469 2035253384 469 2035253384 470 4258303374 471 3054203364	-					
4512027253355 452 3053253365 453 3359253385 454 3035253385 455 3025253385 456 4460253395 456 4460253345 457 6360253345 458 5160253415 459 4260253415 460 6360403425 461 2040253424 462 3260253414 463 2160253414 464 4026253414 466 301530B 467 6052253384 468 2030253384 469 2035253384 470 4258303374 471 3054203364	-	-	÷			
4523053253365 453 3359253385 454 3035253385 455 3025253385 456 4460253395 456 4460253395 457 6360253345 458 5160253415 459 4260253415 460 6360403425 461 2040253414 462 3260253414 463 2160253414 464 4026253414 466 301530B 467 6052253384 468 2030253384 469 2035253384 470 4258303374 471 3054203364						
4533359253385 454 3035253385 455 3025253385 456 4460253395 456 4460253395 457 6360253345 458 5160253415 459 4260253415 460 6360403425 461 2040253414 462 3260253414 463 2160253414 464 4026253414 466 301530B 467 6052253384 468 2030253384 469 2035253384 470 4258303374 471 3054203364						
45430 35 25 3385 455 30 25 25 3385 456 4460 25 3395 457 63 60 25 3345 457 63 60 25 3345 458 51 60 25 3345 458 51 60 25 3415 459 42 60 25 3415 460 63 60 40 3425 461 20 40 25 3414 462 32 60 25 3414 463 21 60 25 3414 463 21 60 25 3414 464 40 26 25 3414 466 3015 30 B 466 3015 30 B 466 20 32 25 3384 468 20 35 25 3384 469 20 35 25 3384 470 42 58 30 3374 471 30 54 20 3364						
45530 25 25 3385 456 4460 25 3395 457 63 60 25 3345 458 51 60 25 3415 459 42 60 25 3415 460 63 60 40 3425 461 20 40 25 3414 462 32 60 25 3414 463 21 60 25 3414 463 21 60 25 3414 463 21 60 25 3414 464 40 26 25 3414 466 30 15 30 B 466 30 15 30 B 467 60 52 25 3384 468 20 30 25 3384 469 20 35 25 3384 470 42 58 30 3374 471 30 54 20 3364						
45644 60 25 3395 457 63 60 25 3345 458 51 60 25 3415 459 42 60 25 3415 460 63 60 40 3425 461 20 40 25 3414 462 32 60 25 3414 463 21 60 25 3414 464 40 26 25 3414 465 50 57 30 3404 466 30 15 30 B 467 60 52 25 3384 468 20 30 25 3384 469 20 35 25 3384 470 42 58 30 3374 471 30 54 20 3364						
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$						
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$						
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$						
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$						
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$						
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$						
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$						
464 4 0 26 25 3414 465 5 0 57 30 3404 466 3 0 15 30 B 467 6 0 52 25 3394 468 2 0 30 25 3384 469 2 0 35 25 3384 470 4 2 58 30 3374 471 3 0 54 20 3364 472 5 0 52 30 3364						
465 5 0 57 30 3404 466 3 0 15 30 B 467 6 0 52 25 3394 468 2 0 30 25 3384 469 2 0 35 25 3384 470 4 2 58 30 3374 471 3 0 54 20 3364 472 5 0 52 30 3364						
466 3 0 15 30 B 467 6 0 52 25 3394 468 2 0 30 25 3384 469 2 0 35 25 3384 470 4 2 58 30 3374 471 3 0 54 20 3364 472 5 0 52 30 3364						
467 6 0 52 25 3394 468 2 0 30 25 3384 469 2 0 35 25 3384 470 4 2 58 30 3374 471 3 0 54 20 3364 472 5 0 52 30 3364						
468 2 0 30 25 3384 469 2 0 35 25 3384 470 4 2 58 30 3374 471 3 0 54 20 3364 472 5 0 52 30 3364						
469 2 0 35 25 3384 470 4 2 58 30 3374 471 3 0 54 20 3364 472 5 0 52 30 3364						
470 4 2 58 30 3374 471 3 0 54 20 3364 472 5 0 52 30 3364						
471 3 0 54 20 3364 472 5 0 52 30 3364						
472 5 0 52 30 3364						
473 5 2 60 30 B			0	52	30	3364
	473	5	2	60	30	В

#	High/8ths	Low/8ths	Inches	Sq Ft	Hazard Location
474	4	0	50	25	3344
475	2	0	29	30	X6888 McGrady Dr
476	3	0	31	30	X6888 McGrady Dr
477	3	0	55	20	X6888 McGrady Dr
478	2	0	43	25	6929
479	3	0	54	25	6929
480	3	2	60	25	6939
481	3	0	36	25	6949
482	3	0	35 56	25 30	<u>6949</u>
483 484	4 4	0	50 52	30	6949 B
485	4 2	0		30 25	6969
486	4	3	45 60	25	6969
487	6	4	22	25	6979
488	3	0	38	25	6999
489	3	2	60	25	6978
490	2	1	60	25	6968
491	2	1	60	25	6968
492	3	2	60	25	6968
493	3	0	25	25	6958
494	3	0	38	25	6938
495	4	0	40	25	6938
496	3	2	60	25	6928
497	5	0	21	25	6908
498	5	2	60	25	6888
499	3	0	40	25	6888
500	4	0	33	20	Carambola Cir 3303
501	3	3	60	20	3303
502	5	0	54	20	3303
503	6	5	72	80	3303
504	4	0	33	20	3303
505	3	0	34	20	3333
506	4	3	60	20	3333
507 508	3 4	2 2	60 60	20 20	<u> </u>
508	4	4	60	20	3353 PG
510	3	2	60	20	3353
510	4	0	27	20	3363 PG
512	7	0	39	20	3363 PG
513	6	0	45	25	3363
514	3	0	38	20	3373
515	2	0	24	20	3373
516	2	1	60	20	3373
517	6	4	60	20	3373
518	4	0	37	20	3383
519	4	2	60	20	3383
520	4	0	33	20	3393
521	2	0	32	20	3393
522	5	4	60	20	3403
523	3	2	60	20	3403
524	3	0	52	20	3403
525	4	2	60	20	3403
526	5	4	60	20	3403
527	3	2	60	20	3403
528	5	4	56	20	3413
529	3	0	35	20	3413
530	4	2	60	20	3413
531	4	3 4	60 60	20	3413
532	4 3	<u>4</u> 0	60 50	20 20	3413 3413
533	3	U	50	20	3413

#	High/8ths	Low/8ths	Inches	Sq Ft	Hazard Location
534	3	0	57	20	3423
535	3	0	9	20	3423
536	4	0	30	20	3433 PG
537	5	0	35	20	3433 PG
538	3	0	10	20	3433
539	4	0	37	20	3433
540	4	3	60	20	3433
541	4	3	60	20	3443 3443
542 543	6 2	3 2	60 60	20 20	3443 3463
543 544	3	0	38	20	3463
544 545	4	0	48	20	3463
546	2	0	22	20	3463
547	6	4	60	20	3483
548	8	7	51	50	3483
549	5	3	60	20	3503
550	3	2	60	20	3503
551	8	4	60	20	3523
552	3	0	34	20	3523
553	3	0	12	20	3523
554	5	3	60	20	3533
555	6	0	56	20	3543 PG
556	3	0	28	20	3543
557	4	0	36	20	3543
558	7	4	60	20	3543
559	4	0	41	20	3553
560	5	0	28	20	3553
561	4	0	43	20	3553
562	8	3	61	20	3563
563	3	0	39	20	3563
564	7	4	60	20	3563
565	3	0	29	20	3563
566 567	6 3	0	37 34	20 20	3573 3573
568	4	0 3	60	20	3573
569	4	3	60	20	3593
570	5	4	60	20	3593
571	4	3	60	20	3593
572	5	0	52	20	3593
573	2	2	60	20	3593
574	3	0	36	20	3593
575	6	3	60	20	3603
576	4	0	29	20	3603
577	2	0	26	20	3603
578	4	4	60	20	3623
579	4	3	60	20	3623
580	3	0	7	20	3623
581	3	0	9	20	3623
582	4	3	60	20	3653 CB
583	4	2	60	25	X 3303 Carambola Cir
584	5	2	60	25	X 3303 Carambola Cir
585	3	2	60	25	X 3313
586	4	3	60	25	X 3343
587	4	0	24	25	X 3343
588	3	0	27	25	X 3343
589	2	0	14	25	X 3343
590 501	2	0	35	25	X 3343
591 592	4	0	37 23	25	X 3343
592 593	2 4	0	<u>23</u> 30	25 25	X 3343 X 3343
393	4	U	30	23	∧

#	High/8ths	Low/8ths	Inches	Sq Ft	Hazard Location
594	3	0	26	25	X 3343
595	3	1	60	25	X 3343
596	3	1	60	25	X 3403
597	3	0	30	25	X 3403
598	3	0	19	25	X 3403
599	2	0	18	25	X 3403
600	3	1	51	25	X 3403
601	3	0	33	25	X 3403
602	2	0	21	25	X 3403
603	2	0	23	25	X 3403
604	3	0	32	25	X 3403
605	4	2	60	25	X 3413
606	3	2	54	25	X 3413
607	3	0	54	25	X 3413
608	2	2	60	25	X 3413
609	6	2	40	25	X 3413
610	5	3	60	25	X 3413
611	4	2	60	25	X 3433
612	4	3	60	25	3452
613	3	2	60	25	3452
614	7	0	23	25	3452
615	4 5	1	60 60	25	3462
616 617	3	4	60 60	25 25	<u>3472</u> 3482
	6		27	25 25	3482
618 619	4	0	27	25 25	3462 3502
620	4	0	31	25	3502
621	3	0	17	25	3502
622	7	0	48	25	3502
623	3	2	60	25	3512
624	6	0	48	25	3512
625	3	0	12	25	3512
626	3	1	60	25	3522
627	3	0	34	25	3522
628	4	0	31	25	X 3553
629	3	0	26	25	X 3553
630	5	4	60	25	3702
631	4	0	27	25	3762
632	4	0	26	25	3762
633	3	0	22	25	3762
634	4	0	27	25	3762
635	4	3	60	25	3792
636	5	4	60	25	3802
637	7	4	72	30	Corner of Carambola Cir
638	6	4	60	25	3862 Carambola Cir
639	7	4	60	25	3872
640	4	4	60	25	3872
641	3	2	60	25	3673 Carambola Cir
642	4	2	60	25	3673
643	4	0	42	25	3703
644	3	0	16	25	3703
645 646	2 5	1 5	60 60	25	3703
646 647	5 3	5 0	60 34	25 25	3763 3763
648	3	1	<u> </u>	25 25	3763 3793
648	3 4	2	45	25 25	3793 3803
649	4 2	<u> </u>	45 60	25 25	3803
650	3	0	29	25 25	3803
652	2	0	32	25 25	3833
653	4	3	<u> </u>	25 25	3833
000	-7	5	00	20	0000

654 7 4 60 25 3363 655 3 0 32 25 3373 656 3 00 22 3953 3673 657 4 3 60 25 3953 659 5 2 60 25 3953 660 10 7 60 25 3953 661 7 4 60 25 3953 661 7 4 60 25 3923 663 4 2 60 25 3823 664 4 2 60 25 3823 666 10 0 43 25 3802 3873 666 7 0 43 25 3802 3873 671 6 2 66 25 6953 6953 671 6 2 60 25 6953 6953	#	High/8ths	Low/8ths	Inches	Sq Ft	Hazard Location
656 3 0 32 25 3873 657 4 3 60 25 3953 Grambola Gir 658 4 3 60 25 3953 Grambola Gir 659 5 2 60 25 3853 Grambola Gir 661 7 4 60 25 3823 Grambola Gir 662 4 2 60 25 3873 Grambola Gir 662 4 2 60 25 3873 Grambola Gir 664 4 2 60 25 3873 Grambola Gir 666 10 0 43 25 3802 Grambola Gir Grambola Gir 666 2 0 17 25 3802 Grambola Gir 677 7 0 36 25 Grambola Gir Grambola Gir 672 5 46 25 Grambola Gir Grambola Gir Grambola Gir	654	7	4	60	25	3853
657 4 3 60 25 3953 658 4 3 60 25 3953 659 5 2 60 25 3953 660 10 7 60 25 3953 661 7 4 60 25 3933 662 4 2 60 25 3833 663 4 3 60 25 3873 666 10 0 43 25 3802 3802 667 3 2 64 50 3802 3802 670 7 0 36 25 x3893 3671 673 3 0 39 25 6963 6963 6963 676 3 2 60 25 6963 6963 6963 677 4 1 60 25 6963 6964 6963 6964 <td< td=""><td>655</td><td>4</td><td>1</td><td>60</td><td>25</td><td>3873</td></td<>	655	4	1	60	25	3873
668 4 3 60 25 3953 669 10 7 60 25 3953 661 7 4 60 25 3953 661 7 4 60 25 3923 662 4 2 60 25 3933 663 4 2 60 25 3973 664 4 2 60 25 3973 665 3 2 64 50 3802 Carambola Cir 666 10 0 43 25 3802 670 7 0 36 25 x3933 670 7 0 36 25 x3933 671 6 2 60 25 6933 674 6 2 60 25 6933 675 4 0 51 25 6923 676 4 0 51 <td>656</td> <td>3</td> <td></td> <td>32</td> <td>25</td> <td>3873</td>	656	3		32	25	3873
659 5 2 60 25 3953 661 7 4 60 25 3953 661 7 4 60 25 3953 662 4 2 60 25 3923 663 4 3 60 25 3863 664 4 2 60 25 3873 666 10 0 43 25 3802 Carambola Cir 667 3 2 64 50 3802 carambola Cir 668 7 0 43 25 3802 670 7 0 36 25 x3893 671 6 2 66 25 6693 Kepler Dr 672 5 0 46 26 6923 6933 674 6 2 60 25 6913 6912 673 2 60 25 6913 6912	657					3953 Carambola Cir
660 10 7 60 25 3953 661 7 4 60 25 3933 662 4 2 60 25 3923 663 4 2 60 25 3873 664 4 2 60 25 3873 665 3 2 60 25 3873 666 10 0 43 25 3802 Carambola Cir 667 3 2 64 50 3802 atom drain 668 7 0 43 25 3802 670 7 0 36 25 x8933 671 6 2 66 25 6933 673 3 0 39 25 6933 674 6 2 60 25 6933 677 4 1 60 25 6912 680 3						
661 7 4 60 25 3933 662 4 2 60 25 3823 663 4 3 60 25 3823 664 4 2 60 25 3873 666 10 0 43 25 3802 Carambola Cir 666 10 0 43 25 3802 667 3 2 64 50 3802 carambola Cir 668 7 0 36 25 x3893 671 6 2 66 25 6863 Kepler Dr 672 5 0 46 25 6833 674 6 2 60 25 6923 676 3 2 60 25 6923 677 4 1 60 25 6923 678 3 1 60 25 6923 678 3						
662 4 2 60 25 3823 663 4 2 60 25 3873 666 3 2 60 25 3873 666 3 2 60 25 3873 666 10 0 43 25 3802 carambola Cir 667 3 2 64 50 3802 carambola Cir 668 7 0 43 25 3802 670 7 0 36 25 $x3893$ 671 6 2 66 25 6963 kepler Dr 673 3 0 39 25 6933 676 4 0 52 25 6933 677 4 1 60 25 6913 678 3 160 25 6912 681 3 260 25						
663 4 3 60 25 3883 664 4 2 60 25 3873 665 3 2 60 25 3873 666 10 0 43 25 3802 Carambola Cir 667 3 2 64 50 3802 storm drain 668 7 0 43 25 3802 670 7 0 36 25 x3893 671 6 2 66 25 6603 Kepter Dr 672 5 0 46 25 6933 674 6 2 60 25 6923 677 4 1 60 25 6923 678 3 2 60 25 6913 678 4 0 51 25 6913 679 4 0 51 25 6912 681 3 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>						
664 4 2 60 25 3873 665 3 2 60 25 3802 Carambola Cir 666 10 0 43 25 3802 Carambola Cir 667 3 2 64 50 3802 Carambola Cir 668 7 0 43 25 3802 Carambola Cir 669 2 0 17 25 3802 Carambola Cir 670 7 0 36 25 x3893 Carambola Cir 671 6 2 66 25 6963 Kepler Dr 673 3 0 39 25 6933 Carambola Cir 674 6 2 60 25 6933 Carambola Cir 676 4 0 51 25 6923 Carambola Cir 677 4 1 60 25 6932 Cararambola Cir 68						
665 3 2 60 25 3873 666 10 0 43 25 3802 Carambola Clr 667 3 2 64 50 3802 storm drain 668 7 0 43 25 3802 670 7 0 36 25 x3893 671 6 2 66 25 6963 Kepler Dr 672 5 0 46 25 6983 Kepler Dr 673 3 0 39 25 6933 675 674 6 2 60 25 6933 675 677 4 1 60 25 6923 6912 678 3 1 60 25 6912 6813 679 4 0 51 25 6912 6814 680 3 0 39 25 6912 6812 681 3 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>						
666 10 0 43 25 3802 Carambela Cir 667 3 2 64 50 3802 storm drain 668 7 0 43 25 3802 669 2 0 17 25 3802 670 7 0 36 25 x3893 671 6 2 66 25 6963 Kepler Dr 672 5 0 46 25 6963 Kepler Dr 673 3 0 39 25 6953 676 4 0 52 25 6933 676 4 0 52 25 6923 677 4 1 60 25 6912 680 3 0 39 25 6912 680 3 0 39 25 6912 681 3 2 60 25 6932 683						
667 3 2 64 50 3802 storm drain 668 7 0 43 25 3802 669 2 0 17 25 3802 670 7 0 36 25 x3833 671 6 2 66 25 6963 Kepler Dr 672 5 0 46 25 6963 Kepler Dr 673 3 0 39 25 6953 674 6 2 60 25 6933 675 3 2 60 25 6923 676 4 0 51 25 6913 679 4 0 51 25 6912 680 3 0 39 25 6912 681 3 2 60 25 6942 681 3 60 25 6942 682 5 60						
668 7 0 43 25 3802 669 2 0 17 25 3802 670 7 0 36 25 x3893 671 6 2 66 25 6963 Kepler Dr 672 5 0 46 25 6953 674 6 2 60 25 6953 677 3 0 39 25 6953 676 4 0 52 6933 6923 676 4 0 52 6913 6923 677 4 1 60 25 6912 680 3 0 39 25 6912 681 3 2 60 25 6932 681 3 2 60 25 6942 686 7 2 60 25 3191 686						
669201725 3802 670 703625 $x3893$ 671 626625 6963 Kepler Dr 672 504625 6963 Kepler Dr 673 303925 6953 674 626025 6933 675 326025 6933 676 405225 6923 677 416025 6923 677 316025 6912 680 303925 6912 681 326025 6912 681 326025 6942 681 326025 6942 681 326025 6942 684 436025 6942 684 436025 3191 685 856025 3191 686 72 60 25 3191 687 83 60 25 3191 688 31 60 25 3191 690 201325 3191 690 201325 3191 690 2018 25 3181 693 303225 3131						
670 7 0 36 25 x3893 671 6 2 66 25 6963 Kepler Dr 672 5 0 46 25 6953 673 3 0 39 25 6953 674 6 2 60 25 6933 675 3 2 60 25 6933 676 4 0 52 25 6923 677 4 1 60 25 6912 680 3 0 39 25 6912 681 3 2 60 25 6932 683 3 3 60 25 6932 684 4 3 60 25 6942 686 7 2 60 25 X3171 686 7 2 60 25 X3171 686 7 2						
6716266256963 Kepter Dr 672 5046256963 Kepter Dr 673 3039256953 674 6260256933 676 4052256923 677 4160256923 677 4160256923 677 4051256912 680 3039256912 680 3039256912 680 3039256912 681 3260256942 681 3260256942 682 5360256942 684 4360256942 684 4360253191 687 8360253191 687 8360253191 688 3160253191 690 2013253191 690 2013253191 690 2013253181 693 3032253181 694 4038253181 693 3033253181 694 403825317						
6725046256963 Kepler Dr 673 3039256933 674 6260256933 675 3260256923 676 4052256923 677 4160256923 677 4051256913 677 4051256912 680 3039256912 680 3039256912 681 3260256932 683 3360256942 684 4360256942 684 4360256942 686 726025X3171 687 8360253191 689 6042253191 689 6042253191 690 2013253181 693 3032253181 694 3033253181 694 3032253181 699 4032253181 699 4032253131 699 5460253131 699 637253131						
6733039256963 674 6260256933 675 3260256933 676 4052256923 677 4160256923 678 3160256913 678 3160256912 680 3039256912 681 3260256912 681 3260256942 684 4360256942 684 4360256942 684 4360256942 684 4360253191 687 8360253191 687 8360253191 688 3160253191 689 6042253191 689 6042253191 690 2018253181 693 3032253181 693 032253181 694 3032253181 699 4032253181 699 4032253181 699 4032253131 699 <	-					
6746260256933 675 3260256933 676 4052256923 677 4160256923 678 3160256913 679 4051256912 680 3039256912 681 3260256912 682 5360256932 683 3360256932 684 4360256942 684 4360256942 684 7260253191 685 8560253191 686 7260253191 686 7260253191 686 042253191 699 6042253191 691 4160253191 692 2013253181 694 3033253181 694 3032253181 694 3033253181 694 3033253181 694 3033253131 694 032253131 694 0<						
67532 60 25 6933 676 40 52 25 6923 677 41 60 25 6923 678 31 60 25 6913 679 40 51 25 6912 680 30 39 25 6912 681 32 60 25 6912 681 32 60 25 6942 682 53 60 25 6942 683 33 60 25 6942 684 43 60 25 6942 684 43 60 25 8962 685 85 60 25 8942 686 72 60 25 3171 687 83 60 25 3191 688 31 60 25 3191 690 20 13 25 3191 690 20 18 25 3181 693 30 32 25 3171 696 32 60 25 3131 693 30 32 25 3171 693 30 32 25 3181 693 30 32 25 3181 693 30 32 25 3171 693 <th< td=""><td></td><td></td><td></td><td></td><td></td><td></td></th<>						
6764052256923 677 4160256913 678 3160256913 679 4051256912 680 3039256912 681 3260256912 682 5360256942 682 5360256942 684 4360256942 684 4360256942 686 7260253191 685 8560253191 686 7260253191 686 7260253191 687 8360253191 688 3160253191 689 6042253191 699 2013253191 691 4160253181 693 3032253181 694 3038253171 697 5460253171 697 5460253171 697 5460253131 697 5037253131 697 5460253131						
6774160256923 678 3160256913 679 4051256912 680 3039256912 681 3260256932 681 3260256932 682 5360256932 683 3360256942 684 4360256942 684 4360256942 686 726025X3171 687 836025X3171 687 8360253191 688 3160253191 689 6042253191 690 2013253191 690 2018253181 691 4160253181 693 3032253181 693 3032253181 694 038253171 696 3260253131 699 4032253131 699 4032253131 699 4032253131 699 4032253131 699 <td>-</td> <td></td> <td></td> <td></td> <td></td> <td></td>	-					
67831 60 25 6913 679 4051 25 6912 680 30 39 25 6912 681 32 60 25 6912 682 53 60 25 6942 684 43 60 25 6942 684 43 60 25 6942 684 43 60 25 6942 685 85 60 25 6942 686 72 60 25 $X3171$ 687 83 60 25 $X3171$ 688 31 60 25 3191 690 20 13 25 3191 690 20 13 25 3191 690 20 13 25 3191 692 20 18 25 3181 692 20 18 25 3181 694 30 32 25 3181 694 0 32 25 3131 694 0 32 25 3131 694 0 32 25 3131 694 0 32 25 3131 695 40 32 25 3131 696 320 37 25 3131 699 40 32						
67940512569126803039256912681326025691268253602569326833360256942684436025694268585602569426867260258942686726025X317168783602531916883160253191689604225319169020132531916914160253191692201825318169330322531816943033253181695403825317169632602531316975460253131698201625313170050372531317013020253121702203725312170430392531217052037253121706986025	-					
680 3 0 39 25 6912 681 3 2 60 25 6912 682 5 3 60 25 6932 683 3 3 60 25 6942 684 4 3 60 25 6942 684 4 3 60 25 6942 685 8 5 60 25 X3171 686 7 2 60 25 X3171 687 8 3 60 25 X3171 688 6 0 42 25 3191 689 6 0 42 25 3191 690 2 0 13 25 3181 691 4 1 60 25 3181 692 2 0 18 25 3181 693 3 2 6			0			
682536025 6932 683 336025 6942 684 436025 6942 685 856025 6942 686 726025 $X3171$ 687 836025 $X3171$ 687 836025 $X3171$ 688 316025 3191 689 604225 3191 690 201325 3191 690 201325 3191 691 416025 3191 692 201825 3181 693 303225 3181 693 303325 3181 694 303825 3171 696 326025 3171 697 546025 3131 Camberly Cir 698 201625 3131 Camberly Cir 700 503725 3131 Camberly Cir 701 302025 3121 704 303925 3121 706 986025 3121 706 986025 3091 710 6025 3091 <t< td=""><td>680</td><td></td><td>0</td><td></td><td></td><td>6912</td></t<>	680		0			6912
683 3 3 60 25 6942 684 4 3 60 25 6962 Keplar Dr 685 8 5 60 25 6942 686 7 2 60 25 X3171 687 8 3 60 25 X3171 688 3 1 60 25 X3171 688 6 0 42 25 3191 Camberly Cir 689 6 0 42 25 3191 690 2 0 13 25 3191 691 4 1 60 25 3191 692 2 0 18 25 3181 693 3 0 32 25 3181 694 3 0 38 25 3171 696 3 2 60 25 3131 Camberly Cir 699 4 </td <td>681</td> <td>3</td> <td>2</td> <td>60</td> <td>25</td> <td>6912</td>	681	3	2	60	25	6912
684 4 3 60 25 6962 Keplar Dr 685 8 5 60 25 6942 686 7 2 60 25 X3171 687 8 3 60 25 X3171 688 3 1 60 25 X3171 688 3 1 60 25 X3171 689 6 0 42 25 3191 Camberly Cir 689 6 0 42 25 3191 690 2 0 18 25 3181 691 4 1 60 25 3181 692 2 0 18 25 3181 693 3 0 33 25 3181 694 3 0 38 25 3171 696 3 2 60 25 3131 Camberly Cir 697 5<	682	5	3	60	25	6932
68585 60 25 6942 686 72 60 25 $X3171$ 687 83 60 25 $X3171$ 688 31 60 25 3191 689 60 42 25 3191 690 20 13 25 3191 690 20 13 25 3191 691 41 60 25 3191 692 20 18 25 3181 693 30 32 25 3181 693 30 33 25 3181 694 30 33 25 3181 694 30 33 25 3171 696 32 60 25 3171 696 32 60 25 3171 697 54 60 25 3131 Camberly Cir 700 50 37 25 3131 Camberly Cir 701 30 20 25 3121 703 20 17 25 3121 706 98 60 25 3121 706 98 60 25 3121 707 42 60 25 3101 709 5019 25 3091 711 118 60 25 3071 <td>683</td> <td>3</td> <td>3</td> <td>60</td> <td>25</td> <td>6942</td>	683	3	3	60	25	6942
68672 60 25 X3171 687 83 60 25 X3171 688 31 60 25 3191 Camberly Cir 689 60 42 25 3191 690 20 13 25 3191 691 41 60 25 3191 692 20 18 25 3191 693 30 32 25 3181 694 30 33 25 3181 694 30 33 25 3171 696 32 60 25 3171 696 32 60 25 3171 697 54 60 25 3131 Camberly Cir 698 20 16 25 3131 Camberly Cir 700 50 37 25 3131 Camberly Cir 701 30 20 25 3121 702 20 37 25 3121 704 30 39 25 3121 706 98 60 25 3101 709 50 19 25 3091 710 60 33 25 3091 711 118 60 25 3071	684	4	3	60	25	6962 Keplar Dr
687 8 3 60 25 X3171 688 3 1 60 25 3191 Camberly Cir 689 6 0 42 25 3191 690 2 0 13 25 3191 690 2 0 13 25 3191 691 4 1 60 25 3191 692 2 0 18 25 3181 693 3 0 32 25 3181 694 3 0 33 25 3171 696 3 2 60 25 3171 697 5 4 60 25 3131 Camberly Cir 698 2 0 16 25 3131 Camberly Cir 700 5 0 37 25 3131 Camberly Cir 701 3 0 20 25 3131 Camberly Cir <	685					6942
688 3 1 60 25 3191 Camberly Cir 689 6 0 42 25 3191 690 2 0 13 25 3191 691 4 1 60 25 3191 692 2 0 18 25 3181 693 3 0 32 25 3181 694 3 0 33 25 3181 695 4 0 38 25 3171 696 3 2 60 25 3131 Camberly Cir 697 5 4 60 25 3131 Camberly Cir 698 2 0 16 25 3131 Camberly Cir 700 5 0 37 25 3131 Camberly Cir 701 3 0 20 25 3131 Camberly Cir 703 2 0 17 25 3121 <t< td=""><td>-</td><td></td><td></td><td></td><td></td><td></td></t<>	-					
689 6 0 42 25 3191 690 2 0 13 25 3191 691 4 1 60 25 3191 692 2 0 18 25 3181 693 3 0 32 25 3181 694 3 0 33 25 3181 694 3 0 33 25 3181 695 4 0 38 25 3171 696 3 2 60 25 3171 697 5 4 60 25 3171 698 2 0 16 25 3131 Camberly Cir 700 5 0 37 25 3131 Camberly Cir 701 3 0 20 25 3121 703 2 0 17 25 3121 704 3 <			3			
690 2 0 13 25 3191 691 4 1 60 25 3191 692 2 0 18 25 3191 692 2 0 18 25 3181 693 3 0 32 25 3181 694 3 0 33 25 3181 695 4 0 38 25 3171 696 3 2 60 25 3171 697 5 4 60 25 3131 698 2 0 16 25 3131 Camberly Cir 700 5 0 37 25 3131 Camberly Cir 701 3 0 20 25 3121 3121 703 2 0 17 25 3121 3121 705 2 0 37 25						
691 4 1 60 25 3191 692 2 0 18 25 3181 693 3 0 32 25 3181 693 3 0 33 25 3181 694 3 0 33 25 3181 695 4 0 38 25 3171 696 3 2 60 25 3171 696 3 2 60 25 3171 697 5 4 60 25 3131 Camberly Cir 698 2 0 16 25 3131 Camberly Cir 700 5 0 37 25 3131 Camberly Cir 701 3 0 20 25 3121 703 2 0 17 25 3121 704 3 0 39 25 3121 706 9 </td <td></td> <td></td> <td>-</td> <td></td> <td></td> <td></td>			-			
692 2 0 18 25 3181 693 3 0 32 25 3181 694 3 0 33 25 3181 694 3 0 33 25 3181 694 3 0 33 25 3181 695 4 0 38 25 3171 696 3 2 60 25 3171 697 5 4 60 25 3131 698 2 0 16 25 3131 Camberly Cir 699 4 0 32 25 3131 Camberly Cir 700 5 0 37 25 3131 Camberly Cir 701 3 0 20 25 3131 Camberly Cir 703 2 0 17 25 3121 704 705 2 0 37<						
693 3 0 32 25 3181 694 3 0 33 25 3181 695 4 0 38 25 3171 696 3 2 60 25 3171 696 3 2 60 25 3171 697 5 4 60 25 3171 698 2 0 16 25 3131 Camberly Cir 699 4 0 32 25 3131 Camberly Cir 700 5 0 37 25 3131 Camberly Cir 701 3 0 20 25 3131 Camberly Cir 702 2 0 30 25 3121 703 2 0 17 25 3121 704 3 0 39 25 3121 705 2 0 37 25 3121 706						
694 3 0 33 25 3181 695 4 0 38 25 3171 696 3 2 60 25 3171 697 5 4 60 25 3171 698 2 0 16 25 3131 Camberly Cir 699 4 0 32 25 3131 Camberly Cir 700 5 0 37 25 3131 Camberly Cir 701 3 0 20 25 3131 Camberly Cir 702 2 0 30 25 3121 703 2 0 17 25 3121 704 3 0 39 25 3121 705 2 0 37 25 3121 706 9 8 60 25 3121 707 4 2 60 25 3111 708						
695 4 0 38 25 3171 696 3 2 60 25 3171 697 5 4 60 25 3171 697 5 4 60 25 3171 698 2 0 16 25 3131 Camberly Cir 699 4 0 32 25 3131 Camberly Cir 700 5 0 37 25 3131 Camberly Cir 701 3 0 20 25 3131 Camberly Cir 702 2 0 30 25 3121 703 2 0 17 25 3121 704 3 0 39 25 3121 705 2 0 37 25 3121 706 9 8 60 25 3121 707 4 2 60 25 3101 708						
696 3 2 60 25 3171 697 5 4 60 25 3171 698 2 0 16 25 3131 Camberly Cir 699 4 0 32 25 3131 Camberly Cir 700 5 0 37 25 3131 Camberly Cir 701 3 0 20 25 3131 Camberly Cir 702 2 0 30 25 3121 703 2 0 17 25 3121 704 3 0 39 25 3121 705 2 0 37 25 3121 706 9 8 60 25 3121 707 4 2 60 25 3121 707 4 2 60 25 3101 709 5 0 19 25 3091 710						
697 5 4 60 25 3171 698 2 0 16 25 3131 Camberly Cir 699 4 0 32 25 3131 Camberly Cir 700 5 0 37 25 3131 Camberly Cir 701 3 0 20 25 3131 Camberly Cir 702 2 0 30 25 3121 703 2 0 17 25 3121 704 3 0 39 25 3121 704 3 0 39 25 3121 705 2 0 37 25 3121 706 9 8 60 25 3121 707 4 2 60 25 3101 708 6 2 60 25 3091 710 6 0 33 25 3091 710						
698 2 0 16 25 3131 Camberly Cir 699 4 0 32 25 3131 Camberly Cir 700 5 0 37 25 3131 Camberly Cir 701 3 0 20 25 3131 Camberly Cir 702 2 0 30 25 3121 703 2 0 17 25 3121 704 3 0 39 25 3121 705 2 0 37 25 3121 706 9 8 60 25 3121 707 4 2 60 25 3121 708 6 2 60 25 3101 709 5 0 19 25 3091 710 6 0 33 25 3091 711 11 8 60 25 3071						
699 4 0 32 25 3131 Camberly Cir 700 5 0 37 25 3131 Camberly Cir 701 3 0 20 25 3131 Camberly Cir 702 2 0 30 25 3131 Camberly Cir 703 2 0 17 25 3121 704 3 0 39 25 3121 705 2 0 37 25 3121 706 9 8 60 25 3121 707 4 2 60 25 3121 708 6 2 60 25 3101 709 5 0 19 25 3091 710 6 0 33 25 3091 711 11 8 60 25 3071						
700 5 0 37 25 3131 Camberly Cir 701 3 0 20 25 3131 Camberly Cir 702 2 0 30 25 3121 703 2 0 17 25 3121 704 3 0 39 25 3121 705 2 0 37 25 3121 705 2 0 37 25 3121 706 9 8 60 25 3121 707 4 2 60 25 3121 708 6 2 60 25 3101 709 5 0 19 25 3091 710 6 0 33 25 3091 711 11 8 60 25 3071						
701 3 0 20 25 3131 Camberly Cir 702 2 0 30 25 3121 703 2 0 17 25 3121 704 3 0 39 25 3121 705 2 0 37 25 3121 706 9 8 60 25 3121 707 4 2 60 25 3121 708 6 2 60 25 3101 709 5 0 19 25 3091 710 6 0 33 25 3091 711 11 8 60 25 3071						
702 2 0 30 25 3121 703 2 0 17 25 3121 704 3 0 39 25 3121 705 2 0 37 25 3121 706 9 8 60 25 3121 707 4 2 60 25 3111 708 6 2 60 25 3101 709 5 0 19 25 3091 710 6 0 33 25 3091 711 11 8 60 25 3071						
703 2 0 17 25 3121 704 3 0 39 25 3121 705 2 0 37 25 3121 706 9 8 60 25 3121 707 4 2 60 25 3111 708 6 2 60 25 3101 709 5 0 19 25 3091 710 6 0 33 25 3091 711 11 8 60 25 3071						
704 3 0 39 25 3121 705 2 0 37 25 3121 706 9 8 60 25 3121 707 4 2 60 25 3111 708 6 2 60 25 3101 709 5 0 19 25 3091 710 6 0 33 25 3091 711 11 8 60 25 3071						
705 2 0 37 25 3121 706 9 8 60 25 3121 707 4 2 60 25 3111 708 6 2 60 25 3101 709 5 0 19 25 3091 710 6 0 33 25 3091 711 11 8 60 25 3071						
706 9 8 60 25 3121 707 4 2 60 25 3111 708 6 2 60 25 3101 709 5 0 19 25 3091 710 6 0 33 25 3091 711 11 8 60 25 3071						
707 4 2 60 25 3111 708 6 2 60 25 3101 709 5 0 19 25 3091 710 6 0 33 25 3091 711 11 8 60 25 3071						
708 6 2 60 25 3101 709 5 0 19 25 3091 710 6 0 33 25 3091 711 11 8 60 25 3071						
709 5 0 19 25 3091 710 6 0 33 25 3091 711 11 8 60 25 3071						
710 6 0 33 25 3091 711 11 8 60 25 3071						
712 3 1 60 25 2071	711	11	8	60	25	3071
	712	3	1	60	25	3071
713 6 6 60 25 3031	713	6	6	60	25	3031

#	High/8ths	Low/8ths	Inches	Sq Ft	Hazard Location
714	3	0	32	25	3031
715	3	0	28	25	3021
716	7	3	60	25	3021
717	4	2	60	25	3011
718	6	0	51	25	3011
719	8	4	60	25	3011
720	7	5	60	25	3001
721	8	4	60	25	3001
722	3	0	43	25	3001
723	2	0	44	25	2991
724	5 4	0	41	25	2981
725 726	4 6	0 2	48 60	25 25	<u> </u>
720	3	0	36	25	2971
728	7	4	60	25	2951
729	3	1	60	25	2951
730	4	1	60	25	2951
731	5	0	39	25	2951
732	3	1	60	25	2941
733	3	0	45	25	2941
734	6	4	60	25	2931
735	5	0	38	25	2931
736	4	2	60	25	2931
737	3	3	60	25	2921
738	3	1	60	25	2921
739	2	2	60	25	2911
740	3	2	60	25	X3151 Camberly Cir
741	3	2	60	25	X3131
742	5	2	60	25	X3121
743	2	0	24	25	X3121
744	3	0	44	25	X3101
745	4	2	60	25	X3101
746	3	2	60	25	X3091
747	3	2	60	25	X3091
748	3	2	60	25	X3081
749	4	2	60	25	X3081
750	5	4	60	25	X3081
751	6	4 7	60 72	25	X3081 3010
752 753	8 7	6	16	25 0	Sec 2
754	3	0	30	25	3000
755	3	0	30	25	3000
756	4	3	60	25	3000
757	3	3	66	25	X2971
758	5	4	60	25	2960
759	4	2	60	25	2960
760	5	3	60	25	2940
761	3	2	60	25	2960
762	9	6	60	25	2940
763	6	5	66	25	2940
764	4	2	60	25	2940
765	3	0	37	25	2940
766	3	0	23	25	2940
767	6	0	39	25	2940
768	3	0	21	25	2940
769	5	3	60	25	2940
770	3	2	60	25	2940
771	4	2	60	25	X2931
772	4	3	60	25	X2921
773	3	0	35	25	X2911

#	High/8ths	Low/8ths	Inches	Sq Ft	Hazard Location
774	3	0	38	25	X2911
775	3	0	22	25	X2911
776	4	0	36	25	2901
777	5	2	60	25	2901
778	2	0	30	25	X2901
779	4	3	60	25	X2901
779	3,009	1,067	36,185	19,027	TOTALS

OTED	Service Report	
PUMPING SYSTEMS	Scheduled:6/13/2025 Tech: AAA Warranty Expires: 12/1/2022 Maint Expires: 11/30/2025	Work Order#:186259
2801 N. Powerline Road Pompano Beach, FL 33069 Tel 954-971-7350 Fax 855-365-PUMP (7	867)	
Bill to Customer #: 5822 Heritage Isle at Viera CDD Attn: c/o Rizzetta & Company 8529 South Park Circle Ste #330 Orlando, FL, 32819 Tel: 407-472-2471 Fax: 407-472-2478 Cust. P.O.#	Job Site: Site ID# 9153 Heritage Isle South Legacy Blvd Melbourne, FL 32940 Tel: Contact: Brian Mendes Maintenance: FG2 Model: HC2F-60J20PDV-460	S
	Pump System	
Sta	ation Design: 1,300 GPM at 70 PSI	
Job Completed YES 🗹 NO	Hoover Additional Work Requir	ed YES NO
System Operating YES 📝 NO	Additional Work Required By Custon	ner YES NO

Nature of Call

Visit #2 of 2, Year 1 of 1, Level 5 Tighten electrical connections, check surge protection, and test control logic, Adjust pressure tank to correct set point (if applicable), Verify motor connections within junction boxes, Grease motor bearings (if applicable), Check condition of motor seal(s) (if applicable), Clean wye-strainer(s) and flush all hydraulic tubing, Clean filtration system control filter(s) (if applicable), Clean rain gauge and replace protective basin filter (if applicable), Replace panel AC unit filter (if applicable), Clean enclosure, skid, and slab, Verify proper operation of Variable Frequency Drives (VFDs) (if applicable), Test flow meter(s) and pressure transducer(s) for proper operation, Evaluate pump performance, Check UPS backup battery, Check RCS operation and rebuild (if applicable), Check level transducer operation (if applicable), Check HMI (if applicable), Rebuild shut-off valve (if applicable), Check operation of chemical pump (if applicable) per proposal# MA 6815. Service pre-authorized for up to \$0.00

Work Performed

Hoover technician Tony sent an email/text to Brian prior to arrival.

- Upon arrival, the technician checked and torqued connections in panel.
- Checked and torqued connections in VFD.
- Checked all motor cased motors and greased motors.
- Verified tank pressure.
- Cleaned y-strainer.
- Replaced AC filter.
- Checked filter discs and pods.
- Removed a leaking air relief valve and installed a plug.
- Ran water and tested syystem for operation.
- Checked and cleaned rain gauge and replaced filter for rain gauge.
- Hosed off skid.
- Wiped down components.
- Left system as it was found.
- Maintenance complete.



Service Report

Scheduled:6/13/2025 Tech: AAA Warranty Expires: 12/1/2022 Maint Expires: 11/30/2025 Work Order#:186259

2801 N. Powerline Road Pompano Beach, FL 33069 Tel 954-971-7350 Fax 855-365-PUMP (7867)

Work Performed





June 5, 2025

Ana Saunders, P.E. B.S.E. Consultants, Inc. 312 S. Harbor City Boulevard, Suite 4 Melbourne, FL 32901

RE: Heritage Isle Community Pedestrian Bridges

Subject: Inspection Price Proposal

Ms. Saunders,

Per B.S.E. Consultants, Inc.'s request, RUSH Marine LLC. is pleased to provide this proposal to perform inspection services of five pedestrian bridges located within the Heritage Isle community. See below for additional details concerning the services provided and a cost summary.

Inspection Services Include:

- RUSH Marine will provide all labor, equipment, and materials to complete all necessary work.
- RUSH Marine will inspect the condition of the timber materials, including piling, stringers, decking, handrails, and retaining walls for signs of damage and deterioration.
- RUSH Marine will inspect the condition of the hardware materials, including thru-bolts, nuts & washers, nails & screws, and tie-back systems for signs of damage and corrosion.
- RUSH Marine will inspect the condition of the soil surrounding the bridges, retaining walls, and concrete approach slabs for signs of erosion.
- Upon completion of the inspection, RUSH Marine will provide B.S.E. with a report outlining the findings and recommendations for repairs.

Excluded Items:

Furnishing of all materials, labor, and equipment associated with the recommended repairs.

Clarifications:

- Following Notice to Proceed, we are anticipating that it will take 4 days to mobilize and perform the necessary inspections at the five pedestrian bridge locations.
- The Heritage Isle security or management team shall allow for street parking and the loading and unloading of equipment for our team at each bridge location.


Continuation of Clarifications

 RUSH Marine has performed preliminary inspections of the superstructure from the top side of all five bridges. To provide a report as requested, it is necessary to mobilize waterside equipment to perform the necessary inspections on the underside of the bridge structures and bulkhead approaches.

Cost summary:

The total cost associated with this scope of work is **\$15,025.00 (Fifteen Thousand Twenty-Five dollars)**. No additional contingency funds have been included. Following submission of the evaluation report, RUSH Marine can provide a cost estimate for the necessary repairs based on the recommendations provided within the evaluation report.

Should this proposal be acceptable, please provide a purchase order at your earliest convenience so our team can continue with the remaining inspection and provide the requested evaluation report.

Please do not hesitate to contact us, should you have any questions regarding this proposal. We would like to thank you for this opportunity as we look forward to working with the B.S.E. staff on this project.

Sincerely, RUSH MARINE LLC.

Unthony tenday

Anthony Landry President – RUSH Marine LLC.

TAB 6

1	MINUTES OF MEETING				
2 3 4 5 6 7	Each person who decides to appeal any decision made by the Board with respect to any matter considered at the meeting is advised that the person may need to ensure that a verbatim record of the proceedings is made, including the testimony and evidence upon which such appeal is to be based.				
8 9	HERITAGE ISLE AT VIERA				
10	COMMUN	ITY DEVELOPMENT DISTRICT			
11 12 13 14 15 16	Development District was held o	d of Supervisors of Heritage Isle at Viera Community on May 20, 2025, at 12:30 p.m. at the Brevard County om, located at 2725 Judge Fran Jamieson Way, Viera,			
17 18	Present and constituting a	quorum:			
19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35	Jay Williams Bob Goldstein Jo LaBrecque Jon Smallegan Kenneth Walter Also present were: Brian Mendes Kyle Magee Ana Saunders Chris Wade Dave Thomas Bill Fisher Cotton Roberts	Board Supervisor, Chairman Board Supervisor, Vice Chairman Board Supervisor, Assistant Secretary Board Supervisor, Assistant Secretary Board Supervisor, Assistant Secretary District Manager, Rizzetta & Company District Counsel, Kutak Rock LLP District Engineer, BSE Consultants Landscape Maintenance, Juniper Landscape Maintenance, Juniper Landscape Maintenance, Juniper Aquatic Maintenance, Aquagenix			
36	Audience	Present			
37 38	FIRST ORDER OF BUSINESS	Call to Order/Roll Call			
39 40	Mr. Williams called the mee	eting to order and called the roll. Quorum was established.			
41 42	SECOND ORDER OF BUSINES	S Audience Comments			
43 44 45 46	and expressed the impor	nplimented the District regarding landscape refreshments tance communication efforts regarding landscape e member also complimented Supervisor Walter on his			

47	perfor	rmance.	
48 49	THIRD O	ORDER OF BUSINESS	Community Updates
50 51	Α.	. Juniper Community Update	
52 53 54		Mr. Williams and the Juniper team brie projects in the community.	efed the Board about current operations and
55 56 57		Mr. Williams updated the Board of Sup ongoing projects at the parks.	pervisors regarding the mow schedules and
58 59 60		Mr. Williams commented about issues their best to work through the obstack	with weed control and that Juniper is doing es.
61 62 63		Mr. Williams updated the Board of discussed a fertilizer program being r	Supervisors regarding palm pruning and endered.
64 65	B.	. Field Inspection Updates	
66 67		No Board or audience discussion ens	ued.
68 69	C.	. Monthly Report Update by Superviso	<u>Ken Walter</u>
70 71		Mr. Walter complimented Juniper's pe	erformance during the drought season.
72 73		Mr. Walter reviewed his reports with	he Board of Supervisors and District Staff.
74 75		Mr. Walter reviewed the massive irrig	gation project being prepped for next year.
76 77		Mr. Walter reviewed proposals need	
78 79		Mr. Walter reviewed the completed F	
80 81		Supervisor Goldstein complimented	
82			
83 84		Mr. Walter reviewed the joint landsca	
85 86	_		additional irrigation bids for other phases.
87 88	D.	. Pond Maintenance Update	
89 90 91		Mr. Roberts reported on progress w treatments have been progressing we	ith pond maintenance and that stem rush II.
92		Mr. Roberts discussed possible hydri	la treatment with the Board.

93		Mr. Williams requested Aquagenix to prep a pamphlet of treatment updates.
94 95		Mr. Mendes stated that the treatments have been looking good.
96 97		The Board thanked Aquagenix for their performance.
98 99		Mr. Roberts reported that the water's health looks great.
100 101		Mr. Walter suggested before and after pictures.
102 103	FOUF	RTH ORDER OF BUSINESS Staff Reports
104 105	A.	. <u>District Counsel</u>
106 107		Mr. McGee briefed the Board on upcoming budget discussion.
108 109		Mr. Williams inquired about Form 1 forms.
110 111 112	В.	. <u>District Engineer</u>
113 114		Ms. Saunders briefed and reviewed all engineering updates with the Board of Supervisors.
115 116 117		Ms. Saunders reported on struggles with bridge bids.
118		Ms. Saunders prepped the Board on the upcoming hurricane season.
119 120		Mr. Williams requested a hurricane e-blast be prepped and sent out to residents.
121 122 123		Mr. Walter commented regarding the needed square footage for sidewalks for upcoming pressure wash project.
124 125 126		Ms. LaBrecque commented about residents putting debris near storm drains.
120 127 128		Mr. Walter inquired about separation of irrigation system.
120 129 130		Ms. Saunders explained efforts from the team regarding this matter.
131 132		Discussion ensued amongst the Board regarding issues with the looping system.
133 134		Mr. Walter requested meeting with Ms. Saunders and Mr. Wade to review this connection issue.
135 136 137 138	C.	District Manager 1. Presentation of Registered Voter Count 2. Website Audit

HERITAGE ISLE AT VIERA COMMUNITY DEVELOPMENT DISTRICT May 20, 2025 Minutes of Meeting Page 4

139 140	 Quarterly Newsletter Update (Under Separate Cover) 	
141 142 143 144	 Sidewalk Repairs Update Mr. Mendes reviewed all agenda items with the E questions. 	Board and asked if there were any
145 146 147	Mr. Williams reviewed the newsletter success.	
148 149	Mr. Mendes stated that he will follow up regarding the	Quint sidewalk repair.
150 151	Mr. Mendes reviewed the sidewalk repairs progression	n.
152 153 154 155	FIFTH ORDER OF BUSINESS	Consideration of the Minutes of the Board of Supervisors' Meeting held on March 25, 2025
156 157	Mr. Williams presented the meeting minutes from the E March 25, 2025 and asked if any changes were reque	
158 159 160 161	Mr. Mendes stated that the School Now billing the Dist financial statements confirm this.	trict was not double billed and that the
	On a Motion by Mr. Smallegan, seconded by Mr. W Supervisors approved the Board of Supervisor Reg 2025, in substantial form, for Heritage Isle at Viera (ular Meeting minutes held March 25,
162 163 164 165	SIXTH ORDER OF BUSINESS	Ratification of Operation and Maintenance Expenditures for March – April 2025
166 167 168	Mr. Williams presented the expenditures to the Board c any questions.	of Supervisors and asked if there were
169 170 171	Mr. Walter commented about Juniper billing issues.	
	On a Motion by Mr. Walter, seconded by Ms. LaBre Supervisors ratified the operation and maintenance (\$49,508.15) and April (\$144,037.33), for Heritage I Development District.	expenditures for March
172 173	SEVENTH ORDER OF BUSINESS	Ratification of District Items
174 175 176	<u>1. Decoder Replacements Proposal</u> 2. Replacement of Seasonal Annuals Proposal	

3. Tree Stump Removal Proposal	iaaa			
 Agreement for Aquatic Maintenance Servi Carambola Bullnose Revamp Proposal 	ices			
6. Chair's Acceptance of the FY 2024 Financial Audit				
7. Legacy Blvd Mainline Break Proposal				
B. FPL LED Lighting Agreement				
9. Guard Shack Enhancements Proposal 10. Consideration of Engagement Letter for	FY 2025 Auditing Services			
11. Irrigation Maintenance and Decoder Inst				
<i>I</i> r. Williams presented the items for ratification here were any questions.	to the Board of Supervisors and asked			
nere were any questions.				
he Board of Supervisors requested Druse's billi	ing info be updated.			
On a Motion by Mr. Walter, seconded by Mr. S Supervisors ratified all the agenda items unde Community Development District.				
Mr. Mendes presented the resolution to Board questions. There were none.	of Supervisors and asked if they had an			
· · · · ·	Smallegan, with all in favor, the Board of			
questions. There were none. On a Motion by Mr. Walter, seconded by Mr. S Supervisors adopted Resolution 2025-04, (na	Smallegan, with all in favor, the Board of me), in substantial form, for Heritage Isle			
uestions. There were none. On a Motion by Mr. Walter, seconded by Mr. S Supervisors adopted Resolution 2025-04, (na at Viera Community Development District. Is. LaBrecque commented about a potential et	Smallegan, with all in favor, the Board of me), in substantial form, for Heritage Isle			
questions. There were none. On a Motion by Mr. Walter, seconded by Mr. S Supervisors adopted Resolution 2025-04, (na at Viera Community Development District. Ms. LaBrecque commented about a potential en Mr. McGee commented about potential sunshir	Smallegan, with all in favor, the Board of me), in substantial form, for Heritage Isle			
Questions. There were none. On a Motion by Mr. Walter, seconded by Mr. S Supervisors adopted Resolution 2025-04, (na at Viera Community Development District. Ms. LaBrecque commented about a potential en Mr. McGee commented about potential sunshir	Smallegan, with all in favor, the Board of ime), in substantial form, for Heritage Isle email opportunity. ne violations. Public Hearing on Distric Policies			
Questions. There were none. On a Motion by Mr. Walter, seconded by Mr. S Supervisors adopted Resolution 2025-04, (nata trian community Development District. Ms. LaBrecque commented about a potential end Mr. McGee commented about potential sunshimetric EIGHTH ORDER OF BUSINESS 1. Consideration of Resolution 2025-02, A	Smallegan, with all in favor, the Board of ime), in substantial form, for Heritage Isle email opportunity. ne violations. Public Hearing on Distric Policies Adopting Sidewalk Vehicle Policies			
Questions. There were none. On a Motion by Mr. Walter, seconded by Mr. S Supervisors adopted Resolution 2025-04, (nail at Viera Community Development District. Ms. LaBrecque commented about a potential er Mr. McGee commented about potential sunshime EIGHTH ORDER OF BUSINESS 1. Consideration of Resolution 2025-02, A Mr. Williams commented about the rule revisions	Smallegan, with all in favor, the Board of ime), in substantial form, for Heritage Isle email opportunity. ne violations. Public Hearing on Distric Policies Adopting Sidewalk Vehicle Policies s.			
questions. There were none. On a Motion by Mr. Walter, seconded by Mr. S Supervisors adopted Resolution 2025-04, (nat at Viera Community Development District. Ms. LaBrecque commented about a potential en Mr. McGee commented about potential sunshir EIGHTH ORDER OF BUSINESS	Smallegan, with all in favor, the Board of ime), in substantial form, for Heritage Isle email opportunity. ne violations. Public Hearing on Distric Policies Adopting Sidewalk Vehicle Policies s. ding health needs to be considered.			

HERITAGE ISLE AT VIERA COMMUNITY DEVELOPMENT DISTRICT May 20, 2025 Minutes of Meeting Page 6

On a Motion by Ms. LaBrecque, seconded by Mr. Walter, with all in favor, the Boa Supervisors opened the public hearing, for Heritage Isle at Viera Community Development District.	
Development District.	ard of
Mr. Williams reviewed the public hearing to the audience.	
On a Motion by Ms. LaBrecque, seconded by Mr. Williams, with all in favor, the B of Supervisors opened the public comments, for Heritage Isle at Viera Community Development District.	
A member of the audience spoke regarding education efforts to community.	
District Counsel commented staying on topic for the public hearing.	
On a Motion by Mr. Walter, seconded by Ms. LaBrecque, with all in favor, the Boa Supervisors closed the public comments, for Heritage Isle at Viera Community Development District.	ard of
Mr. Williams commented regarding wording and the rule revision.	
On a Motion by Mr. Williams, seconded by Mr. Walter, with all in favor, the Board Supervisors adopted Resolution 2025-02, Adopting Sidewalk Vehicle Policies, in substantial form, for Heritage Isle at Viera Community Development District.	of
Cabetaniaa ferrigier fieldage fele at field een inding Betelepinent Biethea	
NINTH ORDER OF BUSINESS 2025-03, Approving the 2025/2026 Proposed Bud	e FY get &
NINTH ORDER OF BUSINESS Consideration of Reso 2025-03, Approving the 2025/2026 Proposed Bud Setting Mr. Williams reviewed the budget in detail with the Board of Supervisors and asked	P FY get &
NINTH ORDER OF BUSINESS Consideration of Reso 2025-03, Approving the 2025/2026 Proposed Bud Setting Mr. Williams reviewed the budget in detail with the Board of Supervisors and asked were any questions.	PFY get &
NINTH ORDER OF BUSINESS Consideration of Reso 2025-03, Approving the 2025/2026 Proposed Bud Setting Mr. Williams reviewed the budget in detail with the Board of Supervisors and asked were any questions. Mr. Walter spoke regarding extensive budget preparation and review of active contractions.	PFY get &
NINTH ORDER OF BUSINESS Consideration of Resc 2025-03, Approving the 2025/2026 Proposed Bud Setting Mr. Williams reviewed the budget in detail with the Board of Supervisors and asked were any questions. Mr. Walter spoke regarding extensive budget preparation and review of active contra Mr. Walter presented photos of the sidewalk sealant.	PFY get &
NINTH ORDER OF BUSINESS Consideration of Resc 2025-03, Approving the 2025/2026 Proposed Bud Setting Mr. Williams reviewed the budget in detail with the Board of Supervisors and asked were any questions. Mr. Walter spoke regarding extensive budget preparation and review of active contra Mr. Walter presented photos of the sidewalk sealant. Mr. Smallegan spoke about prior reviews of searching for sealers.	PFY get &

IVIs. Labre	ecque inquired about the different cost per lot.
Mr. McGe	ee responded to the inquiry.
Mr. Mend	es commented about an operational audit being completed.
Discussio operation	on ensued amongst the Board of Supervisors and District Staff regarding al audits.
The Boar	d of Supervisors requested to table the audits until further notice.
The Board	d of Supervisors discussed tree planting services.
Mr. Mend he comm	les stated that he will work with Juniper and Supervisor Walter for adding trees to nunity.
Mr. Willia years bud	ms made some closing comments highlighting a successful preparation for this dget.
	of Supervisors adopted Resolution 2025-03, Approving the FY 2025/2026
· · ·	Budget & Setting, for Heritage Isle at Viera Community Development District. DRDER OF BUSINESS Supervisor Requests and Audience Comments
TENTH O	ORDER OF BUSINESS Supervisor Requests and Audience Comments er of the audience stated that he will assist Supervisor Walter with a memo to go out
TENTH O A membe to the con	ORDER OF BUSINESS Supervisor Requests and Audience Comments er of the audience stated that he will assist Supervisor Walter with a memo to go out
TENTH O A membe to the con ELEVEN ⁻ On a M with all	ORDER OF BUSINESS Supervisor Requests and Audience Comments er of the audience stated that he will assist Supervisor Walter with a memo to go out nmunity.
TENTH O A membe to the con ELEVEN ⁻ On a M with all	ORDER OF BUSINESS Supervisor Requests and Audience Comments Audience Comments and er of the audience stated that he will assist Supervisor Walter with a memo to go out nmunity. TH ORDER OF BUSINESS Adjournment TH ORDER OF BUSINESS Adjournment Motion by Mr. Smallegan, seconded by Ms. LaBrecque, the Board of Supervisors, in favor, adjourned the meeting at 2:49 p.m., for Heritage Isle at Viera
TENTH O A membe to the con ELEVEN ⁻ On a M with all	ORDER OF BUSINESS Supervisor Requests and Audience Comments Audience Comments and er of the audience stated that he will assist Supervisor Walter with a memo to go our nmunity. TH ORDER OF BUSINESS Adjournment TH ORDER OF BUSINESS Adjournment Motion by Mr. Smallegan, seconded by Ms. LaBrecque, the Board of Supervisors, in favor, adjourned the meeting at 2:49 p.m., for Heritage Isle at Viera
TENTH O A membe to the con ELEVEN ⁻ On a M with all	ORDER OF BUSINESS Supervisor Requests and Audience Comments Audience Comments and er of the audience stated that he will assist Supervisor Walter with a memo to go ou nmunity. TH ORDER OF BUSINESS Adjournment TH ORDER OF BUSINESS Adjournment Motion by Mr. Smallegan, seconded by Ms. LaBrecque, the Board of Supervisors, in favor, adjourned the meeting at 2:49 p.m., for Heritage Isle at Viera
TENTH O A membe to the con ELEVEN ⁻ On a M with all	ORDER OF BUSINESS Supervisor Requests and Audience Comments er of the audience stated that he will assist Supervisor Walter with a memo to go ou nmunity. TH ORDER OF BUSINESS Adjournment Motion by Mr. Smallegan, seconded by Ms. LaBrecque, the Board of Supervisors, in favor, adjourned the meeting at 2:49 p.m., for Heritage Isle at Viera unity Development District.
TENTH O A membe to the con ELEVEN ⁻ On a M with all	ORDER OF BUSINESS Supervisor Requests and Audience Comments er of the audience stated that he will assist Supervisor Walter with a memo to go ou nmunity. TH ORDER OF BUSINESS Adjournment Motion by Mr. Smallegan, seconded by Ms. LaBrecque, the Board of Supervisors, in favor, adjourned the meeting at 2:49 p.m., for Heritage Isle at Viera unity Development District.
TENTH O A membe to the con ELEVEN ⁻ On a M with all	ORDER OF BUSINESS Supervisor Requests and Audience Comments er of the audience stated that he will assist Supervisor Walter with a memo to go out nmunity. TH ORDER OF BUSINESS Adjournment Motion by Mr. Smallegan, seconded by Ms. LaBrecque, the Board of Supervisors, in favor, adjourned the meeting at 2:49 p.m., for Heritage Isle at Viera unity Development District.

282		
283		
284		
285		
286		
287		
288		
289		
290		
291		
292		
293		
294		
295		
296	Secretary/Assistant Secretary	Chairman/Vice Chairman
297 298		
299		
300		
301		
302		
303		
304		
305		
306		
307		~
308		
309		
310		
311		
312		
313		
314		
315		
316		
317		
318		
319		
320		
321		
321		

323		
324		
325	"Exhibit A"	
326	Resident Email	

From: Paul Greenis <<u>ppgreenis@gmail.com</u>> Date: Tuesday, May 20, 2025 at 8:54 AM To: Brian Mendes <<u>BMendes@rizzetta.com</u>> Cc: Ken Walter <<u>kwalter38@cfl.rr.com</u>>, Jr. E. J. Jay Williams <<u>jay4heritageisle@gmail.com</u>>, Jo LaBrecque <<u>JoAnneLaB@gmail.com</u>> Subject: Re: [EXTERNAL]Fwd: CDD Resolution 2025-02

Oh, an should the CDD Board elect to pass resolution 2025-02 as currently proposed, with a further reality check, I believe our local TV stations and Newspapers might be interested in knowing that children, particularly a 6 yr old, will have to use her manual push scooter in the unsafe bike lanes on Legacy Blvd.

What do I mean by unsafe... well there are no bike lanes around the circle by clubhouse, so one would have to use their scooter or bike "in the narrow street" in order to navigate around the circle. And the HIDA Roads and Gates Committee has recommended adding additional stop signs along Legacy Blvd...and why...because so many vehicles, and yes residents too, speed down Legacy. So, now the CDD, via resolution 2025-02, wants children and other's, to use the INCOMPLETE and UNSAFE bike lanes verses the safe sidewalk.

Since we're part of the Viera community, has the CVCA review this proposed resolution as their rules tend to take precedence?

Gee, I wonder how all the golf carts, bicycles, scooters, mobility scooters, joggers, walkers can safely travel along the sidewalks on Pineda Blvd all the way from Wickham road, starting near Heritage Isle all the way to A1A??

Please reconsider amending resolution 2025-02 to simply say that "Caution, Pedestrians Have The Right of Way, and all others must safely yield to them" or something to that effect. And I do think restricting golf carts from sidewalks is an appropriate action.

Please read my email into the CDD records.

Regards, Paul Greenis 3150 Le Conte St.

327		
328		
327 328 329		
330 331		
331		

TAB 7

HERITAGE ISLE AT VIERA COMMUNITY DEVELOPMENT DISTRICT

District Office · Orlando, FL 32819

MAILING ADDRESS · 3434 COLWELL AVE, SUITE 200 · TAMPA, FLORIDA 33614 WWW.HERITAGEISLEATVIERACDD.ORG

Operation and Maintenance Expenditures May 2025 Presented For Board Approval

Attached please find the check register listing the Operation and Maintenance expenditures paid from May 1, 2025 through May 31, 2025. This does not include expenditures previously approved by the Board.

The total items being presented: **\$59,737.77**

Approval of Expenditures:

_____ Chairperson

_____ Vice Chairperson

_____ Assistant Secretary

Heritage Isle at Viera Community Development District

Paid Operation & Maintenance Expenditures

May 1, 2025 Through May 31, 2025

Vendor Name	Check #	Invoice Number	Invoice Description	Invoice Amount
Doggie Doo Doo Disposal Services	300034	19407	Monthly Service 05/25	\$512.00
Druse Landscaping & Tree Service	300039	8821	Tree Services 05/25	\$825.00
Florida Power & Light Company	20250528-1	Monthly Summary 04/25 ACH	Summary Electric Services 04/25	\$6,357.19
Gannett Florida LocaliQ	300040	0007094136	Legal Advertising 04/25	\$423.58
Juniper Landscaping of Florida, LLC	300038	328479	Irrigation Repair - Replacement of Controller #21 04/25	\$10,014.45
Juniper Landscaping of Florida, LLC	300042	332662	Landscape Maintenance 05/25	\$26,772.00
Kutak Rock, LLP	300037	3554954	Legal Services 02/25	\$367.50
Rizzetta & Company, Inc.	300035	INV0000098904	District Management Fees 05/25	\$7,198.34
TIGRIS Aquatic Services, LLC	300036	3827295	Aquatic Service 04/25	\$3,011.58
U.S. Bank	300041	7725409	Trustee Fees S2017 04/01/25 - 03/31/25	<u>\$4,256.13</u>

Report Total

\$59,737.77

HERITAGE ISLE AT VIERA COMMUNITY DEVELOPMENT DISTRICT

District Office · Orlando, FL 32819

MAILING ADDRESS · 3434 COLWELL AVE, SUITE 200 · TAMPA, FLORIDA 33614 WWW.HERITAGEISLEATVIERACDD.ORG

Operation and Maintenance Expenditures June 2025 Presented For Board Approval

Attached please find the check register listing the Operation and Maintenance expenditures paid from June 1, 2025 through June 30, 2025. This does not include expenditures previously approved by the Board.

The total items being presented: **\$107,139.37**

Approval of Expenditures:

_____ Chairperson

_____ Vice Chairperson

_____ Assistant Secretary

Heritage Isle at Viera Community Development District

Paid Operation & Maintenance Expenditures

June 1, 2025 Through June 30, 2025

Vendor Name	Check #	Invoice Number	Invoice Description	Invoice Amount
B S E Consultants Inc.	300051	21221	Engineering Services 05/25	\$500.00
Bob Goldstein	300053	BG052025	Board of Supervisors Meeting 05/20/25	\$200.00
Doggie Doo Doo Disposal Services	300043	19615	Monthly Service 06/25	\$512.00
Druse Landscaping & Tree Service	300056	8837	Plants, Mulch and Landscaping Serices 06/25	\$960.00
Emmett J Williams, Jr	300046	EW052025	Board of Supervisors Meeting 05/20/25	\$200.00
Florida Power & Light Company	20250624-1	FPL Monthly Summary 05/25 ACH	Summary Electric Services 05/25	\$7,545.80
Fountain Kings, Inc.	300052	INV-0699	Quarterly Fountain Maintenance 05/25	\$275.00
Gannett Florida LocaliQ	300057	0007039255	Legal Advertising 03/25	\$165.17
Gannett Florida LocaliQ	300057	0007145799	Legal Advertising 05/25	\$161.84
Hoover Pumping Systems Corp.	300055	187167	A/C Service Call 04/25	\$2,045.68
HP Home Maintenance Solutions, LLC	300058	428	Dog station relocated 06/25	\$150.00
HP Home Maintenance Solutions, LLC	300058	429	storage of signs 06/25	\$240.00
JoAnne M. LaBrecque	300047	JL052025	Board of Supervisors Meeting 05/20/25	\$200.00

Heritage Isle at Viera Community Development District

Paid Operation & Maintenance Expenditures

June 1, 2025 Through June 30, 2025

Vendor Name	Check #	Invoice Number	Invoice Description	Invoice Amount
Jon Smallegan	300048	JS052025	Board of Supervisors Meeting 05/20/25	\$200.00
Juniper Landscaping of Florida, LLC	300044	333078	Bed Prep - Plant, Sod, Debris Removal, Dwarf Ixora and Grass	\$1,676.70
Juniper Landscaping of Florida, LLC	300044	333079	Bed Prep - Plant, Sod, Debris Removal, Dwarf Ixora, Enhancement	\$1,837.70
Juniper Landscaping of Florida, LLC	300044	333080	Seasonal Annuals Spring and Soil 05/25	\$5,234.56
Kenneth F. Walter	300049	KW052025	Board of Supervisors Meeting 05/20/25	\$200.00
Precision Sidewalk Safety Corp.	300054	b-2750	Sidewalk Repairs 05/25 - Remaining Balance	\$56,876.00
Precision Sidewalk Safety Corp.	300054	b-2750 A	Sidewalk Repairs 05/25- Desposit	\$17,749.00
Rizzetta & Company, Inc.	300045	INV0000099681	District Management Fees 06/25	\$7,198.34
TIGRIS Aquatic Services, LLC	300050	3827296	Aquatic Service 05/25	<u>\$3,011.58</u>

Report Total

\$107,139.37

TAB 8

ESTIMATE

Druse Landscaping & Tree Service LLC 1557 Cooling St Melbourne, FL 32935 drusemlbm@aol.com +1 (321) 446-5578

C/O

Bill to Heritages Isles CDD 6972 Lake Gloria BLVD. Orlando, FL 32955 United States Ship to Heritages Isles 6972 Lake Gloria BLVD. Orlando, FL 32955 United States

Estimate details

Estimate no.: 3858 Estimate date: 05/07/2025 Job Site: Savoy

# [Date	Product or service	Description	Qty	Rate	Amount
1.		Landscaping Services	Labor for removal and grading.	30	\$50.00	\$1,500.00
2.		Plants	3 gallon Ixoras Red.	6	\$18.00	\$108.00
3.		Brevard County Landfill Disposal Fee	Green Waste Fee.	6	\$50.00	\$300.00
4.		Sod	Flortam Sod per pallet installed.	4	\$450.00	\$1,800.00

Total

\$3,708.00

Accepted date

Accepted by

w



May 15, 2025 Heritage Isle at Viera CDD - Maintenance

Contract No. - 341889

Replacement of timer #6 located in phase 2 the one that has damage due to ant infestation

ITEM	QTY	UNIT PRICE	TOTAL PRICE
Irrigation Tech Labor	5.00	\$75.00	\$375.00
Hunter ACC2 Decoder 75 Station with Plastic Pedestal	1.00	\$8,560.58	\$8,560.58
Hunter ACC2 Decoder Expansion Module 75 Station	1.00	\$1,228.87	\$1,228.87
			\$10,164.45

WORK ORDER SUMMARY

SERVICES	SALES TAX	TOTAL PRICE
Control Components	\$0.00	\$10,164.45
	\$0.00	\$10,164.45
	Sale	\$10,164.45
	Sales Tax	\$0.00
	Total	\$10,164.45

Ву		By Engles
	CHRIS WADE	
Date	5/15/2025	Date 5/15/25
	Juniper Landscaping of Florida LLC	Heritage Isle at Viera CDD - Maintenance
	Juniper Landscaping of F	lorida LLC • 4415 Metro Parkway Suite 300 • Fort Page 1/1 Myers, FL 33916



Proposal

Proposal No.:	342288
Proposed Date:	05/19/25

PROPERTY:	FOR:
Heritage Isle at Viera CDD - Maintenance 3434 Colwell ave, Suite #200 Tampa FL 33614	Park 5 Berm

Park 5 Berm

- Preparation of area for plants and mulch without disturbing the Gopher Tortoise borrow ٠
- Installation of 15-3g trinnette •
- Installation of 12 bags of coco brown mulch •

ITEM	QTY	UOM	TOTAL
Park 5 Berm			
Site Prep			\$120.00
Bed Prep - Plant, Sod, Debris Removal	2.00	HR	
Landscape Material			\$547.19
Enhancement Labor	2.00	HR	
Trinette Arboricola, 03 gallon - 03G	15.00	03g	
Cocobrown Mulch, 03CF bag - 03CF	12.00	03CF	
		Total:	\$667.19

Guarantee: Any alteration from these specs involving additional costs will be executed only upon written order and will become an extra charge over and above estimate.

Standard Warranty: Juniper agrees to warranty irrigation, drainage and lighting for 1 year, trees and palms for 6 months, shrubs and ground cover for 3 months, and sod for 30 days. This warranty is subject to and specifically limited by the following:

Warranty is not valid on relocated material, annuals and any existing irrigation, drainage and lighting systems. Warranty in not valid on new plant material or sod installed without automatic irrigation. Warranty does not cover damage from pests or disease encountered on site, act of God, or damaged caused by others. Failure of water or power source not caused by Juniper will void warranty. The above identified warranty periods commence upon the date of completion of all items included in this proposal. Standard Warranty does not modify or supersede any previously written agreement. Juniper is not responsible for damage to non-located underground.

Residential Agreement: A deposit or payment in full will be required before any work will begin. Any and all balance will be due upon job completion in full, unless otherwise noted in writing. All work will be performed in a workman like manner in accordance to said proposal. Any additional work added to original proposal will require written approval, may require additional deposits and will be due on completion with any remaining balances owed.

DUE TO THE NATURE OF MATERIAL COST VOLATILITY, WE ARE CURRENTLY HOLDING PRICING FOR THIRTY (30) DAYS FROM PROPOSAL DATE

Brian Mendes

05/19/25

Signature (Owner/Property Manager) Brian Mendes Printed Name (Owner/Property Manager)

Signature - Representative

Date

Date



May 19, 2025

Contract No. - 342547

Heritage Isle at Viera CDD - Maintenance

Valve replacement at the park in phase 7 behind 5988 Van Ness and a broken pipe in the same location

ITEM	QTY	UNIT PRICE	TOTAL PRICE
Irrigation Tech Labor	1.00	\$75.00	\$75.00
NDS Pro-Span PVC Expansion Repair Coupling 2-1/2 in. Socket x Spigot SLIP FIX	1.00	\$106.94	\$106.94
Sch 40 PVC Coupling 2-1/2 in. Socket	1.00	\$6.82	\$6.82
Hunter Globe Valve ICV Glass Filled Nylon 2 in. w/ Flow Control and Filter Sentry FIPT x FIPT	1.00	\$450.00	\$450.00
3M DBR-Y6 Direct Bury Splice Kit DBR/Y-6 (Bulk) 600V	2.00	\$3.80	\$7.60
			\$646.36

WORK ORDER SUMMARY

SERVICES	SALES TAX	TOTAL PRICE
Lateral Components	\$0.00	\$188.76
Control Components	\$0.00	\$457.60
	\$0.00	\$646.36

Total	\$646.36
Sales Tax	\$0.00
Sale	\$646.36

Ву		Ву			
	CHRIS WADE				
Date	5/19/2025	Date			
	Juniper Landscaping of Florida LLC	-	Heritage Isle at Vie Maintenance		_
	Juniper Landscaping of Fl	orida LLC • 4415 Metro Park Myers, FL 33916	way Suite 300 • Fort	Page	1/1



Proposal

Proposal No.:	342293
Proposed Date:	05/19/25

PROPERTY:	FOR:
Heritage Isle at Viera CDD - Maintenance	Funston Berm
Brian Mendez	
6800 Legacy Blvd	
Melbourne, FL 32940	

Funston Berm Revamp

- Removal of Wax Myrtle that is over grown for the area
- Clean up of dead/dying Fakahatchee Grass along the bottom border of the planting bed
- Installation of 35-3g Dwarf Ixora

ITEM	QTY	UOM	TOTAL
(TYPE IN LOCATION AND QUICK DESCRIPTION)			
Site Prep			\$600.00
Bed Prep - Plant, Sod, Debris Removal	10.00	HR	
Landscape Material			\$904.62
Enhancement Labor	4.00	HR	
Dwarf Ixora, 03 gallon - 03G	35.00	03g	
		Total:	\$1,504.62

Guarantee: Any alteration from these specs involving additional costs will be executed only upon written order and will become an extra charge over and above estimate.

Standard Warranty: Juniper agrees to warranty irrigation, drainage and lighting for 1 year, trees and palms for 6 months, shrubs and ground cover for 3 months, and sod for 30 days. This warranty is subject to and specifically limited by the following:

Warranty is not valid on relocated material, annuals and any existing irrigation, drainage and lighting systems. Warranty in not valid on new plant material or sod installed without automatic irrigation. Warranty does not cover damage from pests or disease encountered on site, act of God, or damaged caused by others. Failure of water or power source not caused by Juniper will void warranty. The above identified warranty periods commence upon the date of completion of all items included in this proposal. Standard Warranty does not modify or supersede any previously written agreement. Juniper is not responsible for damage to non-located underground.

Residential Agreement: A deposit or payment in full will be required before any work will begin. Any and all balance will be due upon job completion in full, unless otherwise noted in writing. All work will be performed in a workman like manner in accordance to said proposal. Any additional work added to original proposal will require written approval, may require additional deposits and will be due on completion with any remaining balances owed.

DUE TO THE NATURE OF MATERIAL COST VOLATILITY, WE ARE CURRENTLY HOLDING PRICING FOR THIRTY (30) DAYS FROM PROPOSAL DATE

Brian Mendes 05/27/25 Signature (Owner/Property Manager) Date Brian Mendes Printed Name (Owner/Property Manager) **Signature - Representative** Date



May 23, 2025 Heritage Isle at Viera CDD - Maintenance Contract No. - 343425

Heritage Isle at Viera CDD - Maintenance

Proposal to replace two decoder modules that have burnt out one is in phase one clock 9 and the other is in phase two clock 5

ITEM	QTY	UNIT PRICE	TOTAL PRICE
Irrigation Tech Labor	2.00	\$75.00	\$150.00
Hunter ADM-99 Decoder Output Module for ACC Wall Mount Controller	1.00	\$1,698.58	\$1,698.58
Hunter ACC2 Decoder Expansion Module 75 Station	1.00	\$1,228.87	\$1,228.87
			\$3,077.45

WORK ORDER SUMMARY

SERVICES	SALES TAX	TOTAL PRICE
Control Components	\$0.00	\$3,077.45
	\$0.00	\$3,077.45
	Sale	\$3,077.45
	Sales Tax	\$0.00
	Total	\$3,077.45

Ву		Ву	Brian Mende	? \$	
	CHRIS WADE				
Date	5/23/2025	Date	05/27/25		
	Juniper Landscaping of Florida LLC		Heritage Isle at Vie Maintenanc		
	Juniper Landscaping of Flo	rida LLC • 4415 Metro Park Myers, FL 33916	way Suite 300 • Fort	Page	1/1



Proposal

Proposal No.:	347541
Proposed Date:	06/16/25

PROPERTY:	FOR:
Heritage Isle at Viera CDD - Maintenance	pressurized line repair behind 2903 Galindo
Brian Mendez	
6800 Legacy Blvd	
Melbourne, FL 32940	

Pressurized line brake behind 2903 Galindo repair

ITEM	QTY	UOM	TOTAL
Irrigation Renovation			
Lateral Components			\$716.62
Irrigation Tech Labor	6.00	HR	
NDS Pro-Span PVC Expansion Repair Coupling 3 in. Socket x Spigot SLIP FIX	1.00	EA	
3" Misc Fittings	2.00	EA	
2" - 2.5" Misc Fittings	4.00	EA	
PVC Pipe 2 in. x 20 ft. Schedule 40 Bell End (Sold per ft.)	5.00	FT	
		Total:	\$716.62

Guarantee: Any alteration from these specs involving additional costs will be executed only upon written order and will become an extra charge over and above estimate.

Standard Warranty: Juniper agrees to warranty irrigation, drainage and lighting for 1 year, trees and palms for 6 months, shrubs and ground cover for 3 months, and sod for 30 days. This warranty is subject to and specifically limited by the following:

Warranty is not valid on relocated material, annuals and any existing irrigation, drainage and lighting systems. Warranty in not valid on new plant material or sod installed without automatic irrigation. Warranty does not cover damage from pests or disease encountered on site, act of God, or damaged caused by others. Failure of water or power source not caused by Juniper will void warranty. The above identified warranty periods commence upon the date of completion of all items included in this proposal. Standard Warranty does not modify or supersede any previously written agreement. Juniper is not responsible for damage to non-located underground.

Residential Agreement: A deposit or payment in full will be required before any work will begin. Any and all balance will be due upon job completion in full, unless otherwise noted in writing. All work will be performed in a workman like manner in accordance to said proposal. Any additional work added to original proposal will require written approval, may require additional deposits and will be due on completion with any remaining balances owed.

DUE TO THE NATURE OF MATERIAL COST VOLATILITY, WE ARE CURRENTLY HOLDING PRICING FOR THIRTY (30) DAYS FROM PROPOSAL DATE

Signature (Owner/Property Manager)

Date

Printed Name (Owner/Property Manager)

Signature - Representative

Date



June 30, 2025

Contract No. - 349818

Heritage Isle at Viera CDD - Maintenance

Replacement of 2 valves on legacy Blvd. south one near Savoy and the other near Galindo

ITEM	QTY	UNIT PRICE	TOTAL PRICE
Hunter Globe Valve ICV Glass Filled Nylon 2 in. w/ Flow Control and Filter Sentry FIPT x FIPT	2.00	\$450.00	\$900.00
			\$900.00

WORK ORDER SUMMARY

SERVICES	SALES TAX	TOTAL PRICE
Control Components	\$0.00	\$900.00
	\$0.00	\$900.00
	Sale	\$900.00
	Sales Tax	\$0.00

Total	\$900.00

Ву		Ву			
	CHRIS WADE	-			
Date	6/30/2025	Date			
	Juniper Landscaping of Florida LLC	-	Heritage Isle at Vie Maintenanc		
	Juniper Landscaping of Florida LLC • 4415 Metro Parkway Suite 300 • Fort			Page	1/1

Myers, FL 33916

ESTIMATE

Prepared For

Heritage Isle CDD 3434 Colwell Suite 200 Tampa, Florida 33614 (407) 472-2741

HP Home Maintenance Solutions LLC		Estimate #	165
2812 Shelburne Way Saint Cloud , Florida 34772 Phone: (407) 412-3731 Email: hphomemaintenancesolutions@gmail.com Web: Www.hphomemaintenancesolutions.com		Date	06/27/2025
Description	Rate	Quantity	Total

Signs reinstalling,grinding, concrete repair	\$1,750.00	1	\$1,750.00
Removal and reinstalling 14 signs with concrete. 3 concrete grinding and storm concrete repair.			pair.

 Total	\$1,750.00		
Subtotal	\$1,750.00		

Heritage Isle CDD



