## Vasari Community Development District

## JANUARY 12, 2021 MEETING

## AGENDA PACKAGE

The meeting will be held at: Vasari Country Club, 11250 Via De Vasari Drive, Bonita Springs, Florida



### Vasari Community Development District

#### Inframark, Infrastructure Management Services

210 North University Drive, Suite 702 • Coral Springs, Florida 33071 Telephone: (954) 603-0033 • Fax: (954) 345-1292

January 5, 2021

Board of Supervisors Vasari Community Development District

Dear Board Members:

The regular meeting of the Board of Supervisors of the Vasari Community Development District will be held **Tuesday**, **January 12**, **2021 at 9:00 a.m.** at the Vasari Country Club, 11250 Via De Vasari Drive, Bonita Springs, Florida. Following is the advance agenda for the meeting:

- 1. Roll Call
- 2. Approval of Agenda
- 3. Audience Comments on Agenda Items
- 4. Fountain & Aeration Firm Interviews Superior Waterways & Mettauer Environmental [Page 5]
- 5. Staff Reports
  - A. Manager's Report [Page 12]
    - i. Field Manager's Report
    - ii. Approval of the Minutes of the December 8, 2020 Meeting
    - iii. Acceptance of the November 2020 Financial Statements and Check Register
    - iv. Follow Up Items
      - a. CDD Email Account Update / Archiving Discussion

#### B. Lake & Wetland Management [Page 48]

- i. Inspection Reports
  - a. December 8, 2020
  - b. December 9, 2020
- ii. Proposal Lake Raking
- C. Fountain/Aerators [Page 52]
  - i. Fountain Inspection Reports
  - ii. Aeration Inspection Reports
  - iii.. Fountain & Aeration Log
- D. Attorney's Report
- E. Engineer's Report
  - i. Altessa/Imperial Wall Repair Discussion
- 6. Old Business
  - A. Bulkhead Discussion
  - B. FY2021 Erosion Discussion
- 7. New Business
- 8. Master Association Report
- 9. Supervisors Requests
- **10.** Audience Comments
- 11. Adjournment

January 5, 2021 Vasari CDD Page 2

Any additional supporting material for the items listed above is enclosed or will be distributed at the meeting. The balance of the agenda is routine in nature. If you have any questions, please contact me.

Sincerely,

Justin Faircloth

Justin Faircloth/ms

Manager

cc: Greg Urbancic Terry Cole

# **Fourth Order of Business**



### **Reference Response Sheet**

Todd Legan – sent email 12/29/20 Cedar Hammock Golf and Country Club Naples, FL (239) 825-4599

• "I've worked with several lake management companies over the course of my career. Superior Waterways is by far the best company that I have worked with. Eric always answers his phone or immediately calls me back if he's on the line when I call. He promptly addresses any issues that pertain to algae, fountains, plantings, dye etc. He is extremely knowledgeable with lake management, preserve maintenance and fountains and aerators. His company also has the resources and man power to handle any situation. Eric has always been extremely polite and is always a pleasure to work with. I can type up a letter of recommendation when I get back from vacation. I'm using my phone. I think whoever hires Superior to maintain their lakes will be extremely pleased."

Todd Legan, Cedar Hammock Golf Course Superintendent

Ron Kent – spoke by phone on 12/29/20 Burnt Store Lakes Punta Gorda, FL (909) 938-1822

• Aeration for 11 lakes comprising of 29 compressors and 80+ diffusers, quick on response time, reasonably priced, use their services for 5+ yrs.

Butch McGovern – spoke by phone on 12/29/20 Earth Tech Enterprises (239) 980-2611

• They use them as a subcontractor/partner with Monroe County for 5+ yrs.

John Johnson – spoke by phone on 12/29/20 Trafalgar Woods (239) 340-3216

• They have used their services for about 1 yr. They had issues with their previous fountain/aeration vendor and Superior came in and showed them the issues with the previous work. As a result of the good performance they began using them for lake maintenance as well.

# VASARI HOMEOWNERS ASSOCIATION, INC. AERATION MANAGEMENT SERVICES

#### **REFERENCES**

Please provide two references for your fountain and aeration services.

#### Reference 1

Community	Breckenridge Golf and Tennis Club
Community Address	20091 Wimbleton Ct, Estero FL, 33928
Contact Name	Steadmon Allen
Contact Phone No.	239-850-9262
Contact E-mail Address	breckclub@comcast.net
Type of Contract	Reoccuring Annual
Lake Acres	16 lakes totaling 13.5 Ac
Number of Units	
Scope of Work	

#### Reference 2

Community	Quail Run @ Forest Lakes Golf Club
Community Address	16161 Tamiami Trail, Naples, FL 34114
Contact Name	Dan Schumacher
Contact Phone No.	239-227-4011
Contact E-mail Address	danschumacher@colliergov.net
Type of Contract	Reoccurring Annual Contract
Lake Acres	Lake 14
Unit	Fountain motor and pump replacement
Scope of Work	

From: Faircloth, Justin
To: Slaughter, Mona

Subject: VCDD-1/12/21 Agenda Packet item - Mettauer Environmental Reference response

**Date:** Tuesday, January 5, 2021 10:38:28 AM

Attachments: <u>image001.png</u>



239.785.0675 | www.inframarkims.com

#### SUPERVISORS, PLEASE DO NOT REPLY TO ALL AS THIS COULD BE A VIOLATION OF THE FLORIDA SUNSHINE PROVISIONS.

CONFIDENTIALITY NOTICE: The information in this email is intended for the sole use of the recipient(s) and may be confidential and subject to protection under the law. If you are not the intended recipient, you are hereby notified that any distribution or copying of this email is strictly prohibited. If you have received this message in error, please contact the sender immediately and delete your copy from your computer.

From: SchumacherDan <Dan.Schumacher@colliercountyfl.gov>

Sent: Tuesday, January 5, 2021 10:18 AM

**To:** Faircloth, Justin < justin.faircloth@inframark.com> **Subject:** RE: Mettauer Environmental Reference Check

Justin,

While this response is not a Collier County Government endorsement, Mettauer Environmental has performed well in Quail Run.

Respectfully,

-Dan Schumacher (239) 252-5775

MSTU Project Manager
Public Transit & Neighborhood Enhancement Division
Public Services Department

**From:** Faircloth, Justin < <u>justin.faircloth@inframark.com</u>>

Sent: Monday, January 4, 2021 10:39 PM

**To:** SchumacherDan <<u>Dan.Schumacher@colliercountyfl.gov</u>>

**Subject:** Mettauer Environmental Reference Check

EXTERNAL EMAIL: This email is from an external source. Confirm this is a trusted sender and use extreme caution when opening attachments or clicking links.

Mr. Schumacher,

Your name was given to me by SonnyDan Backes as a reference to contact about Mettauer Environmental and their performance. I have client that is looking at using them for aeration and fountain maintenance in numerous lakes. Would you please take a moment to tell me your thoughts of Mettauer Environmental and their service they have provided to you in Quail Run? My client's next meeting is 1/12/21 and I would appreciate any response beforehand. Thank you in advance for your assistance.

Happy New Year to you and yours.

Sincerely, Justin

Justin Faircloth | CAM, CDM | District Manager



239.785.0675 | www.inframarkims.com

#### SUPERVISORS, PLEASE DO NOT REPLY TO ALL AS THIS COULD BE A VIOLATION OF THE FLORIDA SUNSHINE PROVISIONS.

CONFIDENTIALITY NOTICE: The information in this email is intended for the sole use of the recipient(s) and may be confidential and subject to protection under the law. If you are not the intended recipient, you are hereby notified that any distribution or copying of this email is strictly prohibited. If you have received this message in error, please contact the sender immediately and delete your copy from your computer.

# **Fifth Order of Business**


# **5A**

# 5Ai.



# Vasari CDD

# 12/29/20 – Field Management Report



www.inframarkims.com

Inspected on: 11/28/2020 and 12/29/2020 by: Tim Hall

## 1. Lake Management

The water levels in the lakes are still elevated for this time of year. Additional lake maintenance information is found below. Except where specifically noted, lakes appeared to be in very good shape and all issues are minor.

a. Algae on Lakes: Noted in Lakes 10, 11, 14, 15, 20, and 21. Most algae noted was contained in littoral plantings.





Lake 11 Lake 14

b. Filamentous Algae: Small patches noted in Lake 11



Lake 11

**c.** Littorals: Littoral plantings are recovering from high water levels, Balsam apple vine noted in littorals and lake bank plantings on the south side of Lake 3 have been treated.





Lake 3 (11/19/2020)

Lake 3 (12/29/2020)

New trees have been planted in littoral areas along Lake 24.



Lake 24

i. Alligator Flag in Lakes: Plants along north side of Lake 18 due for trimming as they continue to brown out.



Lake 18

### d. Weeds:

- i. Alligator Weed in Lakes: No issues observed.
- ii. Brazilian Pepper: No issues observed.
- iii. Cattails in Lakes: No issues observed.
- iv. Climbing Hemp Vine in Lakes: No issues observed.
- v. Chara in Lakes: No issues noted
- vi. Hydrilla in Lakes: No issues observed.
- vii. Illinois Pond Weed in Lakes: No issues observed.

viii. Palms on Lake Banks: Several small palms noted previously have been treated.





Lake 12 Lake 22

ix. Red Ludwigia in Lakes: Noted in Lakes 11, 18, 19, and 21



Lake 18

- x. Sedges in Lakes: No issues observed.
- xi. Spatterdock/Lily Pads in Lakes: Noted in Lakes 7 and 12.





Lake 7 Lake 12

xii. Torpedo Grass in Lakes: Very minor patches observed on Lakes 1, 4, 9, 19, and 21.





Lake 11 Lake 21

e. Trash in Lakes: Styrofoam noted in Lake 14 and a plastic bag noted in Lake 10.





Lake 14 Lake 10

f. Bulkheads: Weeds noted in Lake 2 and Lake 18 bulkheads.





Lake 2 Lake 18

g. Clippings in Lakes: No issues noted.

h. Other issues: Logs or poles were noted in Lakes 18 and 24.





Lake 18 Lake 24

2. Lake Bank Erosion: Site inspection was conducted with the entire CDD Board last month. No new areas of erosion were noted. A couple of the noted areas have had repair work done.

Area of erosion on southwest corner of Lake 10 has been filled in.





11/19/2020 12/29/2020

Erosion from leaking pipe on Lake 17 is being repaired.



Lake 17

Erosion from a past drain box repair on Lake 19 is no worse.



Lake 19

# 3. Storm Drainage System

a. Outfall Structures: No issues observed.





Lake 5 Lake 24

b. Drains: No issues noted.

c. Roadway Catch Basins: Road drain structures by Lake 10 are open and appear to have been recently emptied.





22 inches of space in southwest drain

21 inches to top of debris in northeast drain

- d. Storm Drain: No issues noted.
- e. Catch Basins: No issues observed.
- f. Inter-Connect/Drain Pipes: No issues noted.
- g. Lake Drainage Pipes: Several golf course drainage pipes are currently sticking up above the water line. Pipes noted on Lakes 9, 11, 12, 14, 18, 19, 21, 23, and 24. Some pipes will likely need to remain exposed but could be better anchored once water levels drop further to prevent them floating up when water levels rise again






Lake 14 Lake 19

# 4. Irrigation Water Use as Reported to SFWMD:

Month	НОА	Golf	TOTAL
August 2019	2.675 MG	1.946 MG	4.621 MG
September 2019	7.611 MG	7.283 MG	14.894 MG
October 2019	9.365 MG	5.561 MG	15.926 MG
November 2019	7.944 MG	3.738 MG	11.682 MG
December 2019	7.798 MG	2.964 MG	10.762 MG
January 2020	7.719 MG	5.688 MG	13.407 MG
February 2020	6.733 MG	5.718 MG	12.451 MG
March 2020	9.734 MG	9.581 MG	19.315 MG
April 2020	12.111 MG	9.956 MG	22.067 MG
May 2020	6.612 MG	10.425 MG	17.037 MG
June 2020	5.690 MG	7.064 MG	12.754 MG
July 2020	7.883 MG	7.413 MG	15.296 MG
August 2020	7.445 MG	3.587 MG	11.032 MG
September 2020	6.170 MG	4.642 MG	10.812 MG
October 2020	9.673 MG	3.751 MG	13.424 MG
November 2020	7.015 MG	5.130 MG	12.145 MG

## 5. Lake Elevations



6. Fountains & Aeration: Lake 24 fountains still off until power is re-established for building but all other fountains were working.



\*\*Diffusers in many of the Lakes did not appear to be working. Issues noted in Lake 3 (south center), Lake 4, Lake 5, Lake 6, Lake 7, Lake 8, Lake 9, Lake 11, Lake 12, Lake 13 (northeast and center not working), Lake 18 (east not working), Lake 20, Lake 21, and Lake 23.

Also noted abandoned (?) air lines on Lake 19.



7. Boundary Wall: Fencing along north property line still has several posts not connected to top rail.



Cap still separated from post

Fence screening adjacent to I-75 has fallen. Golf course will be trimming back vegetation but has not happened yet.



Vines and Brazilian pepper noted between boundary wall and I-75 ROW fencing. Vines are starting to take over the landscaping in a few locations to the north.





Pepper also starting to grow over the wall in a couple of locations



Along hole #17

8. Preserves: Preserves still have standing water and appear to be in good shape. Signage around preserves is in pretty bad shape. Should consider repairing/replacing.



9. Fish/Wildlife Observations:

<b>⊠</b> Bass	☐ Bream	Catfish	
<b>Egrets</b>	Herons	Coots	Gallinules
⊠Anhinga	Cormorant	Osprey	Ibis
Woodstork	Otter	Alligators	Snakes
X Turtles	Other: Hoode	d Mergansers	





**Hooded Mergansers** 

Little Blue Heron (white phase)

- 10. Residential Complaints/Concerns: No issues reported.
- 11. Non-CDD Issues: No new issues reported.

# 5Aii.

1						
2	MINUTES OF MEETING					
3	VASARI					
4	COMMUNITY DEVELOPMENT DISTRICT					
5						
6	The regular meeting of the Board of	Supervisors of the Vasari Community Development				
7	District was held Tuesday, December 8, 202	0 at 9:15 a.m. at the Vasari Country Club, located at				
8	11250 Via De Vasari Drive, Bonita Springs,	Florida and via Zoom.				
9 10	Present and constituting a quorum we	ere:				
11						
12	Richard Brant	Chairman				
13	Barry Sands	Vice Chairman				
14	Dennis Lavalle	Assistant Secretary				
15	Jeffrey Shein	Assistant Secretary (via phone)				
16	Richard Kraska	Assistant Secretary (via phone)				
17						
18	Also present were:					
19		D' ( ' ( ) (				
20	Justin Faircloth	District Manager				
21	Tim Hall	Hall & Associates (via phone)				
22	Steve Malvinni	Vasari Country Club L&WM				
23 24	Gonzalo Ayers	L& W IVI				
25	The following is a summary of the	discussions and actions taken at the December 8,				
26	2020 Vasari Community Development Distr					
27	2020 Tusuri Community Development Disti	tet & Bourn of Supervisors Meeting.				
28	FIRST ORDER OF BUSINESS	Roll Call				
29		ent with Mr. Shein and Mr. Kraska via phone.				
		_				
30	<u> </u>	seconded by Mr. Brant, with all in				
31	. —	d Mr. Kraska to participant via phone				
32	was approved.					
33						
34	SECOND ORDER OF BUSINESS	Approval of Agenda				
35	<ul> <li>A packet of documents was handed of</li> </ul>	out to the Board to be added to the agenda:				
36	o Hole Montes 12/7/20 Inspects	ion Report				
37	o FF November inspections					
38	o FF Proposal 2020-12203 – La	ake 5 Compressor Replacement				
39	o FF Proposal 2020-12204 – La	ake 19 Aeration Manifold Repair				
40	o Vasari Country Club request	to cover initial littoral/tree installation for Lake 24				

Proposal from Disaster Law and Consulting (DLC) for FEMA appeal work 41 0 42 On MOTION by Mr. Sands seconded by Mr. Lavalle, with all in 43 favor, the agenda was approved as amended. 44 45 THIRD ORDER OF BUSINESS Audience Comments on Agenda 46 **Items** 47 48 There being none, the next item followed. 49 50 FOURTH ORDER OF BUSINESS **Staff Report** Manager's Report 51 Field Manager's Report 52 Mr. Hall reviewed the Field Manager's Report. 53 Balsam apples, alligator flag and small palms were discussed. Staff will have 54 L&WM spray or pull them. 55 Lake bank erosion was discussed. 56 0 Floating pipes were discussed and will be tracked going forward. 57 0 58 The Board requested the District Engineer provide direction to have the floating 0 pipes in the lakes anchored down when the Board looks at completing erosion 59 repairs to the lake banks in the Spring. 60 It was requested the irrigation issue on Lake 17 be included in next month's 61 0 62 report. Mr. Avers joined the meeting and Mr. Faircloth addressed the hand pulling of balsam 63 apples and alligator flag, and the Thalia trimming. 64 65 The Board considered the request by the Club to cover the initial cost to install littorals and trees for Lake 24 as required by the City of Bonita Springs with it being noted there 66 are concerns about the triploid grass carps' effect on the littorals. 67 68 Mr. Sands MOVED to approve the CDD to cover the cost of 69 \$16,016.25 by L&WM to complete the project with the 70 understanding that staking would be performed at this cost for any 71 tree that needs it and the Club would reimburse the CDD and Mr. 72 Brant seconded the motion. 73 74

The types of trees were addressed with it being noted it is 50 Bald Cypress, 85 Sweet Bay
Magnolias and 50 Red Maples. Mr. Kraska noted he is not in favor of planting any Bald
Cypress.

78

79

80

On VOICE vote with Mr. Sands, Mr. Brant, Mr. Shein and Mr. Lavalle voting aye and Mr. Kraska voting nay, the motion was approved.

81 82

- Mr. Brant addressed the agreements with the Club.
- Discussion followed on the Altessa wall with Mr. Malvinni noting he will take care of the plantings.
- Raking the lakes to remove the algae on the sides was addressed. Mr. Ayers noted it was not algae, it is dying plant material.

88 89

### ii. Approval of the Minutes of the November 18, 2020 Meeting

90 91

Mr. Lavalle MOVD to approve the minutes of the November 18, 2020 meeting and Mr. Brant seconded the motion.

92 93 94

• Line 66 add "Vice" before Chair.

95 96

On VOICE vote, the minutes of the November 18, 2020 meeting were approved as amended.

979899

### iii. Acceptance of the October 2020 Financial Statements and Check Register

100101102

Mr. Sands MOVED to approve the October 2020 financial statements and check register and Mr. Brant seconded the motion.

103104

- Mr. Faircloth reviewed the financial statements noting fund balance is decreasing due to
   non-ad valorem assessment collections not yet being received.
- Reserves and funding the wall repairs were addressed.
- Mr. Faircloth reviewed the Copeland Southern wall repair proposal and the Hole Montes
   report regarding the same. Discussion followed.

110	•	The Board requested staff get Hole Montes and Copeland Southern together to devel	op a
111		scope of work of what need to be repaired for the Imperial Boulevard wall.	
112	•	Mr. Sands addressed a discrepancy in Interest – Investments.	
113			
114		On VOICE vote, with all in favor, the motion was approved.	
115			
116		iv. Follow Up Items	
117	•	Mr. Faircloth reported he had an addendum with SOLitude for the preserve mainten	ance
118		for the Matera area.	
119	•	Mr. Faircloth reviewed the fountain proposals received from Superior Waterways, C	cross
120		Creek, and Mettauer Environmental.	
121	•	The Board requested staff obtain references from Superior Waterways and Mett	auer
122		Environmental and invite both vendors to attend the January meeting for an inter-	view
123		with the Board.	
124			
125		a. FEMA Update	
126	•	The Board reviewed the FEMA denial and the proposal from DLC. The consensus	[3-2]
127		was not to pursue another appeal.	
128	•	Mr. Shein noted he was not paid for the November meeting.	
129			
130		B. Lake & Wetland Management	
131 132		<ul><li>i. Monthly Inspection Reports</li><li>a. November 14, 2020</li></ul>	
133		<ul><li>a. November 14, 2020</li><li>b. November 18, 2020</li></ul>	
134	•	There being no further report, the next item followed.	
		in the country are the first to	
135		C. Fountains/Aerators	
136 137		<ul><li>C. Fountains/Aerators</li><li>i. Fountain Inspection Reports – November</li></ul>	
138		± ±	
139		11 1 Toposai 2020-12203 – Lake 3 Compressor Replacement	
140		11 110posai 2020-12204 – Lake 17 Actation Maintold Repair	
141	_	iii. Fountain & Aeration Log	10
142	•	The consensus of the Board was to hold the proposals submitted by FF for Lakes 5 &	19.
143 144		D. Attorney's Report	
145		i. Easement Update	
145		ii. Facilities Maintenance Agreement Undate	

147 148 149	•	iii. Vasari CDD / Vasari Country Club Master Agreement Update Previously addressed.	Association, Inc Lease
150	•	The Board agreed to hold on the agreements with the Club and	requested Mr. Malvinni
151		work with District Counsel to resolve the issues noted with	the response from the
152		attorney for the Club.	
153 154 155 156	•	E. Engineer's Report i. Wall Inspection Discussion Previously addressed.	
157 158	•	ii. Cassia Drainage Review  Comments from the engineer were received and reviewed with	n the Board noting that
159		water cannot be drained directly into the preserves as requested by	y a homeowner.
160			
161 162 163	FIFT •	TH ORDER OF BUSINESS  A. Bulkhead Discussion  This item postponed.	S
164 165	•	B. FY2021 Erosion Discussion This item postponed.	
166 167		C. November Tour Payment Discussion	
168 169 170 171		On MOTION by Mr. Lavalle seconded by Mr. Sands, Lavalle, Mr. Sands, Mr. Brant, and Mr. Shein voting aye Kraska voting nay, additional payment for the November tour was approved.	and Mr.
172 173	•	Discussion followed on the new email platform.	
174 175 176 177	SIXT	TH ORDER OF BUSINESS  A. Copeland Southern Imperial Wall Repair Proposal This item was tabled.	ss
178	CEVA	VENTUA ODDED OF DUGDUEGG	
179 180 181	SEVI	There being none, the next order of business followed.  Master Asso There being none, the next order of business followed.	ciation Report
182 183	EIGH	HTH ORDER OF BUSINESS  There being none, the next order of business followed.	Requests
184 185	NINT	TH ORDER OF BUSINESS Audience Co	omments

186	There being none, the next order of business followed.			
187 188 189	<b>TENTH ORDER OF BUSINESS</b> The next meeting will be January 12, 2021.	Adjournment		
190	There being no further business,			
191				
400	O MOTIONA NA D			
192	On MOTION by Mr. Brant seconder	ed by Mr. Lavalle, with all in		
192 193	favor, the meeting was adjourned at			
193				
193 194				
193 194 195				

# 5Aiii.

# Vasari Community Development District

**Financial Report** 

November 30, 2020

Prepared by:



## Vasari

## Community Development District

#### **Table of Contents**

FINANG	CIAL STATEMENTS		
	Balance Sheet - All Funds		Page 1
	Statement of Revenues, Expenditures and	Changes in Fund Balances	
	General Fund		Pages 2 - 3
	Debt Service Fund		Page 4
SUPPC	PRTING SCHEDULES		
	Non-Ad Valorem Special Assessments		Page 5
	Cash and Investment Report		Page 6
	Bank Reconciliation		Page 7
	Payment Register by Bank Account		Page 8

# Vasari Community Development District

### **Financial Statements**

(Unaudited)

November 30, 2020

#### **Balance Sheet**

November 30, 2020

ACCOUNT DESCRIPTION	GENERAL FUND		SERIES 2012 DEBT SERVICE FUND		TOTAL	
ASSETS						
Cash - Checking Account	\$	405,661	\$	_	\$	405,661
Due From Other Funds	Ψ	400,001	Ψ	192,262	Ψ	192,262
Investments:				192,202		192,202
Money Market Account		353,657		_		353,657
Reserve Fund		-		70,870		70,870
Revenue Fund		_		97,347		97,347
Deposits		380		91,541		380
Deposits		300		_		300
TOTAL ASSETS	\$	759,698	\$	360,479	\$	1,120,177
<u>LIABILITIES</u>						
Accounts Payable	\$	12,858	\$	-	\$	12,858
Accrued Expenses		1,300		-		1,300
Due To Other Funds		192,262		-		192,262
TOTAL LIABILITIES		206,420		-		206,420
FUND BALANCES						
Nonspendable:						
Deposits		380		-		380
Restricted for:						
Debt Service		-		360,479		360,479
Assigned to:						
Operating Reserves		84,649		-		84,649
Reserves - Bulkheads		43,617		-		43,617
Reserves - Fountains		69,277		=		69,277
Reserves - Irrigation System		127,419		-		127,419
Reserves - Lakes		53,645		-		53,645
Reserves - Perimeter		12,586		-		12,586
Reserves - Stormwater System		31,272		-		31,272
Unassigned:		130,433		-		130,433
TOTAL FUND BALANCES	\$	553,278	\$	360,479	\$	913,757
TOTAL LIABILITIES & FUND BALANCES	\$	759,698	\$	360,479	\$	1,120,177

#### Statement of Revenues, Expenditures and Changes in Fund Balances

For the Period Ending November 30, 2020

ACCOUNT DESCRIPTION	ANNUAL ADOPTED BUDGET	YEAR TO DATE ACTUAL	YTD ACTUAL AS A % OF ADOPTED BUD	NOV-20 ACTUAL
<u>REVENUES</u>				
Interest - Investments	\$ 7,500	\$ 228	3.04%	\$ 112
Interest - Tax Collector	750	· 220	0.00%	·
Special Assmnts- Tax Collector	459,214	125,682	27.37%	125,682
Special Assmnts- Discounts	(18,369)	(5,059)	27.54%	(5,059)
TOTAL REVENUES	449,095	120,851	26.91%	120,735
TOTAL REVENUES	443,030	120,001	20.0170	120,100
<u>EXPENDITURES</u>				
<u>Administration</u>				
P/R-Board of Supervisors	12,000	1,800	15.00%	800
FICA Taxes	918	138	15.03%	61
ProfServ-Arbitrage Rebate	600	-	0.00%	-
ProfServ-Engineering	5,000	-	0.00%	-
ProfServ-Legal Services	12,500	1,745	13.96%	1,583
ProfServ-Mgmt Consulting Serv	61,590	10,265	16.67%	5,133
ProfServ-Property Appraiser	766	766	100.00%	766
ProfServ-Special Assessment	5,264	877	16.66%	439
ProfServ-Web Site Development	894	149	16.67%	75
Auditing Services	5,450	-	0.00%	-
Postage and Freight	1,500	114	7.60%	106
Insurance - General Liability	8,845	8,337	94.26%	-
Printing and Binding	1,100	206	18.73%	206
Legal Advertising	700	301	43.00%	301
Misc-Assessmnt Collection Cost	315	211	66.98%	211
Misc-Contingency	1,000	30	3.00%	_
Misc-Web Hosting	2,500	388	15.52%	388
Office Supplies	1,000	-	0.00%	-
Annual District Filing Fee	175	175	100.00%	_
Total Administration	122,117	25,502	20.88%	10,069
Conservation and Resource Mgmt				
Contracts-Preserve Maintenance	4,500	750	16.67%	375
R&M-Mitigation	600	-	0.00%	-
R&M-Preserves	2,500	-	0.00%	
Total Conservation and Resource Mgmt	7,600	750	9.87%	375
<u>Field</u>				
ProfServ-Field Management	18,360	3,060	16.67%	1,530
R&M-General	2,000	-	0.00%	-
R&M-Renewal and Replacement	1,000	-	0.00%	-
R&M-Walls and Signage	5,000		0.00%	
Total Field	26,360	3,060	11.61%	1,530
	· · · · · · · · · · · · · · · · · · ·	<del></del>	<del></del>	<del></del>

#### Statement of Revenues, Expenditures and Changes in Fund Balances

For the Period Ending November 30, 2020

ACCOUNT DESCRIPTION	ΑI	NNUAL DOPTED UDGET	YEAR TO D		YTD ACTUAL AS A % OF ADOPTED BUD	NOV-20 ACTUAL
<u>Lakes and Ponds</u>						
Contracts-Fountain		12,200	1	,100	9.02%	550
Contracts-Water Mgmt Services		33,644	5	,607	16.67%	2,804
Contracts-Water Quality		4,570	2	2,072	45.34%	2,072
Electricity - Aerator		3,000		292	9.73%	146
Property Insurance		6,908	4	,755	68.83%	-
R&M-Aquascaping		7,500		-	0.00%	-
R&M-Irrigation		8,500	1	,140	13.41%	170
R&M-Lake		32,000		-	0.00%	-
R&M-Stormwater System		5,000		-	0.00%	-
R&M-Aeration & Fountains		15,000	12	2,855	85.70%	1,099
R&M-Bulkhead		18,000		-	0.00%	-
Cap Outlay- Lake		20,382		-	0.00%	-
Total Lakes and Ponds		166,704	27	',821	16.69%	6,841
Capital Expenditures & Projects  Cap Outlay- Lake  Total Capital Expenditures & Projects		16,560 16,560		-	0.00%	 <u> </u>
Reserves						
Reserve - Bulkheads		14,539		_	0.00%	-
Reserves - Irrigation System		42,473		_	0.00%	-
Reserve - Lakes		12,062		_	0.00%	-
Reserves - Perimeter		6,861		_	0.00%	-
Reserve-Stormwater System		10,424		_	0.00%	-
Reserve-Aeration & Fountains		23,395		_	0.00%	-
Total Reserves		109,754		-	0.00%	-
TOTAL EXPENDITURES & RESERVES		449,095	57	',133	12.72%	18,815
Excess (deficiency) of revenues Over (under) expenditures			63	3,718	0.00%	 101,920
Net change in fund balance	\$		\$ 63	3,718	0.00%	\$ 101,920
FUND BALANCE, BEGINNING (OCT 1, 2020)		489,560	489	,560		
FUND BALANCE, ENDING	\$	489,560	\$ 553	,278		

#### Statement of Revenues, Expenditures and Changes in Fund Balances

For the Period Ending November 30, 2020

ACCOUNT DESCRIPTION	Δ	ANNUAL ADOPTED BUDGET	Y	EAR TO DATE	YTD ACTUAL AS A % OF ADOPTED BUD	 NOV-20 ACTUAL
REVENUES						
Interest - Investments	\$	2,500	\$	3	0.12%	\$ 1
Special Assmnts- Tax Collector		747,903		204,692	27.37%	204,692
Special Assmnts- Discounts		(29,916)		(8,240)	27.54%	(8,240)
TOTAL REVENUES		720,487		196,455	27.27%	196,453
EXPENDITURES						
Administration						
ProfServ-Property Appraiser		544		-	0.00%	-
ProfServ-Trustee Fees		3,800		3,408	89.68%	=
Misc-Assessmnt Collection Cost		816		344	42.16%	 344
Total Administration		5,160		3,752	72.71%	 344
<u>Debt Service</u>						
Principal Debt Retirement		585,000		-	0.00%	=
Interest Expense		124,574		62,357	50.06%	=
Total Debt Service		709,574		62,357	8.79%	 
TOTAL EXPENDITURES		714,734		66,109	9.25%	344
TOTAL EXPENDITURES		7 14,7 34		66,109	9.2376	344
Excess (deficiency) of revenues						
Over (under) expenditures		5,753		130,346	n/a	 196,109
OTHER FINANCING SOURCES (USES)						
Contribution to (Use of) Fund Balance		5,753		-	0.00%	-
TOTAL FINANCING SOURCES (USES)		5,753		-	0.00%	-
Net change in fund balance	\$	5,753	\$	130,346	n/a	\$ 196,109
FUND BALANCE, BEGINNING (OCT 1, 2020)		230,133		230,133		
FUND BALANCE, ENDING	\$	235,886	\$	360,479		

## Vasari Community Development District

### **Supporting Schedules**

November 30, 2020

#### Non Ad-Valorem Special Assessments (Lee County Tax Collector - Monthly Collection Distributions) For the Fiscal Year Ending September 30, 2021

								FUND ALL	.00	ATION
		Net		Discount /			Gross			
Date		Amount		(Penalties)	С	ollection	Amount	General	D	ebt Service
Received		Received		Amount		Costs	Received	Assmnts		Assmnts
Assessments	Levi	ed for FY 202	20				\$1,207,120	\$ 459,217	\$	747,903
Allocation %							100%	38%		62%
11/16/20	\$	21,508	\$	985	\$	-	\$ 22,492	\$ 8,557	\$	13,936
11/30/20		295,012		12,315		555	307,882	117,126		190,756
TOTAL		316,519		13,300		555	330,374	125,682		204,692
% COLLECTED							27%	27%		27%
TOTAL O/S							\$ 876,746	\$ 333,535	\$	543,211

#### Cash and Investment Report

November 30, 2020

	Ger	neral	Fu	nd
--	-----	-------	----	----

Account Name	Bank Name	Investment Type	<u>Maturity</u>	<u>Yield</u>	<u>Balance</u>
Checking Account - Operating	Valley National Bank	Government Interest Checking	n/a	0.25%	405,661
Money Market Acct	BankUnited	Public Funds Money Market	n/a	0.30%	\$353,657

#### Debt Service Fund

Account Name	Bank Name	Investment Type	Maturity	<u>Yield</u>	<u>Balance</u>
Series 2012 Reserve Fund	US Bank	1st American Oblig Fund	n/a	0.01%	\$70,870
Series 2012 Revenue Fund	US Bank	1st American Oblig Fund	n/a	0.01%	\$97,347
				Subtotal _	\$168,217
				Total	\$927,534

#### Vasari CDD

Bank Reconciliation

Bank Account No. 4409 VALLEY BANK GENERAL FUND

 Statement No.
 11-20

 Statement Date
 11/30/2020

406,980.65	Statement Balance	405,660.55	G/L Balance (LCY)
0.00	Outstanding Deposits	405,660.55	G/L Balance
		0.00	Positive Adjustments
406,980.65	Subtotal		_
1,320.10	Outstanding Checks	405,660.55	Subtotal
0.00	Differences	0.00	Negative Adjustments
405.660.55	Ending Balance	405.660.55	Ending G/L Balance

Difference 0.00

Posting Date	Document Type	Document No.	Description	Amount	Cleared Amount	Difference
Outstandin	g Checks					
11/19/2020	Payment	3624	LEE COUNTY PROPERTY APPRAISER	766.00	0.00	766.00
11/24/2020	Payment	3626	BARRY J. SANDS	184.70	0.00	184.70
11/24/2020	Payment	3627	RICHARD A. BRANT	184.70	0.00	184.70
11/24/2020	Payment	3628	RICHARD KRASKA	184.70	0.00	184.70
Tota	l Outstanding	Checks		1,320.10		1,320.10

#### **VASARI COMMUNITY DEVELOPMENT DISTRICT**

#### **Payment Register by Bank Account**

For the Period from 11/01/20 to 11/30/20 (Sorted by Check / ACH No.)

Pymt Type	Check / ACH No.	Date	Payee Type	Payee	Invoice No.	Payment Description	Invoice / GL Description	G/L Account#	Amount Paid
VALLEY	BANK GEN	ERAL FUND	) - (ACCT#	# XXXXX4409)					
Check	3621	11/19/20	Vendor	FLORIDA FOUNTAINS & EQUIP LLC	2020-62818	OCT FNTN/AERATION INSPECTION	Contracts-Fountain	001-534023-53917	\$550.00
Check	3622	11/19/20	Vendor	INNERSYNC STUDIO LTD	19007	QUARTERLY WEBSITE HOSTING/SUPPORT/TRAINGIN/COMPLIA	Misc. Web Hosting	001-549915-51301	\$153.75
Check	3622	11/19/20	Vendor	INNERSYNC STUDIO LTD	19007	QUARTERLY WEBSITE HOSTING/SUPPORT/TRAINGIN/COMPLIA	Misc. Web Hosting	001-549915-51301	\$234.38
Check	3623	11/19/20	Vendor	LAKE & WETLAND MANAGEMENT INC	8734-WC	NOV LAKE/LITTORAL MAINTENANCE	Contracts-Water Mgmt Services	001-534047-53917	\$2,803.70
Check	3624	11/19/20	Vendor	LEE COUNTY PROPERTY APPRAISER	009597	2020-2021 NON AD VALOREM ROLL	ProfServ-Property Appraiser	001-531035-51301	\$766.00
Check	3625	11/24/20	Employee	DENNIS P LAVALLE	PAYROLL	November 24, 2020 Payroll Posting			\$184.70
Check	3626	11/24/20	Employee	BARRY J. SANDS	PAYROLL	November 24, 2020 Payroll Posting			\$184.70
Check	3627	11/24/20	Employee	RICHARD A. BRANT	PAYROLL	November 24, 2020 Payroll Posting			\$184.70
Check	3628	11/24/20	Employee	RICHARD KRASKA	PAYROLL	November 24, 2020 Payroll Posting			\$184.70
ACH	DD226	11/11/20	Vendor	FPL- ACH	102020-7055 ACH	09/21/20-10/20/20 84604-77055	Electricity - Aerator	001-543051-53917	\$41.57
ACH	DD227	11/11/20	Vendor	FPL- ACH	102020-6054 ACH	09/21/20-10/20/20 73876-76054	Electricity - Aerator	001-543051-53917	\$104.38
								Account Total	\$5,392.58

## 5B.

# 5Bi

# 5Bi.a



Lake Management - Wetland & Preserve Maintenance Erosion Restoration - Mosquito & Midge Larvae Control Algae & Aquatic Weed Control - Native Planting Water Testing & Analysis - Fountains & Aerators

1/	SE	RVICE & INS				,
Eustomer: / 9596			Account	#: 148	/ Date:_	12/08
echnician: Ma	SUNNY	evy	Territory	BON	org Sp	erros
eather Conditions:	SUNNY					
	- /					
OLAKE MANAGEME		1. 3. 7. 7. 7.	10 22			
ALGAE CON GRASSES & I		Lake(s) #:/ Lake(s) #:/				
SUBMERSED		Lake(s) #: Lake(s) #:2				
FLOATING P		Lake(s) #: 7				
INSPECTION			ALL LAME	5		
☐ DEBRIS		Lake(s) #:				
Water Test Results (	Combined Aver	age)				
Temperature				AVERAGE	☐ LOW	
Dissolved Ox	kygen			AVERAGE	□ LOW	
pH reading Water Clarity				) NEUTRAL I FAIR	☐ BASE ☐ POOR	
Water Clarity Water Level				I AVERAGE	☐ LOW	
LITTORAL SHELF	-		SHELVES #:	7772777		
☐ SHORELINE (	GRASSES & EME	RGENTS	HERBICIDE TR	EATMENT	☐ DEBRI	IS REMOVAL
☐ FLOATING PL			MANUAL REM	10VAL	<del>_</del>	
☐ INVASIVE / E	XOTIC SPECIES		] INSPECTION			
UPLAND / WETLAN	D PRESERVE		PRESERVE(S) #	<b>#:</b>		
□ INVASIVE / E	<b>KOTIC SPECIES</b>		HERBICIDE TR		☐ DEBRI	S REMOVAL
☐ GRASSES			MANUAL REM	IOVAL	_	
□ VINES			INSPECTION			
MOSQUITO / MIDG			LAKE(S) #:			
□INSECTICIDE	_	_	INSPECTION			
omments: \ 470	Jes M3	£ 0000 =	or geag	E, CHARA	8 ANGWA	LLY.
OLFRE O	71040 7	-10 n	ALL FOR	BEST	2 28.11.55	//
100000	Claves /	, ,	y) por	9611 1	0,0213	4
H: OBSERVAT	OBream	O Catfish	O Grass carp	Cilapia	O Mosquitofish	Ochad
RDS: O Raptor	<b>O</b> Duck	O Wood Stork	Shorebird	Wading bird	Songbird	O Vulture
PTILES: O Alligator /ASIVE / EXOTIC PLANTS I	OSnake	<b>Turtle</b>	O Tortoise	Lizard	<b>AMPHIBIANS</b>	
zilian pepper OMelaleuca	OPennywort	OBischofia	OEarleaf Acacia	OAustralian pine	e OShoebutton	○Sedge
mbing Fern OAir potato	<b>OTorpedogras</b> :	S OAzolla	<b>○Salvinia</b>	ODowny rose myrtl	e OJava plum	OFloating H
tana OHydrilla TIVE PLANTS NOTED	OHygrophilia	Owater Lettuce	OWater hyacinth	OCattail	OPrimrose	OAlligatorw
oress OWax Myrtle	OFL Pine	ORed Maple	O Waterlily	OMangrove	OPond Apple	<b>○</b> Oak
coplum Ø Bylrush Iden Canna Ø Spikerush	OBlue flag iris	OStrangler fig	Arrowhead	<b>OPickerelweed</b>	<b>OThalia</b>	O Palms
by tears O Naiad	OButtonbush OChara	O Eelgrass O Duckweed	O Cordgrass O Bladderwort		s OSpatterdock OSlender spikerus	
species noted / commen		(1)	Diadderwort	Oronaweed	Objetituer spikerus	повасора

# 5Bi.b



Lake Management - Wetland & Preserve Maintenance Erosion Restoration - Mosquito & Midge Larvae Control Algae & Aquatic Weed Control - Native Planting Water Testing & Analysis - Fountains & Aerators

#### **SERVICE & INSPECTION REPORT**

Customer:	
Weather Conditions:  AKE MANAGEMENT  ALGAE CONTROL  GRASSES & EMERGENTS  Lake(s) #:  SUBMERSED AQUATICS  Lake(s) #:  INSPECTION  Lake(s) #:  DEBRIS  Water Test Results (Combined Average)  Temperature  Dissolved Oxygen  PM  HIGH  AVERAGE  LOW	
OLAKE MANAGEMENT    ALGAE CONTROL   Lake(s) #:	
☐ ALGAE CONTROL ☐ GRASSES & EMERGENTS ☐ SUBMERSED AQUATICS ☐ ELOATING PLANTS ☐ INSPECTION ☐ DEBRIS ☐ DEBRIS ☐ Lake(s) #: ☐ DEBRIS ☐ LOW ☐ Dissolved Oxygen ☐ ppm ☐ HIGH ☐ AVERAGE ☐ LOW	
GRASSES & EMERGENTS Lake(s) #:  SUBMERSED AQUATICS Lake(s) #:  FLOATING PLANTS Lake(s) #:  INSPECTION Lake(s) #:  DEBRIS Lake(s) #:  Water Test Results (Combined Average)  Temperature°F	
SUBMERSED AQUATICS   Lake(s) #:	
SUBMERSED AQUATICS   Lake(s) #:	
INSPECTION  Lake(s) #:  DEBRIS  Lake(s) #:  Water Test Results (Combined Average)  Temperature  Dissolved Oxygen  ppm  HIGH  AVERAGE  LOW  DISSOLVED  LOW	
DEBRIS   Lake(s) #:     Water Test Results (Combined Average)   Temperature   °F   HIGH   AVERAGE   LOW     Dissolved Oxygen   ppm   HIGH   AVERAGE   LOW	
Water Test Results (Combined Average)  Temperature°F □ HIGH □ AVERAGE □ LOW  Dissolved Oxygenppm □ HIGH □ AVERAGE □ LOW	
Temperature°F □ HIGH □ AVERAGE □ LOW Dissolved Oxygenppm □ HIGH □ AVERAGE □ LOW	
Dissolved Oxygenppm □ HIGH □ AVERAGE □ LOW	
I PUTCHALLY LINEUTRAL LINEUTRAL LINEUTRAL	
Water Clarity ☐ GOOD ☐ FAIR ☐ POOR	
Water Level □ HIGH □ AVERAGE □ LOW	
SHELVES #:	
SHORELINE GRASSES & EMERGENTS DEBRIS REM	10VAL
INVASIVE / EXOTIC SPECIES INSPECTION	
INVASIVE / EXOTIC SPECIES INSPECTION	
O UPLAND / WETLAND PRESERVE PRESERVE(S) #:	
☐ INVASIVE / EXOTIC SPECIES ☐ HERBICIDE TREATMENT ☐ DEBRIS REM	10VAL
☐ GRASSES ☐ MANUAL REMOVAL	
VINES INSPECTION	
O MOSQUITO / MIDGE LARVAE CONTROL  LAKE(S) #:	
☐ INSECTICIDE TREATMENT ☐ INSPECTION	
Comments: tracted lakes for torpalograss and unes.	
Tree triming at later 1, 18, 23; palms 3.5, 17, 19,	22
thatia at like 8	
FISH & WILDLIFE OBSERVATIONS	
FISH: O Bass O Broom O Catfish O Grass carp O Tilapia O Mosquitofish O Sh BIRDS: O Raptor O Duck O Wood Stork O Shorebird O Wading bird O Songbird O Vu	
REPTILES: O Alligator O Snake Turtle O Tortoise O Lizard O AMPHIBIANS O IN	
INVASIVE / EXOTIC PLANTS NOTED  Brazilian pepper O Melaleuca O Pennywort O Bischofia O Earleaf Acacia O Australian pine O Shoebutten O Se	
	age pating Hear
DLantana OHydrilla OHygrophilia OWater Lettuce OWater hyacinth OCattail OPrimrose OAII	ligatorweed
NATIVE PLANTS NOTED  Oppress OWax Myrtle OFL Pine ORed Maple OWaterfily OMartorove OPond Apple OX	al. /
Oppress OwarMyrtle OFL Pine ORed Maple Owaterfily OMangrove OPond Apple Occopium Obulrush OBlue flag iris OStrangler fig OA rowhead Opickerelweed Offialia OPa	
Golden Canna Spikerush OButtonbush OEelgrass OCordgrass OFakahatcheegrass OSpatterdock OFe	rns
Baby tears O Naiad OChara O Duckweed O Bladderwort O Pondweed O Slender spikerush O Ba	сора

## **5**C

From: Faircloth, Justin
To: Slaughter, Mona

Subject: VCDD- 1/12/21 Agenda Packet Item - FF 1/5/21 email

**Date:** Tuesday, January 5, 2021 10:37:44 AM

Attachments: image005.png image001.png

Mona,

Will you please include the email below in the Vasari 1/12/21 agenda packet if possible? If not no worries.

Thanks, Justin

Justin Faircloth | CAM, CDM | District Manager



239.785.0675 | www.inframarkims.com

#### SUPERVISORS, PLEASE DO NOT REPLY TO ALL AS THIS COULD BE A VIOLATION OF THE FLORIDA SUNSHINE PROVISIONS.

CONFIDENTIALITY NOTICE: The information in this email is intended for the sole use of the recipient(s) and may be confidential and subject to protection under the law. If you are not the intended recipient, you are hereby notified that any distribution or copying of this email is strictly prohibited. If you have received this message in error, please contact the sender immediately and delete your copy from your computer.

**From:** office@flfountains.com <office@flfountains.com>

Sent: Tuesday, January 5, 2021 10:21 AM

**To:** Faircloth, Justin < justin.faircloth@inframark.com>

Cc: srhoad@flfountains.com

Subject: RE: VCDD - RE: Fountain and Aeration proposals from Florida Fountains & Equipment

Hello Justin,

Happy New Year to you and yours. I was preparing the Dec. reports over the weekend when I found some discrepancies that I could not get solid answers to. I have sent a 2 man crew over this morning to iron it out and will have it to you post haste.

As far as taking the fountains to shore in order to be cleaned....

We have not been performing our cleanings in that manner for quite some time. We have found through trial and many errors that it causes more problems than the preventative measures save. By pulling the fountain to shore a few issues continually come up:

1. The pump/motor cables get hung up on rocks and other underwater obstructions that can

- easily damage the cable's coating that even unseen can slowly cause damage to the motor, lights, and/or controls. The constant wear and tear causes premature cable replacement.
- 2. The primary splices (at the motor), as well as the secondary ones (repairs and "scabs") become compromised. Even when the technician replaces the splice due to the pulling and stretching, it opens the door for other problems. The new splice may not be as water tight as the last and resplicing it at every service will eventually shorten the cable as well as increase the cost of the services.
- 3. Removing a fountain to clean it and then returning it makes it very difficult to place it back exactly to where it was. We all know that even a few degrees of difference is noticeable from a resident's window or other favorite vantage. Even the slightest change creates an inconsistency and negative experience when viewed from a constant reference point.

We have made some changes in equipment and technique since the new ownership regarding the cleanings. The previous service was a hard brushing of the intake and a towel wipe of the lights. Our PM Service Tech is given a large pressure washer with extended wand and a variety of pressure tips depending on the job. He uses a Round-a-Bout Watercraft that allows him to do all the work from the boat. It is approximately 72" in diameter and cannot be submersed. He can flip the smaller fountains right in place to get to the intake. In severe cases, the basket is removed and the wand is inserted into the tube to be flushed out. The larger fountains cannot be flipped but can easily be reached with the wand using maximum pressure. Also, the nozzles are removed and flushed through. We feel that the current method is by far the best way to perform these cleanings.

As mentioned previously, I will have the reports over to you as soon as our guys are back with the most current findings.

Thank you, Sean

Sean Helmstetter/Operations Manager Florida Fountains & Equipment 17252 Alico Center Rd, Suite 2 Fort Myers, FL 33967 (239) 567-3030

www.FLFOUNTAINS.com



**From:** Faircloth, Justin < <u>justin.faircloth@inframark.com</u>>

**Sent:** Monday, January 4, 2021 10:29 PM

**To:** office@flfountains.com **Cc:** srhoad@flfountains.com

Subject: RE: VCDD - RE: Fountain and Aeration proposals from Florida Fountains & Equipment

**Importance:** High

Good evening,

Hope you and yours had a wonderful Christmas and a happy New Year!

Just following up on my previous email from 12/11/20. Would you please let me know once you have completed the fountain cleaning for those fountains not cleaned on the lake shore as required by the contract as noted in my 12/8/20 email? Additionally, the agenda packet goes out tomorrow morning and I have not received your fountain/aeration reports for December. Would you please send them to me ASAP?

Thank you, Justin

Justin Faircloth | CAM, CDM | District Manager



239.785.0675 | www.inframarkims.com

#### SUPERVISORS, PLEASE DO NOT REPLY TO ALL AS THIS COULD BE A VIOLATION OF THE FLORIDA SUNSHINE PROVISIONS.

CONFIDENTIALITY NOTICE: The information in this email is intended for the sole use of the recipient(s) and may be confidential and subject to protection under the law. If you are not the intended recipient, you are hereby notified that any distribution or copying of this email is strictly prohibited. If you have received this message in error, please contact the sender immediately and delete your copy from your computer.

## 5Ciii.

## Vasari Lake Fountain & Aeration Log

Lake #	Date	Invoice #	Service Issue	Cost	Comments
Lake 1	25		Has lights on the fountain	3331	
24.10 2			The lights on the rountain		
Agua Control 7.5 HP					Collier Water Systems - 3-year warranty
TriTier	8/5/2015		Lake Fountain - New 7.5 Hp Fountain Installed	\$11 795 00	included, 1 year warranty-lights
mmer	0/3/2013	D2016-	Zake Fourtain Wew 7.5 Tip Fourtain installed	Ψ11,733.00	included, 1 year warrancy lights
		9647/2016-			
	3/5/2018		3-36W LED lights - 3 - Custom Brackets	\$1,037.00	FF
		2018-9896	Fountain Pressure Washed	\$175.00	
		2018-10187	Replaced intermatic timer		F.F 1-yr warranty
		2018-10285	Adjusted timer	\$129.00	
		2018-10310	replaced 2 start capacitors		FF - 30 day warranty
		2018-10310	replaced 2 run capacitors		FF - 30 day warranty
		2018-10310	replaced 1 relay		FF - 30 day warranty
	1/13/2013	2010 10310	7.5hp 230V 1P motor Serial #2095215203 and 7.5hp	Ş <del>-1</del> 5.00	11 30 day warrancy
	2/19/2019	2019-10411	pump Serial #222074684861	\$3,890,00	FF 2yr warranty on motor and pump
	3/28/2019		Replaced Start Capacitor	\$0.00	11 Zyr warrancy on motor and pamp
	3/20/2013	201310310	replaced Start capacitor	\$0.00	
	4/12/2010	2019-10546	7.5HP start box extensive rewiring with 2hrs. Labor	\$057.00	FF 1 yr warranty
		2019-10340	repaired cracked nozzle		FF 1 yr warranty
		2020-11336	Replaced one light 36W LED		FF 1 yr warranty
		2016-9865	Reset timer/installed new photo cell		FF - 30 day warranty
		2016-9864	Fountain Pressure Washed	\$129.00	
				\$1/5.00	sent email to FF on 7/7/20
	7/5/2020		Email from Supervisor Brant fountain was down		sent email to FF ON 7/7/20
	7/0/2020		Email from EE stating founts in the stating again		action item completed
	7/8/2020		Email from FF stating fountain was running again Sent email to FF that fountain was out and safety		action item completed
	0/20/2020				L 5: VIA 5 - EE - 40 /E /20
	9/28/2020		issues should be addressed.	4477.00	left VM for FF on 10/5/20
	10/16/2020	2020-62744	Fountain Pressure Washed	\$175.00	FF .
Lake 1-Air			Has pencil diffusers		
			1 Compressor Cabinet, 2 Air Stations, Shoreline Valve		
	5/17/2010		Box, 1" PVC Pipe, Bottom Line Tubing		Vertex
		D2016-			
	/5/183	9647/2016-	1-small filter change, 1-115V fan	\$380.95	F.F.
	6/5/2019	2019-10699	replaced 2 pencil diffusers (1hr. Of labor)	\$227.00	FF 1 yr warranty on diffusers
			1/4HP 120V ro cking piston compressor Serial		·
	8/5/2019	2019-10857	#0619909851	\$917.00	FF 1 yr warranty
	5/5/=5=5			70-1100	
	2/14/2020	2020-11425	enclosure box and cooling fan install	\$702.25	FF 30 day warranty
	2/14/2020	2020-11423	enclosure box and cooling fan install	7733.23	sent email to FF on 7/7/20. 7/21/20
			email from Supervisor Sands about west diffuser not		report states aeration working properly.
	7/7/2020		working properly		Issue resolved.
Lake 2-Air	77772020		Working property		15540 10501404.
Luke 2 All					
					Vertex - connected to lakes 2,3,4,6, & 7 -
					2 Compressor Cabinets, 9 Air Stations, 5
					Shoreline Valve Box, 1" PVC Pipe, Bottom
					Line Tubing - Compressors located Along
	F /17/2010		2 Diffusers		
Labor 2 Aire	5/17/2010		2 Diffusers		Altessa Way on the NW corner of lake 3
Lake 3-Air					
					Vertex - connected to lakes 2,3,4,6, & 7 -
					2 Compressor Cabinets, 9 Air Stations, 5
					Shoreline Valve Box, 1" PVC Pipe, Bottom
1					Line Tubing - Compressors located Along
	5/17/2010		4 Diffusers		Altessa Way on the NW corner of lake 3
			110 Volt 1/2 hp Rocking Piston Compressor		Collier Water Systems - Replaced
	3/27/2017	6003	Replacement	\$965.00	Compressor that runs lakes 2 & 3
			Easy Pro 3/4HP 230V aeration compressor serial #		
	11/16/2020	2020-11609	1118904633 for #3B	\$1,098.98	FF - 1yr warranty
Lake 4-Air					
					, , , , , , , , , , , , , , , , , , ,
					Vertex - connected to lakes 2,3,4,6, & 7 -
					2 Compressor Cabinets, 9 Air Stations, 5
					Shoreline Valve Box, 1" PVC Pipe, Bottom
					Line Tubing - Compressors located Along
	5/17/2010	<u> </u>	1 Diffuser		Altessa Way on the NW corner of lake 3
	8/1/2015		Aeration - Repair Lake Diffusor & Install new valve		
			<u> </u>		

## Vasari Lake Fountain & Aeration Log

		<del></del>	Opuated 12 5 20		
Lake #	Date	Invoice #	Service Issue	Cost	Comments
Lake 5-Air					
			Vertex - 1 Compressor Cabinet, 2 Air Stations, 1" PVC		
			•		
	5/17/2010		Pipe, Bottom Tubing		
Lake 6-Air					
20.10 0 7 111					
					Vertex - connected to lakes 2,3,4,6, & 7 -
					2 Compressor Cabinets, 9 Air Stations, 5
					•
					Shoreline Valve Box, 1" PVC Pipe, Bottom
					Line Tubing - Compressors located Along
	5/17/2010		1 Diffuser		Altessa Way on the NW corner of lake 3
	5/17/2010		1 Dilluser		Artessa way on the NW corner of lake 3
Lake 7-Air					
					Vertex - connected to lakes 2,3,4,6, & 7 -
					2 Compressor Cabinets, 9 Air Stations, 5
					Shoreline Valve Box, 1" PVC Pipe, Bottom
					Line Tubing - Compressors located Along
	5/17/2010		2 Diffusers		Altessa Way on the NW corner of lake 3
	4/1/2019	2019-10516	rebuilt manifold		F.F 1yr. Warranty
	7/ 1/ 2013	-010 10010	Received email from R. Brant that aeration was not	00.51ډ	Tyr. vvariality
	9/21/2020		functioning		Reported to FF on 9/22/20 by email.
Lake 8-Air					
Lake o-All					
1					
1					
1					Vertex - connected to lakes 8 & 9 - 1
					Compressor Cabinet (2 Compressors), 4
1					
1					Air Stations, "1 PVC Pipe, Bottom Tubing,
					1 Valve Box - Compressor located at the
					-
					corner of Via De Vasari Drive on the east
	5/17/2010		1 Diffuser		corner of the FPL Easement
Lake 9-Air	, ,		two compressors in the cabinet		
Lake 3-All			two compressors in the cabinet		
					Vertex - connected to lakes 8 & 9 - 1
					Compressor Cabinet (2 Compressors), 4
					Air Stations, "1 PVC Pipe, Bottom Tubing,
					1 Valve Box - Compressor located at the
					•
					corner of Via De Vasari Drive on the east
	5/17/2010		3 Diffusers		corner of the FPL Easement
				¢1.0C2.44	
	1/6/2017		New Bypass Line Installed	\$1,962.44	Collier Water Systems
			Lake #9 Aeration Repair this set repair Lakes 8 & 9 (2)		
			New Dual membrance Diffusers with check valve		
	1/5/2017		system 1,300 ft of 1/2" ID weighted aeration line	\$1,976,52	Collier Water Systems
	2/0/2027		system 2,000 it of 2/2 is neighted defactor into	ψ <u>2</u> ,52	eemer trater systems
			1/2 hp Commercial 230 V lake Aeration Compressor		
1			w/ Air Release Valve Labor to install compressor &		
1	6/20/2047	co==	· '	ć4 4F0.00	Calliar Water Customs
	6/29/2017	60//	new Mainfold release valve	\$1,450.00	Collier Water Systems
			2ea. 1/2 HP 230V compressors Serial #s 0918907609 &		
	10/4/2018	2018-10036	091890611	\$3,753,00	F.F 1-yr warranty
	20/ 1/2010	_510 10030	1/2hp 230V Dual Head Aqua Master Compressor	<del>75,755.00</del>	
1					l
	12/13/2019	2020-11324	Model # 940460 Serial #312303-3	\$927.20	F.F 1-yr warranty
		2020-11469	1/2HP 230V aeration compressor for #9B	\$1,056,00	F.F 1 yr warranty expries 2/18/21
	9/11/2020			72,000.00	Reported to FF on 9/11/20 by email.
			B. Sands reported aeration was not working		
	9/21/2020		S. Zeidner reported aeration was not working		Reported to FF on 9/22/20 by email.
Lake 10-Air					
					Vertex - Connected to lakes 10, 16 & 17 -
1					-
1					1 AirStation, 1 Valve Box, 1" PVC,
					Bottomline Tubing - Compressor location
1	E /17/2010		1 Diffusor		
	5/17/2010		1 Diffuser		lake 17
	4/1/2015		Aeration - Diffuser change		Collier Water Systems
1			Dual Membrane Diffuser, Aluminum 2-way Manifold		
1					
1			splitter w/connectors & Check Vlave, 12x12 access box		
1	6/1/2017	6056	for adjustment, 200' weighted line	\$1.625.00	Collier Water Systems
	0/1/201/	0030	ror aajastineitt, 200 weigittea iiile	00.620,14	Comer water systems
1					l
1	12/5/2018	2018-10217	Replaced capacitor in compressor under warranty	\$0.00	l
	-, -, -0-10	· ·	3 pencial diffusers installed to help with algae issues -	70.00	
1					
	5/7/2019	2019-10609	2 hrs. of labor.	\$405.00	FF-1yr. Warranty
			email from Steve Brei about the eastern diffuser not		
1	7 /5 /000				t
	7/5/2020		working		sent email to FF on 7/7/20

## Vasari Lake Fountain & Aeration Log

Email from FF stating valves were adjusted and water fulshed out of the line - will check on next visit to determine if there is a continuous leak   2 emails from Steve Brei about the aereation not fixed/barely percolating   sent email to FF on 7/9/20   Received confirmation from FF that new compressor   had been installed   resolved   r	Lake #	Date	Invoice #	Service Issue	Cost	Comments
TRANSPOON				Email from FF stating valves were adjusted and water		
2 emails from Sieve Beri about the aereation not   fineship emboding   fineship embo				fulshed out of the line - will check on next visit to		
2 emails from Sieve Beri about the aereation not   fineship emboding   fineship embo		7/8/2020		determine if there is a continuous leak		
Secretario   Sec				2 emails from Steve Brei about the aereation not		
April		7/9/2020				
Index   1.0				Received confirmation from FF that new compressor		sent email to Steve Brei on 10/5/20 item
Lake 13.Air   S/17/2010   2 Offisers   S/17/		9/25/2020				resolved
Vertex - Connected to lakes 11, 12, & 13 - 2 Air Stations, 1 Valve Roc, Rottomine Lubing, 1°P RC Top ex-Compressor location lake 13				Installed new 3/4/hp Aqua Master Deluxe aeration		
Vertex - Connected to lakes 11, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 11, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 11, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 11, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 11, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 11, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 13, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 13, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 13, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 13, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 13, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 13, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 13, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 13, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 13, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 13, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 13, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 13, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) Control (and to lake 13, 12, 813 - 2 \( \text{Air Stations}, \) 2 \( \text{Vertex} \) 2 \( \t		10/6/2020	2020-62700	system serial #0075771	\$4,300.00	FF - 1yr. Warranty
Lake 12-Air	Lake 11-Air					Northern Coursell to John 44 42 9 42
Lake 12-Air						·
Lake 12-Air						
Vertex - Connected to lakes 11, 12, & 13*   2		- 4 - 4				
Section   Sect		5/1//2010		2 Diffusers		location lake 13
Syl/2010   1 Diffuser   1 Dif	Lake 12-Air					Vertex - Connected to lakes 11 12 & 13 -
Syl17/2010   1 Diffuser   1 D						
Syl172010   September   Syl172010   September   Syl172010   Lake Fountain   Syl172010   Lake Fountain - Fountain Light Bulbs Replaced   Syl172010   Lake Fountain - Fountain Light Bulbs Replaced   Syl172010   September   Syl172010   Syl172010   Syl172010   September   Syl172010						
Agua Control 7.5 HP   3/16/2015   Lake Fountain - Fountain Light Bulbs Replaced   1.4		F /17/2010		1 Different		
Agus Control 7.5 HP TriTier 3/16/2015 1.1ke Fountain - Fountain Light Bulbs Replaced 1.1ke Fountain - Replaced steel eye hook and repositioned fountain back into place 4/12/2016 4/12/2016 1/12/2018 2018-1081 1/12/2018 2018-10187 1/12/2019 2	Lake 12	5/17/2010				location lake 13
TriTier   3/16/2015   Lake Fountain - Fountain Light Bulbs Replaced to Lake Fountain - Replaced Steel eye hook and repositioned fountain heak into place   \$246.00				Has LED Lights on the fountain		
Lake Fourtain - Replaced steel eye hook and repositioned fortusin back into place   \$246.00	· ·	3/16/2015		Lake Fountain - Fountain Light Bulbs Poplaced		
3/1/2015   3/1/2016   5671 & 5694   New 7.51p Fountain hask into place   \$246.00   \$41,2016   5011 & 5694   New 7.51p Fountain hask into place   \$11,202,003   2-year warranty included   \$11,202,003   5018-030   New 7.51p Fountain hask into place   \$175,001   \$175,001   \$1018-0310   New 7.51p Fountain hask into place   \$175,001   \$175,001   \$1018-0310   New 7.51p Fountain hask into place   \$175,001   \$175,001   \$1018-0310   New 7.51p Fountain hask into place   \$175,001   \$175,001   \$175,001   \$1018-0310   New 7.51p Fountain hask into place   \$180,000   \$180,000   New 7.51p Fountain hask into place   \$180,000   \$180,000   New 7.51p Fountain hask into place   \$180,000   \$180,000   New 7.51p Fountain hask into place   \$180,000   New 7.51p Fou	miller	3/10/2015				
Af12/2016   5671 & 5694   New 7-5Hp Fountain Installed   \$11,195.00   3-year warranty included   \$11/20/2018   2018-986   Fountain Pressure Washed   \$175.00   FF   \$11/20/2018   2018-10317   \$11/20/2019   2018-10310   replaced 2 start capacitors   \$49.98   FF - 30 day warranty   \$49.00   FF - 30 day warranty   \$49.		3/1/2015			\$2 <i>16</i> 00	
8/15/2018 2018-998   Fourtian Pressure Washed   \$175.00   FF     11/20/2018 2018-10187   Replaced 2 start capacitors   \$49.98   FF - 30 day warranty     11/15/2019 2018-10310   replaced 2 start capacitors   \$49.98   FF - 30 day warranty     11/15/2019 2018-10310   replaced 2 run capacitors   \$49.98   FF - 30 day warranty     11/15/2019 2018-10310   replaced 2 run capacitors   \$49.98   FF - 30 day warranty     11/15/2019 2018-10310   replaced 5 run capacitors   \$49.98   FF - 30 day warranty     11/15/2019 2018-10310   replaced 5 run capacitors   \$49.98   FF - 30 day warranty     11/15/2019 2018-103136   replaced 5 run capacitors   \$49.98   FF - 30 day warranty     11/15/2019 2018-103136   replaced 6 run capacitors   \$49.99   FF - 30 day warranty     11/15/2019 2018-10310   replaced 6 run capacitors   \$49.99   FF - 30 day warranty     11/15/2019 2018-10310   replaced 6 run capacitors   \$49.90   FF - 30 day warranty     11/15/2019 2016-965   ratialed a new 60 AMP breaker   \$14.95   FF - 30 day warranty     11/15/2010 2016-965   fourtain Pressure Washed   \$175.00   FF     11/15/2010   3 Diffusers   2 Air Stations, 1 Valve Box, Bottomline     11/15/2010   3 Diffusers   2 Air Stations, 1 Valve Box, Bottomline     11/15/2010   3 Diffusers   2 Air Stations, 1 Valve Box, Bottomline     11/15/2010   3 Diffusers   2 Air Stations, 1 Valve Box, Bottomline     11/15/2019   3 Diffusers   2 Air Stations, 1 Valve Box, Bottomline     11/15/2019   3 Diffusers   3 Air Stations, 1 Valve Box, Bottomline     11/15/2019   2 Air Station   8 Air Station   8 Air Station     11/15/2019   3 Diffusers   3 Air Station   8 Air Station     11/15/2019   2 Diffusers   3 Air Station   8 Air Station   8 Air Station     11/15/2019   2 Diffusers   3 Air Station   8 Air Station   8 Air Station     11/15/2010   2 Diffusers   3 Air Station   8 Ai			5671 & 569 <i>1</i>			3-vear warranty included
11/20/2018   2018-10.187				·		
1/15/2019   2018-10310   replaced 2 start capacitors   \$49.98   FF - 30 day warranty						
1/15/2019   2018-10310   replaced 2 run capacitors   \$49.98   F- 30 day warranty						
1/15/2019   2018-10310   replaced I relay   \$49.00   FF - 30 day warranty   1/16/2019   2019-11317   replaced start box   \$368.00   FF - 30 day warranty   1/16/2020   2020-11336   replaced timer   \$149.99   FF - 6 months   \$149.99   FF - 6 months   \$147/2020   2018-2056   for months   \$149.99   FF - 6 months   \$149.99   FF - 6 months   \$149.99   FF - 6 months   \$147/2020   2018-2056   for months   \$149.99   FF - 6 months   \$149.99   FF - 6 months   \$147/2020   2020-62744   for months   \$149.99   FF - 70 day warranty   \$149.99   FF - 70 day warranty   \$149.99   FF - 30 day warranty   \$1				·		
11/4/2019   2019-11117   replaced start box   3368.00   F.F 1-yr warranty						
18/2020   2020-11336   replaced timer   \$149.99   F.F 6 months				· · ·	•	· ·
3/12/2020   2016-9864   Fountain Pressure Washed   \$175.00   FF						
3/12/2020   2016-9864   Fountain Pressure Washed   \$175.00   F				'		
Lake 13-Air						
Lake 13-Air   Vertex - Connected to lakes 11, 12, & 13 - 2 Air Stations, 1 Valve Box, Bottomline tubing, 1" PVC Pipe - Compressor location lake 13   2 Air Stations, 1 Valve Box, Bottomline tubing, 1" PVC Pipe - Compressor location lake 13   3/1/2015   Aeration - New 3/4 Hp Aeration compressor   \$1,795.00   Collier Water Systems   7/1/2016   Aeration System Capacitor Replaced   \$0.00   Collier Water Systems   \$3/1/2017   Aeration New 1/2 Hp Rocking Piston Compressor   Collier Water Systems - 1-Year Warranty Included   Collier Water Systems - 1-Year Warranty Included   \$1/2/1/2016   S1/2018   \$9738   2- large compressor filter changes   \$144.40   F.F.   F.						
Vertex - Connected to lakes 11, 12, & 13-2 Air Stations, 1 Valve Box, Bottomline tubing, 1" PVC Pipe - Compressor sor so, 2 Air Stations, 1 Valve Box, Bottomline tubing, 1" PVC Pipe - Compressor location lake 13   3/1/2015	Lake 13-Air	10/ 10/ 2020	2020 027	- Caritain 1 1 23341 2 1 Vashea	<b>¥175.00</b>	
Solition						Vertex - Connected to lakes 11, 12, & 13 -
S/17/2010   3 Diffusers   location lake 13						2 Air Stations, 1 Valve Box, Bottomline
3/1/2015   Aeration - New 3/4 Hp Aeration compressor   \$1,795.00   Collier Water Systems						tubing, 1" PVC Pipe - Compressor
7/1/2016   Aeration System Capacitor Replaced   \$0.00   Collier Water Systems		5/17/2010		3 Diffusers		location lake 13
Aeration New 1/2 Hp Rocking Piston Compressor  D2016- 9647/2016- 3/5/2018 9738  2- large compressor filter changes  \$144.40 F.F.  New cabinet with 2 3/4 HP 115V compressors, valve assemblies, pressure gauge, pressure relief valves, high volume cooling fans, sound suppression  1/15/2019 2018-10310  repaired air lines  \$39.00 FF - 1-yr warranty  email from Supervisor Sands about cover missing on equipment box  email from FF on 7/9/20 that new cover on handhold  7/8/2020  8-email from FF on 7/9/20 that new cover on handhold  was installed  2 Diffusers  5/17/2010  2 Diffusers  5/17/2010  2 Diffusers  1/2/HP 230V Commpressor installed  1/2/13/2019 2020-11323  #940460 Serial #313203-1  \$1,056.20 FF1-yr warranty		3/1/2015		Aeration - New 3/4 Hp Aeration compressor	\$1,795.00	Collier Water Systems
Aeration New 1/2 Hp Rocking Piston Compressor  D2016- 9647/2016- 3/5/2018 9738  2- large compressor filter changes  \$144.40 F.F.  New cabinet with 2 3/4 HP 115V compressors, valve assemblies, pressure gauge, pressure relief valves, high volume cooling fans, sound suppression  1/15/2019 2018-10310  repaired air lines  \$39.00 FF - 1-yr warranty  email from Supervisor Sands about cover missing on equipment box  email from FF on 7/9/20 that new cover on handhold  7/8/2020  8-email from FF on 7/9/20 that new cover on handhold  was installed  2 Diffusers  5/17/2010  2 Diffusers  5/17/2010  2 Diffusers  1/2/HP 230V Commpressor installed  1/2/13/2019 2020-11323  #940460 Serial #313203-1  \$1,056.20 FF1-yr warranty		7/1/2016		Aeration System Capacitor Replaced	\$0.00	Collier Water Systems
D2016- 9647/2016- 3/5/2018 9738						Collier Water Systems - 1-Year Warranty
9647/2016- 3/5/2018 9738  2- large compressor filter changes  5144.40 F.F.  New cabinet with 2 3/4 HP 115V compressors, valve assemblies, pressure gauge, pressure relief valves, high volume cooling fans, sound suppression  7/25/2018 2018-9835 high volume cooling fans, sound suppression  1/15/2019 2018-10310 repaired air lines  939.00 F.F 1-yr warranty  email from Supervisor Sands about cover missing on equipment box  email from FF on 7/9/20 that new cover on handhold  7/8/2020 email from FF on 7/9/20 that new cover on handhold  was installed  1/8/2020 2 Diffusers  2 Diffusers  6/12/2018 2018-2526 1/2/HP 230V Commpressor installed  1/2/13/2019 2020-11323 #940460 Serial #312303-1  1/2/13/2019 2020-11323 #940460 Serial #312303-1  3/12/2020 2016-9864 Fountain Pressure Washed  5/15.00 FF		3/1/2017		Aeration New 1/2 Hp Rocking Piston Compressor		Included
3/5/2018   9738   2- large compressor filter changes   \$144.40   F.F.			D2016-			
New cabinet with 2 3/4 HP 115V compressors, valve assemblies, pressure gauge, pressure relief valves, high volume cooling fans, sound suppression \$3,753.00 F.F 1-yr warranty  1/15/2019 2018-10310 repaired air lines \$39.00 FF - 1yr warranty  mail from Supervisor Sands about cover missing on equipment box email from FF on 7/9/20 that new cover on handhold was installed  7/8/2020 email from FF on 7/9/20 that new cover on handhold was installed  Lake 14-Air  Lake 14-Air  Vertex - Connected to lakes 14 & 15 - 1 Compressor Cabinet, 1" PVC Pipe, Bottomline Tubing - Compressor location lake 14  F.F 1-yr warranty from date of installation. Sent request for \$1,288.00 confirmation  1/2hp 230V dual head aqua master compressor Model 12/13/2019 2020-11323 #940460 Serial #312303-1 \$1,056.20 F.F 1-yr warranty  3/12/2020 2016-9864 Fountain Pressure Washed \$175.00 FF			9647/2016-			
assemblies, pressure gauge, pressure relief valves, high volume cooling fans, sound suppression  1/15/2019 2018-10310  repaired air lines  7/7/2020  email from Supervisor Sands about cover missing on equipment box email from FF on 7/9/20 that new cover on handhold 7/8/2020  was installed  Lake 14-Air  Vertex - Connected to lakes 14 & 15 - 1 Compressor Cabinet, 1" PVC Pipe, Bottomline Tubing - Compressor location lake 14  F.F 1-yr warranty from date of installation. Sent request for confirmation  1/2hp 230V Commpressor installed  1/2hp 230V dual head aqua master compressor Model 12/13/2019 2020-11323 #940460 Serial #312303-1  \$1,75.00 FF		3/5/2018	9738	2- large compressor filter changes	\$144.40	F.F.
assemblies, pressure gauge, pressure relief valves, high volume cooling fans, sound suppression  1/15/2019 2018-10310  repaired air lines  7/7/2020  email from Supervisor Sands about cover missing on equipment box email from FF on 7/9/20 that new cover on handhold 7/8/2020  was installed  Lake 14-Air  Vertex - Connected to lakes 14 & 15 - 1 Compressor Cabinet, 1" PVC Pipe, Bottomline Tubing - Compressor location lake 14  F.F 1-yr warranty from date of installation. Sent request for confirmation  1/2hp 230V Commpressor installed  1/2hp 230V dual head aqua master compressor Model 12/13/2019 2020-11323 #940460 Serial #312303-1  \$1,75.00 FF						
7/25/2018   2018-9835   high volume cooling fans, sound suppression   \$3,753.00   F.F 1-yr warranty						
1/15/2019 2018-10310 repaired air lines \$39.00 FF - 1yr warranty  email from Supervisor Sands about cover missing on equipment box  email from FF on 7/9/20 that new cover on handhold was installed  7/8/2020 email from FF on 7/9/20 that new cover on handhold was installed  Vertex - Connected to lakes 14 & 15 - 1 Compressor Cabinet, 1" PVC Pipe, Bottomline Tubing - Compressor location lake 14  F.F 1-yr warranty from date of installation. Sent request for confirmation  1/2hp 230V dual head aqua master compressor Model 12/13/2019 2020-11323 #940460 Serial #312303-1 \$1,056.20 F.F 1-yr warranty 3/12/2020 2016-9864 Fountain Pressure Washed \$175.00 FF						
email from Supervisor Sands about cover missing on equipment box email from FF on 7/9/20 that new cover on handhold was installed  Lake 14-Air  Lake 14-Air  Vertex - Connected to lakes 14 & 15 - 1 Compressor Cabinet, 1" PVC Pipe, Bottomline Tubing - Compressor location lake 14  5/17/2010  2 Diffusers  Bottomline Tubing - Compressor location lake 14  F.F 1-yr warranty from date of installation. Sent request for confirmation  1/2hp 230V dual head aqua master compressor Model 12/13/2019 2020-11323 #940460 Serial #312303-1 \$1,056.20 F.F 1-yr warranty \$1,056.20 F.F 1-yr warranty				high volume cooling fans, sound suppression		
7/7/2020   equipment box   sent email to FF on 7/7/20		1/15/2019	2018-10310		\$39.00	FF - 1yr warranty
email from FF on 7/9/20 that new cover on handhold was installed  Lake 14-Air  Vertex - Connected to lakes 14 & 15 - 1 Compressor Cabinet, 1" PVC Pipe, Bottomline Tubing - Compressor location lake 14  F.F 1-yr warranty from date of installation. Sent request for confirmation  1/2hp 230V dual head aqua master compressor Model 12/13/2019 2020-11323 #940460 Serial #312303-1 \$1,056.20 F.F 1-yr warranty  3/12/2020 2016-9864 Fountain Pressure Washed \$175.00 FF						
Tyle		7/7/2020				sent email to FF on 7/7/20
Lake 14-Air  Vertex - Connected to lakes 14 & 15 - 1 Compressor Cabinet, 1" PVC Pipe, Bottomline Tubing - Compressor location lake 14  F.F 1-yr warranty from date of installation. Sent request for confirmation  1/2hp 230V dual head aqua master compressor Model 12/13/2019 2020-11323 #940460 Serial #312303-1 \$1,056.20 F.F 1-yr warranty  3/12/2020 2016-9864 Fountain Pressure Washed \$175.00 FF						
Vertex - Connected to lakes 14 & 15 - 1 Compressor Cabinet, 1" PVC Pipe, Bottomline Tubing - Compressor location lake 14  F.F 1-yr warranty from date of installation. Sent request for 6/12/2018 2018-2526 1/2/HP 230V Commpressor installed 1/2hp 230V dual head aqua master compressor Model 12/13/2019 2020-11323 #940460 Serial #312303-1 \$1,056.20 F.F 1-yr warranty 3/12/2020 2016-9864 Fountain Pressure Washed \$175.00 FF		7/8/2020		was installed		action item completed
Compressor Cabinet, 1" PVC Pipe, Bottomline Tubing - Compressor location lake 14  F.F 1-yr warranty from date of installation. Sent request for 6/12/2018 2018-2526 1/2/HP 230V Commpressor installed \$1,288.00 confirmation 1/2hp 230V dual head aqua master compressor Model 12/13/2019 2020-11323 #940460 Serial #312303-1 \$1,056.20 F.F 1-yr warranty 3/12/2020 2016-9864 Fountain Pressure Washed \$175.00 FF	Lake 14-Air					Vortov Connected to lake 14.9.45
Bottomline Tubing - Compressor location lake 14  F.F 1-yr warranty from date of installation. Sent request for confirmation  6/12/2018 2018-2526 1/2/HP 230V Commpressor installed \$1,288.00 confirmation  1/2hp 230V dual head aqua master compressor Model 12/13/2019 2020-11323 #940460 Serial #312303-1 \$1,056.20 F.F 1-yr warranty  3/12/2020 2016-9864 Fountain Pressure Washed \$175.00 FF						
5/17/2010 2 Diffusers lake 14  F.F 1-yr warranty from date of installation. Sent request for installation. Sent request for 5/12/2018 2018-2526 1/2/HP 230V Commpressor installed \$1,288.00 confirmation  1/2hp 230V dual head aqua master compressor Model 12/13/2019 2020-11323 #940460 Serial #312303-1 \$1,056.20 F.F 1-yr warranty  3/12/2020 2016-9864 Fountain Pressure Washed \$175.00 FF						
F.F 1-yr warranty from date of installation. Sent request for						
Installation. Sent request for		5/17/2010		2 Dittusers		lake 14
6/12/2018     2018-2526     1/2/HP 230V Commpressor installed     \$1,288.00     confirmation       1/2hp 230V dual head aqua master compressor Model     12/13/2019     2020-11323     #940460 Serial #312303-1     \$1,056.20     F.F 1-yr warranty       3/12/2020     2016-9864     Fountain Pressure Washed     \$175.00     FF						
1/2hp 230V dual head aqua master compressor Model 12/13/2019 2020-11323 #940460 Serial #312303-1 \$1,056.20 F.F 1-yr warranty 3/12/2020 2016-9864 Fountain Pressure Washed \$175.00 FF						·
12/13/2019       2020-11323       #940460 Serial #312303-1       \$1,056.20       F.F 1-yr warranty         3/12/2020       2016-9864       Fountain Pressure Washed       \$175.00       FF		6/12/2018	2018-2526		\$1,288.00	confirmation
3/12/2020 2016-9864 Fountain Pressure Washed \$175.00 FF						
Lake 15 Has Lights on the fountain		3/12/2020	2016-9864		\$175.00	FF
	Lake 15			Has Lights on the fountain		

			Updated 12-9-20		
Lake #	Date	Invoice #	Service Issue	Cost	Comments
					Collier Water Systems - 1-yr warranty
1 HP Funnel	6/1/2015		Lake Fountain - New 1Hp Fountain Installed	\$1,500.00	· · · · · · · · · · · · · · · · · · ·
I HE I UIIIIEI	6/29/2017		·		Collier Water Systems
	6/29/2017	D2016-	Suplly line cut - splice back together	\$125.00	Conier Water Systems
		9647/2016-			
	3/5/2018	9738	2-36W LED Lights, 2-custom brackets	\$687.00	F.F.
	7/25/2018	2018-9833	new wire, tag lines, deep cleaning,	\$455.00	FF
	8/15/2018	2018-9896	Fountain Pressure Washed	\$175.00	FF
		2016-9864	Fountain Pressure Washed	\$175.00	
		2020-9927	2- 36W Lights Installed		FF 1yr. Warranty on lights
		2020-62744	Fountain Pressure Washed	\$175.00	
1 1 4= 4:	10/16/2020	2020-02744	Fountain Pressure Washeu	\$175.00	rr
Lake 15-Air					Vertex Composted to John 14 9 15 1
					Vertex - Connected to lakes 14 & 15 - 1
					Compressor Cabinet, 1" PVC Pipe,
					Bottomline Tubing - Compressor location
	5/17/2010		1 Diffuser		lake 14
	3/12/2020	2020-9863	1.5hp/230V/1P Pentair motor serial #0001	\$1,295,00	F.F 1-yr warranty
Lake 16	3/11/1010			Ψ = /= 0 0 10 0	= ,,
Lake 10			Lake Fountain - Replace Control Box; 3Hp and 40 Amp		
	E /4 /204 E				
	5/1/2015	ļ	Breaker		Callian Matan C
					Collier Water Systems - 1-yer warranty
	10/16/2015		Fountain Pump & Motor Replacement	\$2,185.00	
	12/15/2015	5557	Float Replacement	\$225.00	Collier Water Systems
	2/27/2018	D2016-9788	5HP/230V/1P motor serial#4SF50-3W2614E1710175	\$3,875.00	
	2,2.,2010		, 11., 1	<del>+3,3,3.30</del>	
	7/25/2010	2018-9833	5HD/220V//1D motor corial#45EE0 2W2614E171017E	Ć2 07F 00	EE-2ur warranty on motor and numn
	<del></del>		5HP/230V/1P motor serial#4SF50-3W2614E1710175		FF-2yr warranty on motor and pump
	8/15/2018	2018-9896	Fountain Pressure Washed	\$175.00	FF
			5hp 230 v 1P motor Serial #2094897104 and 5hp		
	2/19/2019	2019-10410	pump Serial #2061388401		FF 2yr warranty on motor and pump
	3/12/2020	2016-9864	Fountain Pressure Washed	\$175.00	FF
	3/25/2020	2020-9913	Replaced 5HP/230V/1P motor - under warranty	\$500.00	FF - warranty good through 2/19/2021
		2020-62744	Fountain Pressure Washed	\$175.00	
	,,			7-10-00	F1 F
Lake 16 - Air					
Lake 16 - Air					Vertex - Connected to lakes 10. 16 & 17 -
Lake 16 - Air					Vertex - Connected to lakes 10, 16 & 17 -
Lake 16 - Air					1 AirStation, 1 Valve Box, 1" PVC,
Lake 16 - Air					1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location
Lake 16 - Air	5/17/2010		1 Diffuser		1 AirStation, 1 Valve Box, 1" PVC,
Lake 16 - Air	5/17/2010 2/1/2015		Aeration - Fix broken aeration line		1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17
Lake 16 - Air					1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location
Lake 16 - Air			Aeration - Fix broken aeration line		1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17
Lake 16 - Air	2/1/2015		Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower		1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for
Lake 16 - Air	2/1/2015		Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan		1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of
Lake 16 - Air	2/1/2015		Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V		1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for
Lake 16 - Air	2/1/2015 6/12/2018	2018-2525	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) -	\$3,753.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.
Lake 16 - Air	2/1/2015 6/12/2018		Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty		1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.
Lake 16 - Air	2/1/2015 6/12/2018 6/5/2019	2018-2525	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration	\$3,753.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.
	2/1/2015 6/12/2018 6/5/2019	2018-2525	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty	\$3,753.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.
Lake 16 - Air	2/1/2015 6/12/2018 6/5/2019	2018-2525	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor	\$3,753.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.
	2/1/2015 6/12/2018 6/5/2019 2/18/2020	2018-2525 2019-10699 2020-11470	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration	\$3,753.00 \$0.00 \$129.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20
	2/1/2015 6/12/2018 6/5/2019	2018-2525 2019-10699 2020-11470	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor	\$3,753.00 \$0.00 \$129.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.
	2/1/2015 6/12/2018 6/5/2019 2/18/2020	2018-2525 2019-10699 2020-11470	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor	\$3,753.00 \$0.00 \$129.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20
	2/1/2015 6/12/2018 6/5/2019 2/18/2020 7/1/2015	2018-2525 2019-10699 2020-11470	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced	\$3,753.00 \$0.00 \$129.00 \$2,591.85	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included
	2/1/2015 6/12/2018 6/5/2019 2/18/2020	2018-2525 2019-10699 2020-11470	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit	\$3,753.00 \$0.00 \$129.00 \$2,591.85	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20
	2/1/2015 6/12/2018 6/5/2019 2/18/2020 7/1/2015 1/13/2017	2018-2525 2019-10699 2020-11470 5926	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems
	2/1/2015 6/12/2018 6/5/2019 2/18/2020 7/1/2015 1/13/2017 1/29/2018	2018-2525 2019-10699 2020-11470 5926 6228	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for new head due to storm damage	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50 \$1,640.50	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems  Collier Water Systems
	2/1/2015 6/12/2018 6/5/2019 2/18/2020 7/1/2015 1/13/2017 1/29/2018 7/25/2018	2018-2525 2019-10699 2020-11470 5926 6228 2018-9833	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for new head due to storm damage Nozzle, tag lines,	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50 \$1,640.50 \$487.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems  FF
	2/1/2015 6/12/2018 6/5/2019 2/18/2020 7/1/2015 1/13/2017 1/29/2018 7/25/2018	2018-2525 2019-10699 2020-11470 5926 6228	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for new head due to storm damage Nozzle, tag lines, Fountain Pressure Washed	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50 \$1,640.50	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems  FF
	2/1/2015 6/12/2018 6/12/2018 2/18/2020 7/1/2015 1/13/2017 1/29/2018 7/25/2018 8/15/2018	2018-2525 2019-10699 2020-11470 5926 6228 2018-9833 2018-9896	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for new head due to storm damage Nozzle, tag lines, Fountain Pressure Washed 3HP motor serial #2094917907 & 3HP pump serial	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50 \$1,640.50 \$487.00 \$175.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems  FF FF
	2/1/2015 6/12/2018 6/12/2018 2/18/2020 7/1/2015 1/13/2017 1/29/2018 7/25/2018 8/15/2018	2018-2525 2019-10699 2020-11470 5926 6228 2018-9833 2018-9896 2019-10443	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for new head due to storm damage Nozzle, tag lines, Fountain Pressure Washed 3HP motor serial #2094917907 & 3HP pump serial #2076278809	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50 \$1,640.50 \$487.00 \$175.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems  FF FF FF - 2yr warranty
	2/1/2015 6/12/2018 6/12/2018 2/18/2020 7/1/2015 1/13/2017 1/29/2018 7/25/2018 8/15/2018	2018-2525 2019-10699 2020-11470 5926 6228 2018-9833 2018-9896	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for new head due to storm damage Nozzle, tag lines, Fountain Pressure Washed 3HP motor serial #2094917907 & 3HP pump serial	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50 \$1,640.50 \$487.00 \$175.00 \$2,290.00 \$175.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems  FF FF FF - 2yr warranty FF
	2/1/2015 6/12/2018 6/12/2018 6/5/2019 2/18/2020 7/1/2015 1/13/2017 1/29/2018 7/25/2018 8/15/2018 3/5/2019 3/12/2020	2018-2525 2019-10699 2020-11470 5926 6228 2018-9833 2018-9896 2019-10443	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for new head due to storm damage Nozzle, tag lines, Fountain Pressure Washed 3HP motor serial #2094917907 & 3HP pump serial #2076278809	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50 \$1,640.50 \$487.00 \$175.00 \$2,290.00 \$175.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems  FF FF FF - 2yr warranty
	2/1/2015 6/12/2018 6/12/2018 6/5/2019 2/18/2020 7/1/2015 1/13/2017 1/29/2018 7/25/2018 8/15/2018 3/5/2019 3/12/2020 3/27/2020	2018-2525  2019-10699  2020-11470  5926  6228  2018-9833  2018-9896  2019-10443  2016-9864  2020-9928	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for new head due to storm damage Nozzle, tag lines, Fountain Pressure Washed 3HP motor serial #2094917907 & 3HP pump serial #2076278809 Fountain Pressure Washed Replaced 20A & 60A breakers	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50 \$487.00 \$175.00 \$2,290.00 \$175.00 \$82.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems  FF FF FF FF - 2yr warranty FF FF - 30 day warranty
Lake 17 - East	2/1/2015 6/12/2018 6/12/2018 6/5/2019 2/18/2020 7/1/2015 1/13/2017 1/29/2018 7/25/2018 8/15/2018 3/5/2019 3/12/2020 3/27/2020	2018-2525  2019-10699  2020-11470  5926  6228  2018-9833  2018-9896  2019-10443  2016-9864	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for new head due to storm damage Nozzle, tag lines, Fountain Pressure Washed 3HP motor serial #2094917907 & 3HP pump serial #2076278809 Fountain Pressure Washed	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50 \$1,640.50 \$487.00 \$175.00 \$2,290.00 \$175.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems  FF FF FF FF - 2yr warranty FF FF - 30 day warranty
Lake 17 - East	2/1/2015 6/12/2018 6/12/2018 6/5/2019 2/18/2020 7/1/2015 1/13/2017 1/29/2018 7/25/2018 8/15/2018 3/5/2019 3/12/2020 3/27/2020 10/16/2020	2018-2525  2019-10699  2020-11470  5926  6228  2018-9833  2018-9896  2019-10443  2016-9864  2020-9928  2020-62744	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for new head due to storm damage Nozzle, tag lines, Fountain Pressure Washed 3HP motor serial #2094917907 & 3HP pump serial #2076278809 Fountain Pressure Washed Replaced 20A & 60A breakers Fountain Pressure Washed	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50 \$487.00 \$175.00 \$175.00 \$175.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems  FF FF FF - 2yr warranty FF FF - 30 day warranty FF
Lake 17 - East	2/1/2015 6/12/2018 6/12/2018 6/5/2019 2/18/2020 7/1/2015 1/13/2017 1/29/2018 7/25/2018 8/15/2018 3/5/2019 3/12/2020 3/27/2020	2018-2525  2019-10699  2020-11470  5926  6228  2018-9833  2018-9896  2019-10443  2016-9864  2020-9928  2020-62744	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for new head due to storm damage Nozzle, tag lines, Fountain Pressure Washed 3HP motor serial #2094917907 & 3HP pump serial #2076278809 Fountain Pressure Washed Replaced 20A & 60A breakers	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50 \$1,640.50 \$487.00 \$175.00 \$2,290.00 \$175.00 \$82.00 \$175.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems  FF FF FF - 2yr warranty FF FF - 30 day warranty FF FF - 30 representations of the property of
Lake 17 - East	2/1/2015 6/12/2018 6/12/2018 6/5/2019 2/18/2020 7/1/2015 1/13/2017 1/29/2018 7/25/2018 8/15/2019 3/12/2020 3/27/2020 10/16/2020 2/9/2016	2018-2525  2019-10699  2020-11470  5926  6228  2018-9833  2018-9896  2019-10443  2016-9864  2020-9928  2020-62744  5616	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for new head due to storm damage Nozzle, tag lines, Fountain Pressure Washed 3HP motor serial #2094917907 & 3HP pump serial #2076278809 Fountain Pressure Washed Replaced 20A & 60A breakers Fountain Pressure Washed New 5Hp Funnel Fountain Installed	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50 \$487.00 \$175.00 \$175.00 \$175.00 \$175.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems  FF FF FF - 2yr warranty FF FF - 30 day warranty FF FF - 30 day warranty FF FF - 1-yr warranty included F.F 1-yr warranty from date of
Lake 17 - East	2/1/2015 6/12/2018 6/12/2018 6/5/2019 2/18/2020 7/1/2015 1/13/2017 1/29/2018 7/25/2018 8/15/2019 3/12/2020 3/27/2020 10/16/2020 2/9/2016 6/27/2018	2018-2525  2019-10699  2020-11470  5926  6228  2018-9833  2018-9896  2019-10443  2016-9864  2020-9928  2020-62744  5616  2018-9753	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for new head due to storm damage Nozzle, tag lines, Fountain Pressure Washed 3HP motor serial #2094917907 & 3HP pump serial #2076278809 Fountain Pressure Washed Replaced 20A & 60A breakers Fountain Pressure Washed Replaced 3HP/230V/1P motor and 3 HP pump	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50 \$487.00 \$175.00 \$2,290.00 \$175.00 \$82.00 \$175.00 \$175.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems  FF FF FF - 2yr warranty FF FF - 30 day warranty FF FF - 1-yr warranty included F.F 1-yr warranty from date of installation.
Lake 17 - East	2/1/2015 6/12/2018 6/12/2018 6/5/2019 2/18/2020 7/1/2015 1/13/2017 1/29/2018 7/25/2018 8/15/2019 3/12/2020 3/27/2020 10/16/2020 2/9/2016 6/27/2018	2018-2525  2019-10699  2020-11470  5926  6228  2018-9833  2018-9896  2019-10443  2016-9864  2020-9928  2020-62744  5616	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for new head due to storm damage Nozzle, tag lines, Fountain Pressure Washed 3HP motor serial #2094917907 & 3HP pump serial #2076278809 Fountain Pressure Washed Replaced 20A & 60A breakers Fountain Pressure Washed New 5Hp Funnel Fountain Installed	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50 \$487.00 \$175.00 \$2,290.00 \$175.00 \$175.00 \$175.00 \$1,995.00 \$1,995.00 \$100.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems  FF FF FF - 2yr warranty FF FF - 30 day warranty FF FF - 1-yr warranty included F.F 1-yr warranty from date of installation. FF
Lake 17 - East	2/1/2015 6/12/2018 6/12/2018 6/5/2019 2/18/2020 7/1/2015 1/13/2017 1/29/2018 7/25/2018 3/5/2019 3/12/2020 3/27/2020 10/16/2020 2/9/2016 6/27/2018 7/25/2018	2018-2525  2019-10699  2020-11470  5926  6228  2018-9833  2018-9896  2019-10443  2016-9864  2020-9928  2020-62744  5616  2018-9753  2018-9833	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for new head due to storm damage Nozzle, tag lines, Fountain Pressure Washed 3HP motor serial #2094917907 & 3HP pump serial #2076278809 Fountain Pressure Washed Replaced 20A & 60A breakers Fountain Pressure Washed Replaced 3HP/230V/1P motor and 3 HP pump	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50 \$487.00 \$175.00 \$2,290.00 \$175.00 \$82.00 \$175.00 \$1,995.00 \$100.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems  FF FF FF - 2yr warranty FF FF - 30 day warranty FF FF - 1-yr warranty from date of installation. FF F.F 1-yr warranty from date of
Lake 17 - East	2/1/2015 6/12/2018 6/12/2018 6/5/2019 2/18/2020 7/1/2015 1/13/2017 1/29/2018 7/25/2018 3/5/2019 3/12/2020 3/27/2020 10/16/2020 2/9/2016 6/27/2018 7/25/2018	2018-2525  2019-10699  2020-11470  5926  6228  2018-9833  2018-9896  2019-10443  2016-9864  2020-9928  2020-62744  5616  2018-9753	Aeration - Fix broken aeration line Install 2 new 1/2 HP 230V Compressors serial #0518906765 & 0518906766 in cabinets with Blower fan Replaced locked up compressor with new 1/2 HP 230V rocking Piston Compressor (Serial #1018909235) - replaced under warranty warranty replacement 1/2/hp 230 v aeration compressor  Lake Fountain - 2 Fountains - East Fountain motor pump replaced  1 New 3Hp fountain from estimate 1056 - Deposit Final payment for new fountain install - minus cost for new head due to storm damage Nozzle, tag lines, Fountain Pressure Washed 3HP motor serial #2094917907 & 3HP pump serial #2076278809 Fountain Pressure Washed Replaced 20A & 60A breakers Fountain Pressure Washed Replaced 3HP/230V/1P motor and 3 HP pump	\$3,753.00 \$0.00 \$129.00 \$2,591.85 \$1,997.50 \$487.00 \$175.00 \$2,290.00 \$175.00 \$82.00 \$175.00 \$1,995.00 \$100.00	1 AirStation, 1 Valve Box, 1" PVC, Bottomline Tubing - Compressor location lake 17  F.F 1-yr warranty from date of installation. I have asked for confirmation.  FF - warranty expries 6/5/20  1-yr warranty included  Collier Water Systems  FF FF FF - 2yr warranty FF FF - 30 day warranty FF FF - 1-yr warranty included F.F 1-yr warranty from date of installation. FF

		T	Updated 12-9-20		T
Lake #	Date	Invoice #	Service Issue	Cost	Comments
		2018-9896	Fountain Pressure Washed	\$175.00	
	3/12/2020	2016-9864	Fountain Pressure Washed	\$175.00	FF
		2020-62744	Fountain Pressure Washed	\$175.00	
Lake 17 - Air					
					Vertex - Connected to lakes 10, 16 & 17 -
					1 AirStation, 1 Valve Box, 1" PVC,
					Bottomline Tubing - Compressor location
			2 Diffusers		
		D2016-	ב טווועאפוא		lake 17
		9647/2016-	4 1 60 1 2 22216	<b>4.</b>	
	3/5/2018	9/38	1-large filter change - 1-230V fan	\$427.90	F.F.
Lake 18 - East					
			Fountain #1 Replacement. Replaced with 3hp fountain		
			with new control box. 3 Hp 230 volt 1 phase Tornado		Collier Water Systems - 3-yr warranty
	1/25/2016	5594 & 5617	Floating Lake Fountain	\$4,950.00	included
				•	
	7/25/2018	2018-9833	New tag lines, deep cleaning	\$125.00	FF
	6/15/2018	2018-9895	3HP start Box replaced.	\$209.00	FF - 1 yr. warranty
	8/15/2018	2018-9896	Fountain Pressure Washed	\$175.00	F.F.
		2018-10310	replaced 3HP start Box		Under warranty
	, :,=:20			72.30	<u> </u>
			3HP230V1Pmotor Serial#EM4-302301E226839L2018		
	1/22/2010	2019-10333	& 3HPpump Serial#2084952407	¢2 200 00	F.F 2 Yr. warranty
	1/22/2019	2013-10333	α 3111 μαιτιμ σετιαι <del>π</del> 2004332407	32,290.00	ı ~ ∠ ıı. waııdılty
			<u> </u>		
	3/12/2020	2016-9864	Fountain Pressure Washed	\$175.00	FF
			Replaced 3hp/230v/1p motor #2107632102, pump #		
			2112369802 and start box (motor & pump under		FF - fountain warranty expries 1/22/21 -
	4/24/2020	2020-9979	warranty)	\$719.00	1yr. Warranty on start box
		2020-62744	Fountain Pressure Washed	\$175.00	
	10/10/2020	2020 02/44	i Gantain i ressure vvasileu	71/3.00	' '
Lake 10 Mast					
Lake 18 - West					
Lake 18 - West					
Lake 18 - West					Collier Water Systems - 3-yr warranty
Lake 18 - West	3/8/2016		Fountain - Changed to 3 HP Trumpet	\$4,500.00	
Lake 18 - West	3/8/2016		Fountain - Changed to 3 HP Trumpet	\$4,500.00	
Lake 18 - West		D2016-	Fountain - Changed to 3 HP Trumpet	\$4,500.00	
Lake 18 - West		D2016- 9647/2016-	-		included
Lake 18 - West		D2016- 9647/2016-	Fountain - Changed to 3 HP Trumpet  3hp/230V/1P control panel	\$4,500.00 \$1,424.00	included
Lake 18 - West		D2016- 9647/2016-	-		included
Lake 18 - West		D2016- 9647/2016-	-		included
Lake 18 - West	3/5/2018	D2016- 9647/2016-	-	\$1,424.00	included
Lake 18 - West	3/5/2018 7/31/2018	D2016- 9647/2016- 9738 2018-9854	3hp/230V/1P control panel	\$1,424.00	F.F.  FF - 1 yr. warranty
Lake 18 - West	3/5/2018 7/31/2018 8/15/2018	D2016- 9647/2016- 9738 2018-9854 2018-9896	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed	\$1,424.00 \$1,495.00 \$175.00	F.F.  FF - 1 yr. warranty F.F.
Lake 18 - West	3/5/2018 7/31/2018 8/15/2018	D2016- 9647/2016- 9738 2018-9854	3hp/230V/1P control panel 3HP/230V/1P motor Serial #4SF30-3W2614C11156	\$1,424.00 \$1,495.00 \$175.00 \$758.00	F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty
Lake 18 - West	3/5/2018 7/31/2018 8/15/2018 8/23/2018	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811	\$1,424.00 \$1,495.00 \$175.00 \$758.00	F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor
Lake 18 - West	3/5/2018 7/31/2018 8/15/2018 8/23/2018 7/22/2019	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00	F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only.
Lake 18 - West	3/5/2018 7/31/2018 8/15/2018 8/23/2018 7/22/2019 3/12/2020	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00	F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF
	3/5/2018 7/31/2018 8/15/2018 8/23/2018 7/22/2019 3/12/2020	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00	F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF
Lake 18 - West	3/5/2018 7/31/2018 8/15/2018 8/23/2018 7/22/2019 3/12/2020	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00	F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FF Compressor runs 18/19
	3/5/2018 7/31/2018 8/15/2018 8/23/2018 7/22/2019 3/12/2020	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00	F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FF Compressor runs 18/19 Vertex - Connected to lakes 18 & 19 - 2
	3/5/2018 7/31/2018 8/15/2018 8/23/2018 7/22/2019 3/12/2020	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00	included  F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FF Compressor runs 18/19 Vertex - Connected to lakes 18 & 19 - 2 Air Stations, Bottomline Tubing -
	3/5/2018 7/31/2018 8/15/2018 8/23/2018 7/22/2019 3/12/2020	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00	F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FF Compressor runs 18/19 Vertex - Connected to lakes 18 & 19 - 2
	3/5/2018 7/31/2018 8/15/2018 8/23/2018 7/22/2019 3/12/2020 10/16/2020	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00	included  F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FF Compressor runs 18/19 Vertex - Connected to lakes 18 & 19 - 2 Air Stations, Bottomline Tubing -
	3/5/2018 7/31/2018 8/15/2018 8/23/2018 7/22/2019 3/12/2020 10/16/2020	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00	included  F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF  FF  Compressor runs 18/19  Vertex - Connected to lakes 18 & 19 - 2  Air Stations, Bottomline Tubing -  Compressor location lake 18
	3/5/2018  7/31/2018 8/15/2018 8/23/2018  7/22/2019 3/12/2020 10/16/2020  5/17/2010  11/3/2016	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed 2 Diffusers 2 1/2hp 110V compressors & Composite Enclosures	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00 \$175.00	included  F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FF Compressor runs 18/19 Vertex - Connected to lakes 18 & 19 - 2 Air Stations, Bottomline Tubing - Compressor location lake 18
	3/5/2018  7/31/2018 8/15/2018 8/23/2018  7/22/2019 3/12/2020 10/16/2020  5/17/2010  11/3/2016	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed 2 Diffusers	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00 \$175.00	included  F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF  FF  Compressor runs 18/19  Vertex - Connected to lakes 18 & 19 - 2  Air Stations, Bottomline Tubing -  Compressor location lake 18
	3/5/2018  7/31/2018 8/15/2018 8/23/2018  7/22/2019 3/12/2020 10/16/2020  5/17/2010 11/3/2016 12/20/2017	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744 5882 D2016-9647	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed  2 Diffusers  2 1/2hp 110V compressors & Composite Enclosures new 3HP/230V/1P control panel	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00 \$175.00 \$175.00	F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FC Compressor runs 18/19 Vertex - Connected to lakes 18 & 19 - 2 Air Stations, Bottomline Tubing - Compressor location lake 18  FF deposit
	3/5/2018  7/31/2018 8/15/2018 8/23/2018  7/22/2019 3/12/2020 10/16/2020  5/17/2010 11/3/2016 12/20/2017	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744 5882 D2016-9647	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed 2 Diffusers 2 1/2hp 110V compressors & Composite Enclosures new 3HP/230V/1P control panel 2-115V 1/2HP compressors planned to be installed	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00 \$175.00 \$175.00 \$1,223.50	included  F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FF Compressor runs 18/19 Vertex - Connected to lakes 18 & 19 - 2 Air Stations, Bottomline Tubing - Compressor location lake 18  FF deposit  FF deposit
	3/5/2018  7/31/2018 8/15/2018 8/23/2018  7/22/2019 3/12/2020 10/16/2020  5/17/2010 11/3/2016 12/20/2017	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744 5882 D2016-9647	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed  2 Diffusers  2 1/2hp 110V compressors & Composite Enclosures new 3HP/230V/1P control panel	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00 \$175.00 \$175.00 \$1,223.50	F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FC Compressor runs 18/19 Vertex - Connected to lakes 18 & 19 - 2 Air Stations, Bottomline Tubing - Compressor location lake 18  FF deposit
	3/5/2018  7/31/2018 8/15/2018 8/23/2018  7/22/2019 3/12/2020 10/16/2020  5/17/2010 11/3/2016 12/20/2017 12/20/2017 3/5/2018	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744 5882 D2016-9647 D2016-9647 2016-9738	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed  2 Diffusers  2 1/2hp 110V compressors & Composite Enclosures new 3HP/230V/1P control panel  2-115V 1/2HP compressors planned to be installed new 3HP/230V/1P control panel	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00 \$175.00 \$175.00 \$175.00 \$712.00	included  F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FF Compressor runs 18/19 Vertex - Connected to lakes 18 & 19 - 2 Air Stations, Bottomline Tubing - Compressor location lake 18  FF deposit FF deposit FF - Final payment
	3/5/2018  7/31/2018 8/15/2018 8/23/2018  7/22/2019 3/12/2020 10/16/2020  5/17/2010 11/3/2016 12/20/2017 12/20/2017 3/5/2018	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744 5882 D2016-9647	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed 2 Diffusers 2 1/2hp 110V compressors & Composite Enclosures new 3HP/230V/1P control panel 2-115V 1/2HP compressors planned to be installed	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00 \$175.00 \$175.00 \$175.00 \$712.00	included  F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FF  Compressor runs 18/19 Vertex - Connected to lakes 18 & 19 - 2 Air Stations, Bottomline Tubing - Compressor location lake 18  FF deposit FF - Final payment  FF - Final payment
	3/5/2018  7/31/2018 8/15/2018 8/23/2018  7/22/2019 3/12/2020 10/16/2020  5/17/2010 11/3/2016 12/20/2017 12/20/2017 3/5/2018	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744 5882 D2016-9647 D2016-9647 2016-9738	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed  2 Diffusers  2 1/2hp 110V compressors & Composite Enclosures new 3HP/230V/1P control panel  2-115V 1/2HP compressors planned to be installed new 3HP/230V/1P control panel	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00 \$175.00 \$175.00 \$175.00 \$712.00 \$712.00	included  F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FF Compressor runs 18/19 Vertex - Connected to lakes 18 & 19 - 2 Air Stations, Bottomline Tubing - Compressor location lake 18  FF deposit FF - Final payment FF - Final payment sent back to FF on 7/20 informing them
	3/5/2018  7/31/2018 8/15/2018 8/23/2018  7/22/2019 3/12/2020 10/16/2020  5/17/2010 11/3/2016 12/20/2017 12/20/2017 3/5/2018	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744 5882 D2016-9647 D2016-9647 2016-9738	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed  2 Diffusers  2 1/2hp 110V compressors & Composite Enclosures new 3HP/230V/1P control panel  2-115V 1/2HP compressors planned to be installed new 3HP/230V/1P control panel	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00 \$175.00 \$175.00 \$175.00 \$712.00 \$712.00	included  F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF  FF  Compressor runs 18/19  Vertex - Connected to lakes 18 & 19 - 2  Air Stations, Bottomline Tubing -  Compressor location lake 18  FF deposit FF - Final payment  FF - Final payment  sent back to FF on 7/20 informing them invoice 2016-9738 actually installed 1-
	3/5/2018  7/31/2018 8/15/2018 8/23/2018  7/22/2019 3/12/2020 10/16/2020  5/17/2010 11/3/2016 12/20/2017 12/20/2017 3/5/2018	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744 5882 D2016-9647 D2016-9647 2016-9738	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed  2 Diffusers  2 1/2hp 110V compressors & Composite Enclosures new 3HP/230V/1P control panel  2-115V 1/2HP compressors planned to be installed new 3HP/230V/1P control panel	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00 \$175.00 \$175.00 \$175.00 \$712.00 \$712.00	included  F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FF Compressor runs 18/19 Vertex - Connected to lakes 18 & 19 - 2 Air Stations, Bottomline Tubing - Compressor location lake 18  FF deposit FF - Final payment FF - Final payment sent back to FF on 7/20 informing them
	3/5/2018  7/31/2018 8/15/2018 8/23/2018  7/22/2019 3/12/2020 10/16/2020  5/17/2010 11/3/2016 12/20/2017 12/20/2017 3/5/2018 3/5/2018	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744 5882 D2016-9647 D2016-9647 2016-9738	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed  2 Diffusers  2 1/2hp 110V compressors & Composite Enclosures new 3HP/230V/1P control panel  2-115V 1/2HP compressors planned to be installed new 3HP/230V/1P control panel	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00 \$175.00 \$175.00 \$175.00 \$712.00 \$712.00	included  F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FF Compressor runs 18/19 Vertex - Connected to lakes 18 & 19 - 2 Air Stations, Bottomline Tubing - Compressor location lake 18  FF deposit FF - Final payment FF - Final payment sent back to FF on 7/20 informing them invoice 2016-9738 actually installed 1-3/4hp compressor and need a revised
	3/5/2018  7/31/2018 8/15/2018 8/23/2018  7/22/2019 3/12/2020 10/16/2020  5/17/2010 11/3/2016 12/20/2017 12/20/2017 3/5/2018  3/5/2018	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744 5882 D2016-9647 D2016-9647 2016-9738	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed  2 Diffusers  2 1/2hp 110V compressors & Composite Enclosures new 3HP/230V/1P control panel  2-115V 1/2HP compressors planned to be installed new 3HP/230V/1P control panel  Actually replaced with 1 - 3/4hp compressor instead	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00 \$175.00 \$175.00 \$175.00 \$712.00 \$712.00	included  F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FF  Compressor runs 18/19 Vertex - Connected to lakes 18 & 19 - 2 Air Stations, Bottomline Tubing - Compressor location lake 18  FF deposit FF - Final payment FF - Final payment  FF - Final payment sent back to FF on 7/20 informing them invoice 2016-9738 actually installed 1-3/4hp compressor and need a revised propsal
	3/5/2018  7/31/2018 8/15/2018 8/23/2018  7/22/2019 3/12/2020 10/16/2020  5/17/2010 11/3/2016 12/20/2017 12/20/2017 3/5/2018 3/5/2018	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744 5882 D2016-9647 D2016-9647 2016-9738	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed  2 Diffusers  2 1/2hp 110V compressors & Composite Enclosures new 3HP/230V/1P control panel  2-115V 1/2HP compressors planned to be installed new 3HP/230V/1P control panel  Actually replaced with 1 - 3/4hp compressor instead  received proposal for 1/2hp compressor received proposal for 3/4 hp compressor	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00 \$175.00 \$175.00 \$175.00 \$175.00 \$712.00 \$1,223.50 \$712.00	included  F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FF Compressor runs 18/19 Vertex - Connected to lakes 18 & 19 - 2 Air Stations, Bottomline Tubing - Compressor location lake 18  FF deposit FF - Final payment FF - Final payment  FF - Final payment sent back to FF on 7/20 informing them invoice 2016-9738 actually installed 1-3/4hp compressor and need a revised propsal Sent approval on 7/22/20
	3/5/2018  7/31/2018 8/15/2018 8/15/2018 7/22/2019 3/12/2020 10/16/2020  5/17/2010  11/3/2016 12/20/2017 12/20/2017 3/5/2018  7/16/2020 7/20/2020	D2016- 9647/2016- 9738 2018-9854 2018-9896 2018-9916 2019-10819 2016-9864 2020-62744 5882 D2016-9647 D2016-9647 2016-9738	3hp/230V/1P control panel  3HP/230V/1P motor Serial #4SF30-3W2614C11156 Fountain Pressure Washed New 3Hp pump serial #31701811  Replaced 3HP/230V/1P moter Serial #2105772905 Fountain Pressure Washed Fountain Pressure Washed  2 Diffusers  2 1/2hp 110V compressors & Composite Enclosures new 3HP/230V/1P control panel  2-115V 1/2HP compressors planned to be installed new 3HP/230V/1P control panel  Actually replaced with 1 - 3/4hp compressor instead	\$1,424.00 \$1,495.00 \$175.00 \$758.00 \$500.00 \$175.00 \$175.00 \$175.00 \$175.00 \$712.00 \$712.00 \$500.50	included  F.F.  FF - 1 yr. warranty F.F.  FF - 1yr warranty FF - remainder of 1 yr warranty labor charge only. FF FF  Compressor runs 18/19 Vertex - Connected to lakes 18 & 19 - 2 Air Stations, Bottomline Tubing - Compressor location lake 18  FF deposit FF - Final payment FF - Final payment  FF - Final payment sent back to FF on 7/20 informing them invoice 2016-9738 actually installed 1-3/4hp compressor and need a revised propsal

	Ť		Updated 12-9-20		
Lake #	Date	Invoice #	Service Issue	Cost	Comments
Lake 19					
			Lake Fountain - Replace 3 Hp fountain motor and		
3 HP Funnel	5/1/2015		pump shaft		1-yr warranty included
3 <u>a</u> e.		2018-9896	Fountain Pressure Washed	\$175.00	
	0/13/2010	2010-3030	Submersible 3HP 230V 1P motor Serial #4SF30-	\$175.00	1.1.
			3W261411711618 with stainless steel pump Serial		
		2019-10409	#31700695		FF - 2 yr warranty on motor and pump
	7/22/2019	2019-10819	Replaced 3HP start box	\$209.00	FF - 1yr warranty
	3/12/2020	2016-9864	Fountain Pressure Washed	\$175.00	FF
		2020-62744	Fountain Pressure Washed	\$175.00	
Lake 19 - Air	10/10/2020	2020 027 11	- Carrent Fredoute Fredoue	<b>\$275.00</b>	
Lake 13 - All					Vertex - Connected to lakes 18 & 19 - 2
					Air Stations, Bottomline Tubing -
	5/17/2010		2 Diffusers		Compressor location lake 18
	9/17/2018	2018-9988	cut out roots installed portions of new air lines	\$715.00	FF - 1yr warranty
	4/1/2019	2019-10516	air leak found. repaired air lines	\$39.00	FF - 1yr warranty
Lake 20 - Air	, ,			, , , , ,	, , , ,
Lunc 20 All					Vertex - Connected to lakes 20, 21, 22 &
			l		23 -1 AirStation, 1" PVC Pipe -
	5/17/2010		1 Diffuser		Compressor location lake 23
Lake 21 - North					
5 HP Funnel	10/16/2015	5499	Ballast Replacement	\$1,050.00	
	2, 22, 22	1	- P	, 1,111.00	Collier Water Systems - 3-yr warranty
2 HD Trumpot	3/8/2016		Fountain - Changed to 3 HP	\$4,500.00	
3 HP Trumpet					
		2018-9833	Replaced start relay	\$1,022.00	
		2018-9896	Fountain Pressure Washed	\$175.00	
	3/12/2020	2016-9864	Fountain Pressure Washed	\$175.00	FF
	8/3/2020		Reported to FF the fountain was not working		
	-,-,-				
			installed 3hp 230v/1p motor serial# 2119332904 &		
	0/24/2020	2020 52500		42.674.00	· · · ·
		2020-62608	3hp 230/gpm pump serial# 2117916405		FF - 2yr warranty motor and pump
	10/16/2020	2020-62744	Fountain Pressure Washed	\$175.00	FF
Lake 21 - South					
	2/1/2015		Lake Fountain - Replace lake fountain run capacitor.	\$282.00	
			Lake Fountain - Fountain "B" Repair - Replaced TLS	7-0	
	4/21/2015		Control Bucket for Pump	\$559.13	
	4/21/2013		Control Bucket for Fullip	\$339.13	C-III:
					Collier Water Systems - 3-yr warranty
3 HP Trumpet	6/14/2016	5732 & 5785	Fountain - Changed to 3 HP	\$4,250.00	included
	7/25/2018	2018-9833	Replaced start box	\$1,102.00	FF
	8/15/2018	2018-9896	Fountain Pressure Washed	\$175.00	F.F.
		2016-9864	Fountain Pressure Washed	\$175.00	
		2020-62744	Fountain Pressure Washed	\$175.00	
Lake 21 - Air	10/10/2020	2020-02744	Todittaiii i ressure wasiied	\$175.00	<u> </u>
Lake 21 - All					Vertex Connected to lakes 20, 21, 22, 9
					Vertex - Connected to lakes 20, 21, 22 &
					23 -1 AirStation, 1" PVC Pipe -
	5/17/2010	<u> </u>	2 Diffusers		Compressor location lake 23
Lake 22 - A(West)					
,,					
	7/12/2017	EUUE.	Deposit Invoice New 3 HP Fountain 3 phase/230 V	\$1 007 FA	Collier Water Systems
					, , , , , , , , , , , , , , , , , , ,
	10/12/2017		Final payment for project above		Collier Water Systems
		2018-9833	5hp 230 v 3P motor pump , timer - deposit	\$1,234.50	
	8/15/2018	2018-9896	Fountain Pressure Washed	\$175.00	F.F.
			Replaced 5hp/230V/3P motor		
	8/23/2018	2018-9917	serial#MH48740/E226839 - final payment	\$1,595.00	FF - 1yr warranty
	8/31/2018	2018-9947	Replaced timer		FF - 1yr warranty
	0,01,2010			Ç143.00	
	5/16/2019	2019-10637	now Ehn/2201//2D motor, Johan shares and	\$500	FF 1 vr. Warranty on replacement restar
	6/46/55	2046 226	new 5hp/230V/3P motor - labor charge only	A.==	FF-1yr. Warranty on replacement motor
		2016-9864	Fountain Pressure Washed	\$175.00	FF
	8/3/2020		reported to FF the fountain was pulsating		
	9/26/2020		observed fountain no longer pulsating		item resolved
		2020-62744	Fountain Pressure Washed	\$175.00	
Lake 22 - B(East)	2, 22, 2020			+2.5.50	
Lune ZZ - D(Last)					
			Laba Farmatain #2 Fl		Callian Matan Control
			Lake Fountain #2 - 5hp motor replacement & pump		Collier Water Systems -1-yr warranty on
5 HP Funnel	9/22/2015	5463	shaft with props	\$2,591.85	pump parts & new submersible motor
					Collier Water Systems -Sold at cost to
	9/22/2015	5464	Lake Fountain #8 3-2 Submersible lake wire - 350ft	\$602.00	Vasari-CDD
	. ,,,			+ 302.00	

			Updated 12-9-20		
Lake #	Date	Invoice #	Service Issue	Cost	Comments
					Collier Water Systems -3-yr warranty
	11/10/2015	5538	New Fountain Replacement-New 5 Hp Trumpet	\$5,879.22	included
	3/5/2018	D2016-9647	Pressure washin deposit	\$137.50	not completed as of 3/5/18
	5/29/2018	2016-9939	New Control Panel, motor, pump 5hp 203V 3p	\$4,067.00	all warrantied for 1 yr. per Steven Rhoad
	8/15/2018	2018-9896	Fountain Pressure Washed	\$175.00	F.F.
	3/12/2020	2016-9864	Fountain Pressure Washed	\$175.00	FF
		2020-9974	Installed new %HP/230V/3PH motor and pump	\$2,490.00	FF - I yr. warranty
	10/16/2020	2020-62744	Fountain Pressure Washed	\$175.00	FF
Lake 22 - Air					
					Vertex - Connected to lakes 20, 21, 22 & 23 -1 AirStation, 1" PVC Pipe -
	5/17/2010		2 Diffusers		Compressor location lake 23
Lake 23	3/17/2010		2 Diffuscis		compressor location take 25
20110 20					Collier Water Systems -3-yr warranty
5 HP Funnel	3/27/2015		Lake Fountain - New 5Hp Lake Fountain	\$9,717.00	
5 ue.	3/27/2014		Lake Fountain - Panel credit	(\$935.00)	
	3/2//2021		and rounding range of care	(\$555.55)	Collier Water Systems -1-yr warranty
	2/17/2015		Installation of Control Panel	\$1,828.00	, , , , , , , , , , , , , , , , , , , ,
	2/27/2018	D2016-9788	50% payment breaker replacement by electrician	\$197.50	FF
			50% payment pump serial #318014048, 2" fan nozzle,		
	2/27/2018	D2016-9788	300' of tag line, control panel	\$2,467.50	FF
	_			_	
	7/25/2018	2018-9833	50% payment breaker replacement by electrician 50% payment pump serial #318014048, 2" fan nozzle,	\$197.50	FF
	7/25/2018	2018-9833	300' of tag line, control panel	\$2.467.50	FF - 2 yr warranty on motor and pump
		2018-9896	Fountain Pressure Washed	\$175.00	
	11/30/2018		Installed new 3 phase fused disconnect		FF - 1yr warranty
		2016-9864	Fountain Pressure Washed	\$175.00	
		2020-11279	Installed new 5HP 230V 3P Motor Serial # 2100955504		FF - 2yr warranty
		2020-62744	Fountain Pressure Washed	\$175.00	
	10/10/2020	2020 02711	Toditali Tressare Washea	<b>Ϋ173.00</b>	
Lake 23 - Air					
Lake 23 - Air					Vertex - Connected to lakes 20, 21, 22 &
Lake 23 - Air					Vertex - Connected to lakes 20, 21, 22 & 23 -1 AirStation, 1" PVC Pipe
Lake 23 - Air	5/17/2010		1 Diffuser		23 -1 AirStation, 1" PVC Pipe -
Lake 23 - Air	5/17/2010		1 Diffuser 110 Volt 1/2 hp Rocking Piston Compressor		23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23
Lake 23 - Air			110 Volt 1/2 hp Rocking Piston Compressor		23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced
Lake 23 - Air	5/17/2010 3/27/2017				23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23
Lake 23 - Air	3/27/2017	6003	110 Volt 1/2 hp Rocking Piston Compressor Replacement	\$965.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3
Lake 23 - Air	3/27/2017 10/1/2018	6003	110 Volt 1/2 hp Rocking Piston Compressor Replacement 1 ea. 30A fuse, 1 ea. Manifold rebuild kit	\$965.00 \$59.90	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild
Lake 23 - Air	3/27/2017 10/1/2018	6003	110 Volt 1/2 hp Rocking Piston Compressor Replacement	\$965.00 \$59.90 \$79.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3
	3/27/2017 10/1/2018 1/15/2019	6003 2018-10022 2018-10310	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold	\$965.00 \$59.90 \$79.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been
Lake 24 - Bubbler	3/27/2017 10/1/2018 1/15/2019	6003	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold removed Bubbler from lake #24	\$965.00 \$59.90 \$79.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty
	3/27/2017 10/1/2018 1/15/2019	6003 2018-10022 2018-10310	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold	\$965.00 \$59.90 \$79.00 \$258.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been
Lake 24 - Bubbler Lake 24 - East	3/27/2017 10/1/2018 1/15/2019 6/1/2018	6003 2018-10022 2018-10310 2018-2525	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain	\$965.00 \$59.90 \$79.00 \$258.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty
Lake 24 - Bubbler	3/27/2017 10/1/2018 1/15/2019 6/1/2018 3/1/2015	6003 2018-10022 2018-10310 2018-2525	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain	\$965.00 \$59.90 \$79.00 \$258.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included
Lake 24 - Bubbler Lake 24 - East	3/27/2017 10/1/2018 1/15/2019 6/1/2018 3/1/2015 1/1/2016	6003 2018-10022 2018-10310 2018-2525	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems
Lake 24 - Bubbler Lake 24 - East	3/27/2017 10/1/2018 1/15/2019 6/1/2018 3/1/2015 1/1/2016 3/23/2018	6003 2018-10022 2018-10310 2018-2525	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains
Lake 24 - Bubbler Lake 24 - East	3/27/2017 10/1/2018 1/15/2019 6/1/2018 3/1/2015 1/1/2016 3/23/2018 2/27/2018	6003 2018-10022 2018-10310 2018-2525 D2016-9788	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle new 5HP/460V/3P motor	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF
Lake 24 - Bubbler Lake 24 - East	3/27/2017 10/1/2018 1/15/2019 6/1/2018 3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018	6003 2018-10022 2018-10310 2018-2525  D2016-9788 2018-9833	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24 Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle new 5HP/460V/3P motor new 5HP/460V/3P motor	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50 \$2,842.50	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump
Lake 24 - Bubbler Lake 24 - East	3/27/2017 10/1/2018 1/15/2019 6/1/2018 3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018	6003 2018-10022 2018-10310 2018-2525 D2016-9788	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24 Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle new 5HP/460V/3P motor fountain Pressure Washed	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump
Lake 24 - Bubbler Lake 24 - East	3/27/2017 10/1/2018 1/15/2019 6/1/2018 3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018 8/15/2018	6003 2018-10022 2018-10310 2018-2525 D2016-9788 2018-9833 2018-9896	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced. Replace 2" Fan Nozzle new 5HP/460V/3P motor fountain Pressure Washed new 5HP/460V/3P motor (serial # 210296605) Installed under warranty	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50 \$2,842.50 \$175.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump F.F.
Lake 24 - Bubbler Lake 24 - East	3/27/2017 10/1/2018 1/15/2019 6/1/2018 3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018 8/15/2018 4/26/2019	6003 2018-10022 2018-10310 2018-2525  D2016-9788 2018-9833 2018-9896 2019-10573	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle new 5HP/460V/3P motor new 5HP/460V/3P motor  Fountain Pressure Washed new 5HP/460V/3P motor (serial # 210296605) Installed under warranty good through 7/25/2020	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50 \$2,842.50 \$175.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump F.F. FF - see comments for warranty
Lake 24 - Bubbler Lake 24 - East	3/27/2017  10/1/2018 1/15/2019 6/1/2018  3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018 8/15/2018 4/26/2019 5/17/2019	2018-10022 2018-10310 2018-2525 2018-2525 2018-9888 2018-9896 2019-10573 2019-10647	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced. Replace 2" Fan Nozzle new 5HP/460V/3P motor fountain Pressure Washed new 5HP/460V/3P motor (serial # 210296605) Installed under warranty	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50 \$175.00 \$500.00 \$816.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump F.F.  FF - see comments for warranty FF - 1yr. Warranty on lights
Lake 24 - Bubbler Lake 24 - East	3/27/2017  10/1/2018 1/15/2019 6/1/2018  3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018 8/15/2018 4/26/2019 5/17/2019 9/30/2019	2018-10022 2018-10310 2018-2525 2018-2525 2018-988 2018-9833 2018-9896 2019-10573 2019-10647 2019-11023	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle new 5HP/460V/3P motor new 5HP/460V/3P motor Fountain Pressure Washed new 5HP/460V/3P motor (serial # 210296005) Installed under warranty good through 7/25/2020 installed 3 36W LED lights installed new step down transformer 3KVA 480V to 120V outdoor transformer	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50 \$175.00 \$500.00 \$816.00 \$1,429.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump F.F.  FF - see comments for warranty FF - 1yr. Warranty on lights
Lake 24 - Bubbler Lake 24 - East	3/27/2017  10/1/2018 1/15/2019 6/1/2018  3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018 8/15/2018 4/26/2019 5/17/2019 9/30/2019	2018-10022 2018-10310 2018-2525 2018-2525 2018-9888 2018-9896 2019-10573 2019-10647	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle new 5HP/460V/3P motor new 5HP/460V/3P motor  Fountain Pressure Washed new 5HP/460V/3P motor (serial # 210296605) Installed under warranty good through 7/25/2020 installed 3 36W LED lights installed new step down transformer 3KVA 480V to 120V outdoor	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50 \$175.00 \$500.00 \$816.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump F.F.  FF - see comments for warranty FF - 1yr. Warranty on lights
Lake 24 - Bubbler Lake 24 - East	3/27/2017  10/1/2018 1/15/2019 6/1/2018  3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018 8/15/2018 4/26/2019 5/17/2019 9/30/2019 3/12/2020	2018-10022 2018-10310 2018-2525 2018-2525 2018-9833 2018-9896 2019-10573 2019-10647 2019-11023 2016-9864	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle new 5HP/460V/3P motor new 5HP/460V/3P motor Fountain Pressure Washed new 5HP/460V/3P motor (serial # 210296605) Installed under warranty good through 7/25/2020 installed 3 36W LED lights installed new step down transformer 3KVA 480V to 120V outdoor transformer Fountain Pressure Washed	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50 \$175.00 \$816.00 \$1,429.00 \$175.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump F.F.  FF - see comments for warranty FF - 1yr. Warranty on lights
Lake 24 - Bubbler Lake 24 - East	3/27/2017  10/1/2018 1/15/2019 6/1/2018  3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018 8/15/2018 4/26/2019 5/17/2019 9/30/2019 3/12/2020 4/15/2020	6003 2018-10022 2018-10310 2018-2525  D2016-9788 2018-9896 2019-10573 2019-10647 2019-11023 2016-9864 2020-1325	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle new 5HP/460V/3P motor new 5HP/460V/3P motor  Fountain Pressure Washed new 5HP/460V/3P motor (serial # 210296605) Installed under warranty good through 7/25/2020 installed 3 36W LED lights installed new step down transformer 3KVA 480V to 120V outdoor transformer Fountain Pressure Washed install new 5HP/460V/3PH motor	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50 \$175.00 \$816.00 \$1,429.00 \$175.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump F.F.  FF - see comments for warranty FF - 1yr. Warranty on lights  FF
Lake 24 - Bubbler Lake 24 - East	3/27/2017  10/1/2018 1/15/2019 6/1/2018  3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018 8/15/2018 4/26/2019 5/17/2019 9/30/2019 3/12/2020 4/15/2020	2018-10022 2018-10310 2018-2525 2018-2525 2018-9833 2018-9896 2019-10573 2019-10647 2019-11023 2016-9864	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle new 5HP/460V/3P motor new 5HP/460V/3P motor Fountain Pressure Washed new 5HP/460V/3P motor (serial # 210296605) Installed under warranty good through 7/25/2020 installed 3 36W LED lights installed new step down transformer 3KVA 480V to 120V outdoor transformer Fountain Pressure Washed	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50 \$175.00 \$816.00 \$1,429.00 \$175.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump F.F.  FF - see comments for warranty FF - 1yr. Warranty on lights
Lake 24 - Bubbler Lake 24 - East	3/27/2017  10/1/2018 1/15/2019 6/1/2018  3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018 8/15/2019 5/17/2019 9/30/2019 3/12/2020 4/15/2020	6003 2018-10022 2018-10310 2018-2525  D2016-9788 2018-9896 2019-10573 2019-10647 2019-11023 2016-9864 2020-1325	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle new 5HP/460V/3P motor new 5HP/460V/3P motor  Fountain Pressure Washed new 5HP/460V/3P motor (serial # 210296605) Installed under warranty good through 7/25/2020 installed 3 36W LED lights installed new step down transformer 3KVA 480V to 120V outdoor transformer Fountain Pressure Washed install new 5HP/460V/3PH motor	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50 \$175.00 \$816.00 \$1,429.00 \$175.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump F.F. FF - see comments for warranty FF - 1yr. Warranty on lights  FF FF - warranty still good through 7/25/20 FF - Warranty 100 days
Lake 24 - Bubbler Lake 24 - East	3/27/2017  10/1/2018 1/15/2019 6/1/2018  3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018 8/15/2019 5/17/2019 9/30/2019 3/12/2020 4/15/2020	6003 2018-10022 2018-10310 2018-2525  D2016-9788 2018-9833 2018-9896 2019-10573 2019-10647 2019-11023 2016-9864 2020-1325 2020-11426	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle new 5HP/460V/3P motor rew 5HP/460V/3P motor Fountain Pressure Washed new 5HP/460V/3P motor (serial # 210296605) Installed under warranty good through 7/25/2020 installed 3 36W LED lights installed new step down transformer 3KVA 480V to 120V outdoor transformer Fountain Pressure Washed install new 5HP/460V/3PH motor Thermal Overload replaced	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50 \$175.00 \$500.00 \$1,429.00 \$175.00 \$500.00 \$328.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump F.F. FF - see comments for warranty FF - 1yr. Warranty on lights  FF FF - warranty still good through 7/25/20 FF - Warranty 100 days
Lake 24 - Bubbler Lake 24 - East 5 HP TriTier	3/27/2017  10/1/2018 1/15/2019 6/1/2018  3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018 8/15/2019 5/17/2019 9/30/2019 3/12/2020 4/15/2020	6003 2018-10022 2018-10310 2018-2525  D2016-9788 2018-9833 2018-9896 2019-10573 2019-10647 2019-11023 2016-9864 2020-1325 2020-11426	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle new 5HP/460V/3P motor rew 5HP/460V/3P motor Fountain Pressure Washed new 5HP/460V/3P motor (serial # 210296605) Installed under warranty good through 7/25/2020 installed 3 36W LED lights installed new step down transformer 3KVA 480V to 120V outdoor transformer Fountain Pressure Washed install new 5HP/460V/3PH motor Thermal Overload replaced	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50 \$175.00 \$1,429.00 \$1,429.00 \$175.00 \$500.00 \$1,429.00 \$175.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump F.F. FF - see comments for warranty FF - 1yr. Warranty on lights  FF FF - warranty still good through 7/25/20 FF - Warranty 100 days
Lake 24 - Bubbler Lake 24 - East 5 HP TriTier	3/27/2017  10/1/2018 1/15/2019 6/1/2018  3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018 8/15/2019 5/17/2019 9/30/2019 3/12/2020 4/15/2020 10/16/2020	6003 2018-10022 2018-10310 2018-2525  D2016-9788 2018-9833 2018-9896 2019-10573 2019-10647 2019-11023 2016-9864 2020-1325 2020-11426	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle new 5HP/460V/3P motor rew 5HP/460V/3P motor Fountain Pressure Washed new 5HP/460V/3P motor (serial # 210296605) Installed under warranty good through 7/25/2020 installed 3 36W LED lights installed new step down transformer 3KVA 480V to 120V outdoor transformer Fountain Pressure Washed install new 5HP/460V/3PH motor Thermal Overload replaced	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50 \$175.00 \$175.00 \$1,429.00 \$175.00 \$328.00 \$175.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump F.F.  FF - see comments for warranty FF - 1yr. Warranty on lights  FF FF - warranty still good through 7/25/20 FF - Warranty 100 days FF Collier Water Systems? - 3-yr warranty
Lake 24 - Bubbler Lake 24 - East  5 HP TriTier	3/27/2017  10/1/2018 1/15/2019 6/1/2018  3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018 8/15/2018 4/26/2019 5/17/2019 9/30/2019 3/12/2020 4/15/2020 10/16/2020  8/9/2016	6003  2018-10022 2018-10310  2018-2525  D2016-9788 2018-9833 2018-9896  2019-10573 2019-10647 2019-11023 2016-9864  2020-1325 2020-11426 2020-62744	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle  new 5HP/460V/3P motor  rew 5HP/460V/3P motor  Fountain Pressure Washed  new 5HP/460V/3P motor (serial # 210296605) Installed under warranty good through 7/25/2020  installed 3 36W LED lights  installed new step down transformer 3KVA 480V to 120V outdoor transformer  Fountain Pressure Washed  install new 5HP/460V/3PH motor  Thermal Overload replaced Fountain Pressure Washed	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50 \$175.00 \$175.00 \$1,429.00 \$175.00 \$328.00 \$175.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump F.F.  FF - see comments for warranty FF - 1yr. Warranty on lights  FF FF - warranty still good through 7/25/20 FF - Warranty 100 days FF  Collier Water Systems? - 3-yr warranty included
Lake 24 - Bubbler Lake 24 - East  5 HP TriTier	3/27/2017  10/1/2018 1/15/2019 6/1/2018  3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018 8/15/2018 4/26/2019 5/17/2019 9/30/2019 3/12/2020 4/15/2020 2/12/2020 10/16/2020 8/9/2016 8/15/2018	6003  2018-10022 2018-10310  2018-2525  D2016-9788 2018-9833 2018-9896  2019-10573 2019-10647 2019-11023 2016-9864  2020-1325 2020-11426 2020-62744  5788 & 5838 2018-9896	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24 Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle new 5HP/460V/3P motor  Fountain Pressure Washed new 5HP/460V/3P motor (serial # 210296605) Installed under warranty good through 7/25/2020 installed a 3 36W LED lights installed new step down transformer 3KVA 480V to 120V outdoor transformer Fountain Pressure Washed  install new 5HP/460V/3PH motor  Thermal Overload replaced Fountain Pressure Washed  Fountain - New 7.5Hp Fountain Fountain Pressure Washed	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50 \$175.00 \$500.00 \$1,429.00 \$175.00 \$500.00 \$175.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump F.F.  FF - see comments for warranty FF - 1yr. Warranty on lights  FF FF - warranty still good through 7/25/20 FF - Warranty 100 days FF  Collier Water Systems? - 3-yr warranty included F.F.
Lake 24 - Bubbler Lake 24 - East  5 HP TriTier	3/27/2017  10/1/2018 1/15/2019 6/1/2018  3/1/2015 1/1/2016 3/23/2018 2/27/2018 7/25/2018 8/15/2018 4/26/2019 5/17/2019 9/30/2019 3/12/2020 4/15/2020 2/12/2020 10/16/2020 8/9/2016 8/15/2018	6003  2018-10022 2018-10310  2018-2525  D2016-9788 2018-9833 2018-9896  2019-10647 2019-11023 2016-9864  2020-1325 2020-11426 2020-62744  5788 & 5838 2018-9896 2016-9864	110 Volt 1/2 hp Rocking Piston Compressor Replacement  1 ea. 30A fuse, 1 ea. Manifold rebuild kit rebuilt manifold  removed Bubbler from lake #24  Has Lights on the fountain  Lake Fountain - New 5Hp Lake Fountain  Warranty - 5hp motor replaced.  Replace 2" Fan Nozzle new 5HP/460V/3P motor  Fountain Pressure Washed new 5HP/460V/3P motor (serial # 210296605) Installed under warranty good through 7/25/2020 installed 3 36W LED lights installed new step down transformer 3KVA 480V to 120V outdoor transformer Fountain Pressure Washed  install new 5HP/460V/3PH motor  Thermal Overload replaced Fountain Pressure Washed  Fountain Pressure Washed  Fountain - New 7.5Hp Fountain	\$965.00 \$59.90 \$79.00 \$258.00 \$9,717.00 \$595.00 \$2,842.50 \$175.00 \$500.00 \$1,429.00 \$175.00 \$175.00 \$175.00	23 -1 AirStation, 1" PVC Pipe - Compressor location lake 23 Collier Water Systems - Replaced Compressor that runs lakes 2 & 3  FF - 1yr warranty on the manifold rebuild FF - 1yr warranty F.F both bubblers have now been removed.  Collier Water Systems -3-yr warranty included Collier Water Systems Florida Fountains FF FF - 2yr warranty motor and pump F.F.  FF - see comments for warranty FF - 1yr. Warranty on lights  FF FF - warranty still good through 7/25/20 FF - Warranty 100 days FF  Collier Water Systems? - 3-yr warranty included F.F.

Lake #	Date	Invoice #	Service Issue	Cost	Comments
	10/16/2020	2020-62744	Fountain Pressure Washed	\$175.00	FF
Lake 24 - Air					
	6/1/2015		Aeration - New Aeration System installed	\$5,340.00	Collier Water Systems -
	3/5/2018	D2016- 9647/2016- 9738	new 1/2hp compressor		F.F 3/4hp will not run with the current power set up
	6/5/2019	2019-10699	Replaced 120V intermatic timer. 0.5hr labor	\$213.50	
	8/5/2019	2019-10858	1/2HP 120V rocking piston compressor Serial # 1018909238	\$1,288.00	FF 1 yr warranty
Lake 25-Air					
	5/17/2010		2 AirStations, 1" PVC, Bottomline Tubing, Valve Box, Compressor Cabinet and Compressor		Vertex
	• •	2020-11322	1/2hp 230V dual head aqua master compressor Model #940460 Serial #312303-2	\$1,288.00	FF - 1yr. Warranty
	5/12/2020, 6/25/20, & 7/7/20		email from Rick Grant about bubller/aeration		sent email to FF on 5/20/20 & follow up on 7/7/20
	7/8/2020		7/9/2020 email from FF that the compressor has failed and they will provide a new proposal		
			email from FF that the capacitor wire was not connected well inside the housing and was shorting out for the compressor. Will be repaired under		
	7/16/2020		warranty by Aqua Master.		and an all to Mar Count on 0/4/20 there
	8/3/2020		email from FF that the aeration had been repaired in the lake.		sent email to Mr. Grant on 8/4/20 Item resolved.
	8/3/2020		warranty repair on the compressor	\$204.00	
	9/10/2020		sent request to FF to cap lines for fountains		sent follow up email on 10/5/20