



**Office of Environmental Public Health Sciences
Washington State Department of Health
243 Israel Road SE, Tumwater WA 98501**

Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

Name of Sampler: Lisa Christensen
Date Collected: 10/22/2018
School Name: Thorndyke Elementary
School Code: 3635
School District Name: Tukwila
Address: 4415 S 150th St, Tukwila WA 98188
County: King
Number of Samples Collected: 70
School Point of Contact: Liliana Cardenas
Title of POC: Director of Maintenance and Operations
Email of POC: cardenasl@tukwila.wednet.edu
POC Phone Number: (206) 901-8020
Date sent to State Lab: 10/22/2018
Date Received by Lab:
Shipment Tracking Number: Hand Delivered 10/25/18

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
1.	15152	First Draw	Tap	Kitchen	TB		Food Prep Area, 6:40 AM
2.	15153	First Draw	Bubbler	Near Gym and Cafeteria	<1	11/05/2018	Left Side
3.	15154	First Draw	Bubbler	Outside Gym and Cafeteria	<1	11/05/2018	Right Side
4.	15155	First Draw	Bubbler	Room 103	1	11/05/2018	Music Room
5.	15156	First Draw	Tap	Room 103	5	11/05/2018	Music Room
6.	15157	First Draw	Tap	Health Room 126	<1	11/05/2018	
7.	15158	First Draw	Bubbler	Room 141	<1	11/05/2018	OT PT Room
8.	15159	First Draw	Tap	Room 141	TB		OT PT Room
9.	15160	First Draw	Bubbler	Room 142	<1	11/05/2018	
10.	15161	First Draw	Tap	Room 142	<1	11/05/2018	
11.	15162	First Draw	Bubbler	Room 144	<1	11/05/2018	
12.	15163	First Draw	Tap	Room 144	1	11/05/2018	
13.	15164	First Draw	Bubbler	Near Side Entrance	<1	11/05/2018	Right side fountain doesn't work
14.	15165	First Draw	Bubbler	Room 148	<1	11/05/2018	
15.	15166	First Draw	Tap	Room 148	1	11/05/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
16.	15167	First Draw	Bubbler	Room 149	<1	11/05/2018	
17.	15168	First Draw	Tap	Room 149	<1	11/05/2018	
18.	15169	First Draw	Bubbler	Room 150	<1	11/05/2018	
19.	15170	First Draw	Tap	Room 150	<1	11/05/2018	
20.	15171	First Draw	Bubbler	Room 153	<1	11/05/2018	
21.	15172	First Draw	Tap	Room 153	<1	11/05/2018	
22.	15173	First Draw	Bubbler	Room 157	<1	11/05/2018	
23.	15174	First Draw	Tap	Room 157	1	11/05/2018	
24.	15175	First Draw	Bubbler	Room 160	<1	11/05/2018	
25.	15176	First Draw	Tap	Room 160	2	11/05/2018	
26.	15177	First Draw	Bubbler	Room 161	<1	11/05/2018	
27.	15178	First Draw	Tap	Room 161	1	11/05/2018	Tap Drips
28.	15179	First Draw	Bubbler	Room 162	<1	11/05/2018	
29.	15180	First Draw	Tap	Room 162	1	11/05/2018	
30.	15181	First Draw	Bubbler	Near back stairs	<1	11/05/2018	Left Side
31.	15182	First Draw	Bubbler	Near back stairs	<1	11/05/2018	Right Side
32.	15183	First Draw	Tap	Room 166	<1	11/05/2018	Bubbler is not working
33.	15184	First Draw	Bubbler	Room 168	<1	11/05/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
34.	15185	First Draw	Tap	Room 168	1	11/05/2018	Leaks at base of tap
35.	15186	First Draw	Bubbler	Room 169	<1	11/05/2018	
36.	15187	First Draw	Tap	Room 169	<1	11/05/2018	
37.	15188	First Draw	Bubbler	Room 171	3	11/05/2018	
38.	15189	First Draw	Tap	Room 171	3	11/05/2018	
39.	15190	First Draw	Bubbler	Room 176	3	11/05/2018	
40.	15191	First Draw	Tap	Room 176	2	11/05/2018	
41.	15192	First Draw	Tap	Room 206	1	11/05/2018	Art Room, Left Side Sink, No Aerator
42.	15193	First Draw	Tap	Room 206	1	11/05/2018	Art Room, Middle Sink
43.	15194	First Draw	Tap	Room 206	1	11/05/2018	Art Room, Right Side Sink
44.	15195	First Draw	Bubbler	Room 208	1	11/05/2018	
45.	15196	First Draw	Tap	Room 208	2	11/05/2018	
46.	15197	First Draw	Bubbler	Room 209	1	11/05/2018	
47.	15198	First Draw	Tap	Room 209	1	11/05/2018	
48.	15199	First Draw	Bubbler	Room 210	1	11/05/2018	
49.	15200	First Draw	Tap	Room 210	1	11/05/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
50.	15201	First Draw	Bubbler	Near Room 210	<1	11/05/2018	Left Side
51.	15202	First Draw	Bubbler	Near Room 210	<1	11/05/2018	Right Side
52.	15203	First Draw	Bubbler	Room 215	1	11/05/2018	
53.	15204	First Draw	Tap	Room 215	2	11/05/2018	
54.	15205	First Draw	Bubbler	Room 216	<1	11/05/2018	
55.	15206	First Draw	Tap	Room 216	<1	11/05/2018	
56.	15207	First Draw	Bubbler	Room 217	<1	11/05/2018	
57.	15208	First Draw	Tap	Room 217	2	11/05/2018	
58.	15209	First Draw	Bubbler	Room 228	1	11/06/2018	
59.	15210	First Draw	Tap	Room 228	1	11/06/2018	
60.	15211	First Draw	Bubbler	Room 229	<1	11/06/2018	
61.	15212	First Draw	Tap	Room 229	<1	11/06/2018	
62.	15213	First Draw	Bubbler	Room 230	<1	11/06/2018	
63.	15214	First Draw	Tap	Room 230	1	11/06/2018	Water in sink used by staff member
64.	15215	First Draw	Bubbler	Near Room 230	<1	11/06/2018	Left Side, Down Hallway
65.	15216	First Draw	Bubbler	Near Room 230	<1	11/06/2018	Right Side, Down Hallway
66.	15217	First Draw	Bubbler	Room 235	<1	11/06/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
67.	15218	First Draw	Tap	Room 235	<1	11/06/2018	Tap used by staff member
68.	15219	First Draw	Bubbler	Room 236	<1	11/06/2018	
69.	15220	First Draw	Tap	Room 236	<1	11/06//2018	
70.	15221	Blank	Blank		<1	11/06/2018	Near Side Entrance 04240