



**Office of Environmental Public Health Sciences  
Washington State Department of Health  
243 Israel Road SE, Tumwater WA 98501**

**Lead Sample Collection Information**

**DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.**

**Name of Sampler:** Lisa Christensen  
**Date Collected:** 10/24/2018  
**School Name:** Cascade View Elementary  
**School Code:** 3226  
**School District Name:** Tukwila  
**Address:** 13601 32nd Ave S, Tukwila WA 98168  
**County:** King  
**Number of Samples Collected:** 63  
**School Point of Contact:** Liliana Cardenas  
**Title of POC:** Director of Maintenance and Operations  
**Email of POC:** cardenasl@tukwila.wednet.edu  
**POC Phone Number:** (206) 901-8020  
**Date sent to State Lab:** 10/24/2018  
**Date Received by Lab:**  
**Shipment Tracking Number:** Hand Delivered 10/25/18

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
1.	15222	First Draw	Tap	Kitchen	3	11/02/2018	Food Prep Area, used by staff member, 6:40 AM
2.	15227	First Draw	Bubbler	Cafeteria	<1	11/02/2018	Left Side
3.	15228	First Draw	Bubbler	Cafeteria	<1	11/02/2018	Right Side
4.	15229	First Draw	Tap	Room A110	3	11/02/2018	Infirmary
5.	15230	First Draw	Tap	Room C107	4	11/02/2018	Left Side Sink
6.	15231	First Draw	Tap	Room C107	4	11/02/2018	Drips around base, middle sink
7.	15232	First Draw	Bubbler	Room C107	<1	11/02/2018	
8.	15233	First Draw	Tap	Room C107	3	11/02/2018	
9.	15234	First Draw	Bubbler	Room C105	<1	11/02/2018	
10.	15235	First Draw	Tap	Room C105	5	11/02/2018	
11.	15236	First Draw	Bubbler	Room C103	<1	11/02/2018	
12.	15237	First Draw	Tap	Room C103	2	11/02/2018	
13.	15238	First Draw	Bubbler	Room C101	<1	11/02/2018	
14.	15239	First Draw	Tap	Room C101	3	11/02/2018	
15.	15240	First Draw	Bubbler	C Building Fountain	<1	11/02/2018	Left Side, Near Bathrooms, Right Side not working
16.	15241	First Draw	Bubbler	Room C102	<1	11/02/2018	No aerator

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
17.	15242	First Draw	Tap	Room C102	3	11/02/2018	
18.	15243	First Draw	Bubbler	Room C104	<1	11/02/2018	
19.	15244	First Draw	Tap	Room C104	4	11/02/2018	
20.	15245	First Draw	Bubbler	Room C106	<1	11/02/2018	
21.	15246	First Draw	Tap	Room C106	2	11/02/2018	
22.	15247	First Draw	Bubbler	Room E101	<1	11/02/2018	
23.	15248	First Draw	Tap	Room E101	2	11/02/2018	
24.	15249	First Draw	Bubbler	Room E103	<1	11/02/2018	
25.	15250	First Draw	Tap	Room E103	3	11/02/2018	Tap Drips
26.	15251	First Draw	Bubbler	Room E106	<1	11/02/2018	
27.	15252	First Draw	Tap	Room E106	7	11/02/2018	
28.	15253	First Draw	Bubbler	D Building Fountains	<1	11/02/2018	Near Bathrooms, Left Side
29.	15254	First Draw	Bubbler	D Building Fountains	<1	11/02/2018	Near Bathrooms
30.	15255	First Draw	Bubbler	Room E111	<1	11/02/2018	
31.	15256	First Draw	Tap	Room E111	5	11/02/2018	
32.	15257	First Draw	Bubbler	Room E102	<1	11/02/2018	
33.	15258	First Draw	Tap	Room E102	8	11/02/2018	
34.	15259	First Draw	Bubbler	Room R114	<1	11/02/2018	Not used

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
35.	15260	First Draw	Tap	Room E114	<1	11/02/2018	Used by staff member
36.	15261	First Draw	Bubbler	Room E115	<1	11/02/2018	
37.	15262	First Draw	Tap	Room E115	8	11/02/2018	No Aerator
38.	15263	First Draw	Bubbler	Room E119	<1	11/02/2018	
39.	15264	First Draw	Tap	Room E119	TB	11/02/2018	
40.	15265	First Draw	Tap	Room E120	1	11/02/2018	Left Tap
41.	15266	First Draw	Tap	Room E120	<1	11/02/2018	Right Tap
42.	15267	First Draw	Tap	Room 123	1	11/02/2018	Sink without bubbler
43.	15268	First Draw	Bubbler	Room 123	<1	11/02/2018	
44.	15269	First Draw	Tap	Room 123	3	11/02/2018	
45.	15270	First Draw	Water Cooler	Room E135	<1	11/02/2018	Smart Lab
46.	15271	First Draw	Bubbler	D Building Fountain	<1	11/02/2018	Right Side Near Bathrooms, Left Side not working
47.	15272	First Draw	Bubbler	Room D102	<1	11/02/2018	
48.	15273	First Draw	Tap	Room D102	TB	11/02/2018	
49.	15274	First Draw	Bubbler	Room D104	<1	11/02/2018	
50.	15275	First Draw	Tap	Room D104	TB	11/02/2018	Tap Dripping
51.	15276	First Draw	Bubbler	Room D106	<1	11/02/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
52.	15277	First Draw	Tap	Room D106	3	11/02/2018	
53.	15278	First Draw	Bubbler	Room D107	<1	11/02/2018	
54.	15279	First Draw	Tap	Room D107	6	11/02/2018	
55.	15280	First Draw	Bubbler	Room D105	<1	11/02/2018	
56.	15281	First Draw	Tap	Room D105	1	11/02/2018	Tap used this morning
57.	15282	First Draw	Bubbler	Room D103	<1	11/02/2018	
58.	15283	First Draw	Tap	Room D103	3	11/02/2018	No Aerator
59.	15284	First Draw	Bubbler	Room D101	<1	11/02/2018	
60.	15285	First Draw	Tap	Room D101	2	11/02/2018	
61.	15286	First Draw	Bubbler	Gym	<1	11/02/2018	Left Side
62.	15287	First Draw	Bubbler	Gym	<1	11/02/2018	Right Side
63.	15288	Blank			<1	11/02/2018	04217